



## **MaxiSys Holden V3.50 2016-10-10**

1. Fixed bugs that caused failure when entering special functions for 2009-2010 models: Colorado / Engine control module/ 3.0L 4JJ1-TC (Delphi).
2. Fixed bugs that caused configuration error in Body/Instrument/Instrument Configuration for 2003 VY series.