

# **Release Notes (December)**

This release includes improved performance and bug fixes for <u>MaxiSys series</u> <u>products</u>, and <u>MaxiSys 906/908/908 pro</u>.

## **MaxiSys Series**

♦ Europe:

• Ferrari (V2.10)

➢ Fixed communication problems in F1 Gearbox for some models.

• Renault/Dacia (V3.80)

> Added support for new models in 2016: CAPTUR/KAPTUR

BR/IN/RU, SCENIC IV, KOLEOS II/QM6, KOLEOS II CN/QM6 CN,

MEGANE IV SEDAN, ALASKAN;

Added support for Renault Samsung series;

> Added 500 Hot Functions, such as DPF, Steering Wheel

Alignment and Rear View Camera Adjustment.

• Fiat (V6.00)

➤ Added 500 special functions.

#### ♦ Asia

• Subaru (V3.00)

Added support for VIN analysis and vehicle model selection;

Improved fault codes library and data stream library;

Improved program running and the response speed;

Added support for basic functions and important special

functions for diesel engine;

Added some special functions such as AT Learning Mode and AT Bleeding Mode.

#### ♦ American

#### • Ford (V 7.00)

➢ Added support for Programmable Module Installation and Parameter Setting for models since 2008.

#### Chrysler (V8.00)

> Added support for basic and special functions (except for

online functions) on all 2017 vehicle models;

> Improved performance of all special functions for old models.

### MaxiSys pro & 908 & 906

### ♦ American

#### ♦ GMUSA(V9.90)

Fixed an issue that caused function failure in Cooling Fan in

Engine in TrailBlazer for 2007 Chevrolet Truck;

➢ Fixed an issue that caused failure in code clearing for some models of 2007 Chevrolet Captiva;

Fixed problems in code reading in Engine for some models of 2015 Chevrolet Aveo and 2014 Chevrolet Sail;

➢ Fixed problems in code reading in Engine for 1997 GMC incomplete model.

➢ Fixed an issue that caused function failure in special function Program Key Fob for 2006 Chevrolet Corvette;

> Added Auto VIN Code Diagnosis for some models.

◆ GM (V6.40)

Added Hot Function: Auto Reset;

Fixed an issue that might cause communication failure in

Active Test and Live Data for 2015 Chevrolet and Sail;

➢ Fixed an issue that might cause failure in Active Test, such as Pump Motor Test and Solenoid Valve Test, for2004 Chevrolet and Sail;

➢ Fixed an issue that caused process problems in special function Steering Wheel Angle Sensor Centering in Power Steering Control Module for 2013 Chevrolet Cruze;

➢ Fixed problems in Auto Bleeding in ABS for 2006-2010 GL8 and Firstland, 2006-2008 WG LaCROSSE and WL LaCROSSE; ➢ Fixed bugs that caused error in Active Test and Live Data in Engine for 2005 GL8;

> Optimized the menu display for Active Test and special functions to improve user experience.

#### ♦ European:

#### Opel/Vauxhall (V5.00)

Fixed bugs in special function Program Idle Speed under 2004/Corsa - C/Engine/Z 10 XEP;

➢ Fixed bugs in special function Regeneration D. Particulate Filter under 2011/Corsa-D/Engine/A 13 DTE;

Fixed bugs in Read & Clear Code under 2002-2004/Vectra-C /

Signum /Body/ CIM (Steering Column Module);

Fixed bugs in special function DPF Service Regeneration under

2014/Vivaro (PH3)/ECM/Engine control module;

➢ Fixed bugs in special functions Program Immobilizer, Program Transponder-key, Program Immobilizer Output, Reset Immobilizer and Program Mechanical Key Number under 2001-2004/ Astra-G/

Immobilizer;

Fixed bugs in special function Bleed Clutch Hydraulic under 2008/Corsa-D/TCM/MTA(Easytronic magneti marelli); ➢ Fixed bugs in special function Program Vehicle Identification No. under 2003/ Meriva/BCM;

Added special function Program Special Vehicle under 2010-2014/Corsa-D/Engine/A 13 DTC.

Benz (V7.00)

➢ Fixed an issue that the screen will return to model selection interface when perform Auto Scan;

Fixed an issue that might cause function failure in Pressure Reservoir: Check Pretension Pressure in SBC system under Chassis

211.

➢ Fixed an issue that might cause failure in code clearing in SRS under Chassis 168;

Improved VIN Code auto reading function;

➢ Fixed an issue that caused function failure in Calibration of control unit ABR in SBC system for Chassis 221;

➢ Fixed an issue that caused display error when reading fault codes during auto scanning in Transmission system under Chassis 251.

#### ◆ VW (V9.00)

Optimized model menu for VW, FAW-Audi, SVW, FAW-VW, Seat, Skoda, Lamborghini and VW Commercial vehicles; ➢ Added Guide function for brake pad replacement in EPB, and adds Auto Oil Reset function;

Added some Hot Functions such as Transport Mode and Injector Adaption.

#### Benz (V7.00)(908 pro only)

> Added diagnosis code guide function

#### Porsche (V6.00)(Maxisys908)

Improved all basic functions and Hot function Service Reset

for models 911(977), Boxster 987 and Cayman 987;

> Added basic functions in DSN of Diesel engine for Old

Cayenne.

#### ♦ Asia

#### ◆ Isuzu (V3.31)

Fixed an issue that DTC status failed to be displayed in DTC

information interface for some systems.

#### • Mitsubishi (V5.10) (MaxiSys 908 only)

Added support for Hot Function;

> Allows users to perform tests according to systems.

#### • Hyundai(V6.51) (MaxiSys 908 only)

Optimized Smart Key Programming function and improved

accuracy of the function;

> Optimized the menu of Hot Function and improved speed of response and accuracy.