

MaxiSys Benz V8.02 2016-08-08

1. Fixed bugs that caused failure in rear signal acquisition and actuation module (SAM) action test for chasis 204.
2. Fixed bugs that caused failure in Electronic Stability Program (ESP) special functions, inlet valve and isolating valve calibration, for chasis 204.