

MX-Sensor V4.06 2016-08-16

1. Fixed bugs that caused failure in sensor (OEM number: 56029398AA/56029398AB) reprogramming or activation after programming.