

MaxiSys Volvo V6.30 2016-08-18

1. Improved EPB function for XC60, XC70, V40, V60, V70, S60, S80 models after 2007, and added warning function when ignition key is in an incorrect position.
2. Fixed bugs that caused failure in engine or transmission(gear box) location when reading VIN for XC90, V70 XC/XC70, V70, V50, V40, S80, S70, S60, S40, C70 Coupe, C70 Conv models 1995-2006.
3. Improved support for AutoVIN in Maxisys APP.