

MaxiSys Pro GM V9.70 2016-10-19

1. Fixed an issue where fault codes cannot be correctly read in ABS; added Read codes function in Instrument cluster system in 1999 Chevrolet Cavalier.
2. Fixed an issue where fault codes cannot be read, and some VINs cannot be analyzed; added definitions for some fault codes in 2000 buick century.
3. Fixed an issue where SIR and EBCM modules cannot be diagnosed in 2013 Chevrolet sail.