

MaxiSys Sprinter V2.30 2016-10-26

1. Fixed an issue that caused failure in DPF regeneration in Engine control module in Chassis 906.
2. Fixed an issue that caused test display error when reading fault codes in AMT module in Chassis 90X.6.