

## **MaxiSys Pro Benz V8.12 2016-10-27**

1. Added Steering angle zero position calibration and other functions in ESP system in Chassis 163.
2. Fixed an issue that caused failure in injection quantity adjustment for engine injector in Chassis 203.008, and resolved undefined error in some fault codes.