

## **MaxiSys ChangAn V6.20 2016-11-16**

1. Fixed bugs that caused failure to enter Jinheng SRS for Changan CX20-GA13.
2. Improved the process of special functions Vehicle Configuration and Central Locking Control in Body Control System for Changan CX20-GA13, which can be diagnosed without extra password.
3. Fixed bugs that caused failure to perform other functions after ECU Reset in ABS system for Changan Alsvin V7.