

MaxiSys BaojunAuto V3.10 2016-11-23

1. Fixed an issue that fault codes would occurred after EPS Zero Position Learning for Baojun 730, Baojun 560 before 2016.