

MaxiSys Saab V2.60 2016-11-28

1. Fixed bugs that caused failure when performing Add Keys function for 2008 9-3 model.
2. Fixed bugs that caused communication failure when programming Follow Me Home Light Active Time for High Beam and Low Beam.