

MaxiSys CV OS Program V03.06.00 2016-12-27

1. Fixed an issue that the device reports error when system was resumed from hibernation during the operation of digital videoscope.
2. Improved the prompting message for formatting and factory reset.
3. Updated the management program version to V2.03.
 - 1) Configured with V2.01 VCI firmware update program, allowing users to update VCI firmware off-line.
 - 2) Fixed an issue that repeated update notifications would arise when users updating softwares for vehicle models.
 - 3) Fixed an issue that download speed for operation system updating always displayed as D: 0KB/s.
 - 4) Fixed an issue that vehicle models status cannot update when users repeatedly click Update all/Pause all.
 - 5) Optimized button name for pausing the updating.
 - 6) Optimized prompting messages for abnormal communication.
 - 7) Fixed bugs that caused abnormal display when reading LANDROVER VIN code in AutoVIN.
 - 8) Added quick link for OBD WIKI.
 - 9) Fixed bugs that caused errors in email sending.
4. Improved battery over-temperature protection mechanism.
 - 1) It can power on the system at low temperature (below -10°C).
 - 2) To prevent the diagnosis device from damage and danger, system will warn users to power off when temperature is above 55°C, and automatically shut down when the temperature reaches 60°C.