MaxiSys Pro GM V9.60 2016-09-23

1. Fixed an issue that caused failure in special function "Engine Speed Control" in ECM for 2012 Chevrolet Truck.

2. Resolved an issue that caused process errors in special function "Immobilizer Key Programming" for 2012 Aveo.

3. Fixed an issue that caused process errors in special function "Steering pos/torque sensor" for 2009 Pontiac.

4. Supports diagnosis for 2016 models.

5. Improved route of entry of hot functions (including DPF, Oil reset, TPMS and IMMO) by grouping the functions for users' convenience.

6. Improved VIN analysis for some models.