MaxiSys Mini OS Program V03.07.00 2016-08-03

1. Improved WiFi performance.

2. Fixed bugs that caused system crash at checking network usage under Setting interface.

3. Increased the stability of communication during diagnosis.

4. Optimized the system power management to be more energy-saving and safe.

5. Fixed bugs that caused failure of SD Card finding.

6. Updated the built-in Teamviewer and its related functions to improve the online support experience.