MaxiSys MS906TS MSTS V2.00 2016-08-22

1. Improved the Italiano translation.

2. Added "Low battery" warning for Sensor at activation.

3. Users can select spare tire state as "Activated" when entering OBDII Relearn.