MaxiSys OS Program V03.11.00

1. Improved WiFi performance.

2. Fixed bugs that caused system crash at checking network usage under Setting interface.

3. Increased the stability of communication during diagnosis.

4. Optimized the system power management to be more energy-saving and safe.

5. Improved battery over-temperature protection mechanism. To prevent the diagnosis device from damage and danger, system will warn users to power off when temperature is above 55℃, and automatically shut down when the temperature reaches 60℃.

6. Updated the built-in Teamviewer and its related functions to improve the online support experience.

7.Fixed bugs that caused black screen or stucked when powered up at low battery.