MaxiSys MS906TS MSTS V2.01 2016-10-26

1. Optimized firmware ungrade method.

2. Resolved an issue that the read ID is inconsistent with the active ID in OBD diagnosis for Toyota.

3. Added Cancel option when performing flash.

4. Resolved algorithm problems in some models.