Maxisys CV Cummins V2.01 2016-11-15

1. Fixed Reset calibration error in Trip function under J1708.

2. Improved Prompt process in Read Codes and Clear Codes under J1708.

3. Fixed bugs that caused failure in re-reading codes after the display of Help information and Freeze frame under J1939.

4. Allowed users to choose YES or NO when exiting system by asking "Are you sure to exit?" under J1939.