MaxiSys MS906TS Buick V5.00 2017-01-11

1. Repaired the error of format and value when reading.

2. Repaired the error DTCs.

3. Fixed an issue that caused communication failure when register ID for some models.

4. Repaired some no display menu for models.