



MX-Sensor_V3.06 Function List (Note:For reference only)

NOTES:

- This function is supported. ○ This function is not supported. ▲ This function is the new feature in this version.

Special Declaration: If the "Relearn Type" is only supported OBD type, and the "OBD-II Function" has not been released for the moment, you can just do the clone for relearning the MX-Sensor.

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, 0=OBD)	Frequency	Sensor Manufactuer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
2	EU	Abarth	4B PUNTO EVO	2010/01-2012/12		○	▲	4	A	433Mhz	TRW	51839114		51839114
2797	EU	Ford	Edge	2015/01-2015/12		○	▲	4	A	433Mhz	Schrader	F2GT1A180CB		
2798	EU	Ford	Galaxy	2015/01-2015/12		○	▲	4	A	433Mhz	Schrader	F2GT1A180CB		
2783	EU	Ford	Ranger	2015/01-2015/12		○	▲	4		433Mhz	Schrader	EV6T1A180CB/ EV6T1A150CB		
2799	EU	Ford	S-Max	2015/01-2015/12		○	▲	4	A	433Mhz	Schrader	F2GT1A180CB		
2808	EU	Jaguar	XE	2015/02-2015/12		○	▲	4	0	433Mhz	Continental	LR058023/ C2D43636	S180052028C	S180052028
2792	EU	Jaguar	XF(X260)	2014/07-2015/12		○	▲	4	0	433Mhz	Continental	LR058023		
429	EU	Landrover	Range Rover	2013/01-2015/12		○	▲	4	0	433Mhz	Continental	LR058023	S180052028Z	S180052028
430	EU	Landrover	Range Rover	2013/01-2015/12		○	▲	5	0	433Mhz	Continental	LR058023	S180052028Z	S180052028
2800	EU	Mazda	CX-3	2015/01-2015/12		○	▲	4	A	433Mhz	Continental	BBP337140B/ BHB637140		
2796	EU	Renault	Kadjar	2015/04-2015/12		○	▲	4	A	433Mhz	Continental	407004CB0A	S180150006	S180150006D
786	EU	Ssangyong	Actyon	2014/03-2015/12		○	▲	4	A	433Mhz	Schrader	4199034000		4199034000
787	EU	Ssangyong	C-CUV	2015/05-2015/12		○	▲	4		433Mhz	Schrader	4199034000		4199034000
788	EU	Ssangyong	Korando C	2013/08-2015/12		○	▲	4	A	433Mhz	Schrader	4199034000		4199034000
789	EU	Ssangyong	Kyron	2014/06-2015/12		○	▲	4		433Mhz	Schrader	4199034000		4199034000
790	EU	Ssangyong	Nomad	2014/12-2015/12		○	▲	4		433Mhz	Schrader	4199034000		4199034000
791	EU	Ssangyong	Rexton	2014/05-2015/12		○	▲	4	A	433Mhz	Schrader	4199034000		4199034000
792	EU	Ssangyong	Rodius	2014/05-2015/12		○	▲	4	A	433Mhz	Schrader	4199034000		4199034000
793	EU	Ssangyong	Tivoli	2015/06-2015/12		○	▲	4		433Mhz	Huf/Beru	4199035000		4199035000
2784	EU	Volvo	XC90	2015/01-2015/12	V526	●	▲	4	A	433Mhz	Schrader	31362304		30748354
2803	EU	Volvo	XC90(LCV)	2015/06-2015/12	Y289	●	▲	4	A	433Mhz	Schrader	31329981/ 30748354	90518149	30748354
2804	EU	Volvo	XC90(LCV)	2015/06-2015/12	V526	●	▲	4	A	433Mhz	Schrader	31362304		30748354
2805	US	Acura	ILX	2016/01-2016/12	315MHz	○	▲	4		315Mhz	Continental	42753TZ3A51	S180052060A	S180052060
2806	US	Acura	MDX	2016/01-2016/12	315MHz	○	▲	4		315Mhz	Continental	42753TZ3A51	S180052060A	S180052060
2807	US	Acura	RDX	2016/01-2016/12	315MHz	○	▲	4		315Mhz	Continental	42753TZ3A51	S180052060A	S180052060
2809	US	BMW	7 Series	2002/01-2005/12	433MHz	●	▲	5	A	433Mhz	Huf/Beru	36118378682	0532207002	RDE002
1639	US	Hyundai	Azera	2012/01-2014/12	315MHz	●	▲	4	0	315Mhz	TRW	529333V000	225816-104	225816-104
2788	US	LandRover	Range Rover	2014/01-2015/12	433MHz	●	▲	4		433Mhz	Continental	LR066378		
2789	US	LandRover	Range Rover	2014/01-2015/12	433MHz	●	▲	5		433Mhz	Continental	LR066378		
2790	US	LandRover	Range Rover Evoque	2014/01-2015/12	433MHz	●	▲	4		433Mhz	Continental	LR066378		
2791	US	LandRover	Range Rover Evoque	2014/01-2015/12	433MHz	●	▲	5		433Mhz	Continental	LR066378		
1878	US	LandRover	Range Rover Sport	2014/01-2015/12	433MHz	●	▲	4		433Mhz	Continental	LR066378		
1879	US	LandRover	Range Rover Sport	2014/01-2015/12	433MHz	●	▲	5		433Mhz	Continental	LR066378		
34	EU	Audi	A6	2011/01-2015/12		●	▲	4	A	433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow: Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, 0=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
139	EU	Chevrolet	Captiva	2006/06-2015/12		●	▲	4	S	433Mhz	Schrader	25789964/ 22853740/ 13581561	90518185	25789964
159	EU	Chrysler	300C	2005/06-2010/05		●	▲	4	A	433Mhz	Continental	56053031AD/ 68001698AB	90518155/ 90518434	56029359AA-AB/ 56053031AC-AD/ 56029481AA-AB
204	EU	Citroen	Nemo	2007/10-2013/12		○	▲	4	A	433Mhz	Schrader	53104671		53104671
210	EU	Dacia	Sandero	2012/10-2015/12		○	▲	4	A	433Mhz	SCHRADER	407001628R		407001628R-B RDE024/RDE026
263	EU	Ford	B-MAX	2014/06-2015/12		○	▲	4	S	433Mhz	Schrader	EV6T1A180CB/ EV6T1A150CB/ EV6T1A180DB/ EV6T1A180DB		EV6T-1A180-CB
264	EU	Ford	C-MAX	2014/04-2015/12		○	▲	4	S	433Mhz	Schrader	EV6T1A180CB/ EV6T1A150CB/ EV6T1A180DB/ EV6T1A180DB		EV6T-1A180-CB
267	EU	Ford	Ecosport	2014/10-2015/12		○	▲	4	S	433Mhz	Schrader	EV6T1A180CB/ EV6T1A150CB/ EV6T1A180DB/ EV6T1A180DB		EV6T-1A180-CB
273	EU	Ford	Focus	2010/12-2015/12		●	▲	4	S	433Mhz	Schrader	EV6T1A180CB/ EV6T1A150CB/ EV6T1A180DB/ EV6T1A180DB		EV6T-1A180-CB
276	EU	Ford	Galaxy	2006/05-2014/12		●	▲	4	S	433Mhz	Continental	8G921A159AC/ 8G921A189KB	S180084730Z	S180052020
278	EU	Ford	Kuga	2012/11-2015/12		○	▲	4	S	433Mhz	Schrader	EV6T1A180CB/ EV6T1A150CB/ EV6T1A180DB/ EV6T1A180DB		EV6T-1A180-CB
280	EU	Ford	Mondeo	2014/10-2015/12		○	▲	4	S	433Mhz	Schrader	EV6T1A180CB/ EV6T1A150CB/ EV6T1A180DB/ EV6T1A180DB		EV6T-1A180-CB
284	EU	Ford	S-Max	2006/05-2014/12		●	▲	4	S	433Mhz	Continental	8G921A159AC/ 8G921A189KB	S180084730Z	S180052020
285	EU	Ford	Tourneo Connect	2013/10-2014/04		○	▲	4	S	433Mhz	Schrader	EV6T1A180CB/ EV6T1A180DB/ DR3V1A180DA		BB5T1A180AA/ DV6T1A180AA
286	EU	Ford	Tourneo Courier	2014/02-2015/12		○	▲	4	S	433Mhz	Schrader	EV6T1A180CB/ EV6T1A180DB/ DR3V1A180DA		BB5T1A180AA/ DV6T1A180AA
291	EU	Ford	Transit Connect	2014/05-2015/12		○	▲	4	S	433Mhz	Schrader	EV6T1A180CB/ EV6T1A180DB/ DR3V1A180DA		BB5T1A180AA/ DV6T1A180AA
2597	EU	Hyundai	Tucson	2015/10-2015/12		○	▲	4	0	433Mhz	Schrader	52933C8000/ 52933C1100		
525	EU	Mercedes	Citan	2012/09-2015/12		●	▲	4	A/0	433Mhz	SCHRADER	407001628R		407001628R-B
731	EU	Renault	Clio IV	2014/06-2015/12		●	▲	4	A	433Mhz	Schrader Huf/Beru	407001628R/ 407009987R		407001628R RDE024/RDE026
923	EU	Volvo	XC90	2011/01-2015/12	Y289	●	▲	4	A	433Mhz	Schrader	31329981/ 30748354	90518149	30748354

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
929	US	Acura	MDX	2014/01-2015/12	315MHz	●	▲	4	A	315Mhz	Continental	42753TX4A51	S180052042G	S180052042
931	US	Acura	RDX	2013/01-2015/12	315MHz	●	▲	4	A	315Mhz	Continental	42753TX4A51	S180052042G	S180052042
934	US	Acura	RLX	2014/01-2016/12	315MHz	●	▲	4	A	315Mhz	TRW	42753TY2A51		
937	US	Acura	TL	2014/01-2014/12	315MHz	●	▲	4	A	315Mhz	TRW	42753TY2A51		
938	US	Acura	TLX	2015/01-2016/12	315MHz	●	▲	4	A	315Mhz	Continental	42753TZ3A51	S180052060A	S180052060
968	US	Audi	S4	2002/01-2008/12	433MHz	●	▲	4	S	433Mhz	Huf/Beru	4F0907275B	0532207011	RDE011
998	US	BMW	3 Series	2000/01-2006/12	433MHz	●	▲	4	A	433Mhz	Huf/Beru	36118378682	0532207002	RDE002
1002	US	BMW	3 Series Sedan	2013/01-2014/02	433MHz	●	▲	4	A	433Mhz	Huf/Beru	36106798872	0532207017	RDE017
1019	US	BMW	7 Series	2002/01-2005/12	433MHz	●	▲	4	A	433Mhz	Huf/Beru	36118378682	0532207002	RDE002
1649	US	Hyundai	Equus	2015/01-2015/12	433MHz	●	▲	4	O	433Mhz	Continental	52933A5000	S180052041F	S180052041
1666	US	Hyundai	Sonata	2010/01-2013/12	315MHz	●	▲	4	O	315Mhz	Continental	529332M000	S180052017G	S180052017
1665	US	Hyundai	Sonata	2009/01-2009/12	Lo Line	●	▲	4	O	315Mhz	TRW	529332F000	216707-101	216707-101
2096	US	Mercedes	SL Class	2012/07-2015/12	433MHz	●	▲	4	A	433Mhz	Schrader	A0035400217		A 003 540 02 17
2302	US	Porsche	Cayman	2005/01-2008/12	433MHz	●	▲	4	A	433Mhz	Huf/Beru	99760602101	0532207001	RDE001
2364	US	Tesla	Model S	2013/01-2015/12	433MHz	○	▲	4	S	433Mhz	Baolong	FS1511130317		
2427	US	Toyota	Prius C	2012/01-2015/12	315MHz	●	▲	4	O	315Mhz	Pacific	4260706020	3729A-PMVC010	42607-06020
2428	US	Toyota	Prius C	2012/01-2015/12	315MHz	●	▲	5	O	315Mhz	Pacific	4260706020	3729A-PMVC010	42607-06020
2435	US	Toyota	RAV4	2013/07-2015/12	Japan made/Push button	●	▲	4	O	315Mhz	Pacific	4260752020	3729A-PMVC010	42607-06020
2436	US	Toyota	RAV4	2013/07-2015/12	Japan made/Push button	●	▲	5	O	315Mhz	Pacific	4260752020	3729A-PMVC010	42607-06020
1	EU	Abarth	4A GRANDE PUNTO	2007/01-2010/12		○	●	4	A	433Mhz	TRW	51839114		51839114
3	EU	Abarth	81 NUOVA PUNTO	2012/01-2013/12		○	●	4	A	433Mhz	TRW	51839114		51839114
4	EU	Alfa Romeo	159	2005/07-2011/12		○	●	4		433Mhz	TRW	51839114		51839114
5	EU	Alfa Romeo	4C	2013/06-2015/12		○	●	4	A	433Mhz	Schrader	05154876AA		670002790
6	EU	Alfa Romeo	Alfa 8C	2006/12-2010/12		○	●	4	S	433Mhz	Huf/Beru	185189	0532207001	RDE001
7	EU	Alfa Romeo	Brera	2005/11-2010/12		○	●	4		433Mhz	TRW	51839114		51839114
2795	EU	Alfa Romeo	Giulietta	2014/01-2015/12		○	●	4		433Mhz	Schrader	53104671		
2794	EU	Alfa Romeo	Giulietta	2010/01-2013/12		○	●	4	A	433Mhz	TRW	51839114		51839114
9	EU	Alfa Romeo	MiTo	2013/08-2016/06		○	●	4		433Mhz	TRW	51839114		53104671
8	EU	Alfa Romeo	MiTo	2008/06-2013/07		○	●	4		433Mhz	TRW	51839114		51839114
10	EU	Alfa Romeo	MiTo(LCV)	2014/06-2015/12		○	●	4		433Mhz	Schrader	53104671	90518358	53104671
11	EU	Alfa Romeo	Spider	2006/06-2010/12		○	●	4		433Mhz	TRW	51839114		51839114
15	EU	Alpina	Alpina 3	2013/04-2015/12		○	●	4	A	433Mhz	Continental	36106856209	S180052056F	S180052056
14	EU	Alpina	Alpina 3	2013/01-2015/12		○	●	4	A	433Mhz	Continental	36106856209	S180052056F	S180052056
13	EU	Alpina	Alpina 3	2009/09-2012/12		○	●	4	A	433Mhz	Huf/Beru	36106790054/ 36106856227	0532207012	RDE012
12	EU	Alpina	Alpina 3	2007/03-2009/09		○	●	4	A	433Mhz	Huf/Beru	36236781847	0532207008	RDE008
16	EU	Alpina	Alpina 5	2010/01-2015/12		○	●	4	A	433Mhz	Huf/Beru	36106790054/ 36106856227	0532207012	RDE012
18	EU	Alpina	Alpina 6	2010/12-2015/12		○	●	4	A	433Mhz	Huf/Beru	36106790054/ 36106856227	0532207012	RDE012
17	EU	Alpina	Alpina 6	2006/03-2010/11		○	●	4	A	433Mhz	Huf/Beru	36236781847	0532207008	RDE008
19	EU	Alpina	Alpina 7	2010/09-2015/12		○	●	4	A	433Mhz	Huf/Beru	36106790054/ 36106856227	0532207012	RDE012

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
20	EU	Alpina	XD3	2010/09-2015/12		○	●	4	A	433Mhz	Huf/Beru	36106790054/ 36106856227	0532207012	RDE012
21	EU	Aston Martin	DB9	2012/01-2015/12		○	●	4	A	433Mhz	Huf/Beru	AD43360671AA	0532207011	RDE011
22	EU	Aston Martin	DBS	2007/09-2015/12		○	●	4	A	433Mhz	Huf/Beru	AD43360671AA	0532207011	RDE011
23	EU	Aston Martin	Rapide	2012/01-2015/12		○	●	4	A	433Mhz	Huf/Beru	AD43360671AA	0532207011	RDE011
24	EU	Aston Martin	V12 Vantage	2012/01-2013/12		○	●	4	A	433Mhz	Huf/Beru	CD23360671AA	0532207011	RDE011
25	EU	Aston Martin	V12 Zagato	2012/09-2015/12		○	●	4		433Mhz	Huf/Beru	7PP907275F	0532207011	RDE011
26	EU	Aston Martin	V8 Vantage	2012/01-2015/06		○	●	4	A	433Mhz	Huf/Beru	AD43360671AA	0532207011	RDE011
27	EU	Aston Martin	V8 Vantage S	2013/01-2015/06		○	●	4	A	433Mhz	Huf/Beru	AD43360671AA	0532207011	RDE011
28	EU	Aston Martin	Vanquish	2012/01-2015/12		○	●	4	A	433Mhz	Huf/Beru	CD23360671AA	0532207011	RDE011
29	EU	Audi	A3	2012/06-2015/12		●	●	4	A	433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018
30	EU	Audi	A4	2004/11-2008/07		●	●	4	S	433Mhz	Huf/Beru	4F0907275D	0532207011	RDE011
31	EU	Audi	A5	2006/12-2015/12		●	●	4	A	433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018
33	EU	Audi	A6	2009/06-2010/12		●	●	4	S	433Mhz	Huf/Beru	4F0907275E	0532207011	RDE011
32	EU	Audi	A6	2004/05-2009/05		●	●	4	S	433Mhz	Huf/Beru	4F0907275D	0532207011	RDE011
37	EU	Audi	A6 Allroad	2009/11-2015/12		●	●	4	S	433Mhz	Huf/Beru	7PP907275F	0532207011	RDE011
36	EU	Audi	A6 Allroad	2006/01-2009/10		●	●	4	S	433Mhz	Huf/Beru	4F0907275D	0532207011	RDE011
35	EU	Audi	A6 Allroad	2000/04-2005/12		●	●	4	S	433Mhz	Huf/Beru	4D0907275C	0532207001	RDE001
40	EU	Audi	A6 Quattro	2011/01-2015/12		●	●	4	A	433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018
39	EU	Audi	A6 Quattro	2009/06-2011/03		●	●	4	S	433Mhz	Huf/Beru	4F0907275E	0532207011	RDE011
38	EU	Audi	A6 Quattro	2004/01-2009/05		●	●	4	S	433Mhz	Huf/Beru	7PP907275F	0532207011	RDE011
41	EU	Audi	A7	2010/09-2015/12		●	●	4	A	433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018
42	EU	Audi	A8	2009/11-2015/12		●	●	4	A	433Mhz	Huf/Beru	7PP907275F	0532207011	RDE011
44	EU	Audi	A8	2002/10-2010/07		●	●	4	S	433Mhz	Huf/Beru	4D0907275C	0532207001	RDE001
2752	EU	Audi	A8	2002/10-2010/07		●	●	5	S	433Mhz	Huf/Beru	4D0907275C	0532207001	RDE001
43	EU	Audi	A8	1999/01-2001/11		●	●	4	S	433Mhz	Huf/Beru	4D0907275C	0532207001	RDE001
45	EU	Audi	Q3 (8U)	2011/07-2015/12		●	●	4	A	433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018
46	EU	Audi	Q5	2008/09-2015/12		●	●	4	S	433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018
49	EU	Audi	Q7	2015/01-2015/12		●	●	4	A	433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018
48	EU	Audi	Q7	2009/06-2014/12		●	●	4	S	433Mhz	Huf/Beru	7PP907275F	0532207011	RDE011
47	EU	Audi	Q7	2005/11-2009/05		●	●	4	S	433Mhz	Huf/Beru	7PP907275F	0532207011	RDE011
51	EU	Audi	R8	2009/06-2015/03		●	●	4	S	433Mhz	Huf/Beru	4F0907275E	0532207011	RDE011
50	EU	Audi	R8	2006/01-2009/05		●	●	4	S	433Mhz	Huf/Beru	4F0907275D	0532207011	RDE011
52	EU	Audi	RS4	2006/04-2008/12		●	●	4	S	433Mhz	Huf/Beru	4F0907275D	0532207011	RDE011
55	EU	Audi	RS6	2013/01-2015/12		●	●	4	A	433Mhz	Huf/Beru	7PP907275F	0532207011	RDE011
53	EU	Audi	RS6	2000/04-2005/09		●	●	4	S	433Mhz	Huf/Beru	4D0907275C	0532207001	RDE001
56	EU	Audi	RS7	2013/01-2015/12		●	●	4		433Mhz	Huf/Beru	7PP907275F	0532207011	RDE011
57	EU	Audi	S4	2004/01-2007/12		●	●	4	S	433Mhz	Huf/Beru	4F0907275D	0532207011	RDE011
59	EU	Audi	S6	2009/01-2011/12		●	●	4	S	433Mhz	Huf/Beru	4F0907275D	0532207011	RDE011
58	EU	Audi	S6	2004/01-2009/12		●	●	4	S	433Mhz	Huf/Beru	4F0907275B	0532207011	RDE011
62	EU	Audi	S8	2009/11-2015/12		●	●	4	S	433Mhz	Huf/Beru	4F0907275D	0532207011	RDE011
61	EU	Audi	S8	2002/10-2009/10		●	●	4	S	433Mhz	Huf/Beru	4D0907275C	0532207001	RDE001
2782	EU	Audi	S8	2002/10-2009/10		●	●	5	S	433Mhz	Huf/Beru	4D0907275C	0532207001	RDE001
60	EU	Audi	S8	1999/09-2002/09		●	●	4	S	433Mhz	Huf/Beru	4D0907275C	0532207001	RDE001
63	EU	Audi	TT	2014/02-2015/12		●	●	4	A	433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018
65	EU	Bentley	Azure	2007/01-2015/12		●	●	4	S	433Mhz	Huf/Beru	7PP907275F	0532207011	RDE011

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow: Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, 0=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
67	EU	Bentley	Continental Flying Spur	2005/03-2015/12		●	●	4	S	433Mhz	Huf/Beru	7PP907275F	0532207011	RDE011
69	EU	Bentley	Continental GT	2005/06-2015/12		●	●	4	S	433Mhz	Huf/Beru	7PP907275F	0532207011	RDE011
68	EU	Bentley	Continental GT	2003/09-2005/05		●	●	4	S	433Mhz	Huf/Beru	4D0907275C	0532207001	RDE001
70	EU	Bentley	Mulsanne	2010/01-2015/12		●	●	4	S	433Mhz	Huf/Beru	7PP907275F	0532207011	RDE011
73	EU	BMW	1 Series	2014/03-2015/12		●	●	4	A	433Mhz	Continental	36106856209	S180052056Z	S180052056
72	EU	BMW	1 Series	2010/09-2014/02		●	●	4	A	433Mhz	Huf/Beru	36106790054/ 36106856227	0532207012	RDE012
71	EU	BMW	1 Series	2006/12-2010/08		●	●	4	A	433Mhz	Huf/Beru	36236781847	0532207008	RDE008
76	EU	BMW	2 Series	2014/07-2015/12	F45/F46	●	●	4	A	433Mhz	Continental	36106856209	S180052056Z	S180052056
74	EU	BMW	2 Series	2014/03-2015/12	F22/F23	●	●	4	A	433Mhz	Continental	36106856209	S180052056Z	S180052056
82	EU	BMW	3 Series	2014/03-2015/12		●	●	4	A	433Mhz	Continental	36106856209	S180052056Z	S180052056
79	EU	BMW	3 Series	2009/09-2011/09		●	●	4	A	433Mhz	Huf/Beru	36106790054/ 36106856227	0532207012	RDE012
78	EU	BMW	3 Series	2006/01-2009/08		●	●	4	A	433Mhz	Huf/Beru	36236781847	0532207008	RDE008
77	EU	BMW	3 Series	1999/03-2005/12		●	●	4	A	433Mhz	Huf/Beru	36118378682	0532207002	RDE002
85	EU	BMW	4 Series	2014/03-2015/12		●	●	4	A	433Mhz	Continental	36106856209	S180052056Z	S180052056
90	EU	BMW	5 Series	2014/03-2015/12		●	●	4	A	433Mhz	Huf/Beru	36106798872	0532207017	RDE017
89	EU	BMW	5 Series	2010/09-2014/02		●	●	4	A	433Mhz	Huf/Beru	36106790054/ 36106856227	0532207012	RDE012
88	EU	BMW	5 Series	2006/03-2010/08		●	●	4	A	433Mhz	Huf/Beru	36236781847	0532207008	RDE008
86	EU	BMW	5 Series	1998/09-2003/07		●	●	4	A	433Mhz	Huf/Beru	36118378682	0532207002	RDE002
93	EU	BMW	6 Series	2014/03-2015/12		●	●	4	A	433Mhz	Huf/Beru	36106798872	0532207017	RDE017
92	EU	BMW	6 Series	2010/01-2014/02		●	●	4	A	433Mhz	Huf/Beru	36106790054/ 36106856227	0532207012	RDE012
91	EU	BMW	6 Series	2006/03-2009/12		●	●	4	A	433Mhz	Huf/Beru	36236798726	0532207008	RDE008
98	EU	BMW	7 Series	2014/03-2015/12		●	●	4	A	433Mhz	Huf/Beru	36106798872	0532207017	RDE017
97	EU	BMW	7 Series	2010/09-2014/02		●	●	4	A	433Mhz	Huf/Beru	36106790054	0532207012	RDE012
96	EU	BMW	7 Series	2008/01-2010/08		●	●	4	A	433Mhz	Huf/Beru	36236781847	0532207008	RDE008
95	EU	BMW	7 Series	2006/01-2010/08		●	●	4	A	433Mhz	Huf/Beru	36236781847	0532207008	RDE008
94	EU	BMW	7 Series	1998/09-2005/12		●	●	4	A	433Mhz	Huf/Beru	36118378682	0532207002	RDE002
99	EU	BMW	i3	2013/08-2015/12		●	●	4	A	433Mhz	Continental	36106856209	S180052056Z	S180052056
100	EU	BMW	i8	2014/03-2015/12		●	●	4	A	433Mhz	Continental	36106856209	S180052056Z	S180052056
101	EU	BMW	M3	2014/04-2015/12		○	●	4	A	433Mhz	Continental	36106856209	S180052056Z	S180052056
102	EU	BMW	M4	2014/04-2015/12		○	●	4	A	433Mhz	Continental	36106856209	S180052056Z	S180052056
2786	EU	BMW	X1	2015/07-2016/12		●	●	4	A	433Mhz	continental	36106856209		S180052056
107	EU	BMW	X1	2014/03-2015/07		●	●	4	A	433Mhz	Huf/Beru	36106798872	0532207017	RDE017
106	EU	BMW	X1	2009/10-2014/02		●	●	4	A	433Mhz	Huf/Beru	36106790054/ 36106856227	0532207012	RDE012
110	EU	BMW	X3	2014/03-2015/12		●	●	4	A	433Mhz	Huf/Beru	36106798872	0532207017	RDE017
109	EU	BMW	X3	2010/11-2014/02		●	●	4	A	433Mhz	Huf/Beru	36106790054/ 36106856227	0532207012	RDE012
108	EU	BMW	X3	2003/03-2010/08		●	●	4	A	433Mhz	Huf/Beru	36236781847	0532207008	RDE008
111	EU	BMW	X4	2013/07-2015/12		●	●	4	A	433Mhz	Huf/Beru	36106798872	0532207017	RDE017
115	EU	BMW	X5	2013/05-2015/12		●	●	4	A	433Mhz	Continental	36106856209	S180052056Z	S180052056
114	EU	BMW	X5	2011/01-2013/06		●	●	4	A	433Mhz	Huf/Beru	36106856227	0532207012	RDE012
113	EU	BMW	X5	2006/11-2010/12		●	●	4	A	433Mhz	Huf/Beru	36236781847	0532207008	RDE008
112	EU	BMW	X5	1999/10-2006/10		●	●	4	A	433Mhz	Huf/Beru	36146752128	0532207003	RDE003

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
118	EU	BMW	X6	2014/08-2015/12		●	●	4	A	433Mhz	Continental	36106856209	S180052056Z	S180052056
117	EU	BMW	X6	2011/12-2014/07		●	●	4	A	433Mhz	Huf/Beru	36106790054/ 36106856227	0532207012	RDE012
116	EU	BMW	X6	2007/12-2011/10		●	●	4	A	433Mhz	Huf/Beru	36236781847	0532207008	RDE008
121	EU	BMW	Z4	2014/03-2016/09		●	●	4	A	433Mhz	Huf/Beru	36106798872	0532207017	RDE017
120	EU	BMW	Z4	2010/09-2014/02		●	●	4	A	433Mhz	Huf/Beru	36106790054/ 36106856227	0532207012	RDE012
119	EU	BMW	Z4	2006/03-2010/08		●	●	4	A	433Mhz	Huf/Beru	36236781847	0532207008	RDE008
122	EU	Buick	Park avenue	1997/01-2005/12		○	●	4	S	433Mhz	Schrader	25789964	90518185	25789964
123	EU	Buick	Rainier	2007/01-2007/12		●	●	4	S	433Mhz	Schrader	25774007	90518110	25774007
125	EU	Cadillac	ATS	2014/01-2015/12		●	●	4	S	433Mhz	Schrader	20925925	60518416	20925925
124	EU	Cadillac	ATS	2012/01-2013/12		●	●	4	S	433Mhz	Schrader	20925925	60518416	20925925
127	EU	Cadillac	CTS	2008/01-2015/12		●	●	4	S	433Mhz	Schrader	20922901	90518390	20922901
126	EU	Cadillac	CTS	2006/01-2007/12		●	●	4	S	433Mhz	Schrader	25774007	90518110	25774007
128	EU	Cadillac	DTS	2005/01-2011/12		●	●	4	S	433Mhz	Schrader	25758221	90518046	25758221
132	EU	Cadillac	Escalade	2013/01-2015/12		●	●	4	S	433Mhz	Schrader	22853740	90518185	22853740
2656	EU	Cadillac	Escalade	2012/01-2012/12		●	●	4	S	433Mhz	Schrader	22853740	90518185	22853740
131	EU	Cadillac	Escalade	2009/01-2011/12		●	●	4	S	433Mhz	Schrader	22853740	90518185	22853740
130	EU	Cadillac	Escalade	2007/01-2008/12		●	●	4	S	433Mhz	Schrader	22853740	90518185	22853740
129	EU	Cadillac	Escalade	2005/01-2006/12		●	●	4	S	433Mhz	Schrader	22853740	90518185	22853740
133	EU	Cadillac	SRX	2005/01-2014/12		●	●	4	S	433Mhz	Schrader	25774007	90518110	25774007
134	EU	Cadillac	STS	2005/01-2011/12		●	●	4	S	433Mhz	Schrader	25758221	90518046	25758221
135	EU	Cadillac	XLR	2004/01-2009/12		●	●	4	S	433Mhz	Schrader	25758221	90518046	25758221
136	EU	Cadillac	XTS	2012/05-2018/03		●	●	4		433Mhz	Schrader	22853740	90518185	22853740
137	EU	Chevrolet	Aveo	2011/11-2015/12		●	●	4		433Mhz	Schrader	22853740	90518185	22853740
138	EU	Chevrolet	Camaro	2009/01-2015/12		●	●	4	S	433Mhz	Schrader	20925925	60518416	20925925
140	EU	Chevrolet	Cobalt	2013/02-2015/12		○	●	4		433Mhz	Schrader	22853740/	90518185	22853740
141	EU	Chevrolet	Colorado	2011/01-2015/12		●	●	4		433Mhz	Schrader	13581561	60518416	20925925
142	EU	Chevrolet	Colorado (LCV)	2013/01-2015/12		●	●	4		433Mhz	Schrader	25758221	90518046	25758221
144	EU	Chevrolet	Corvette	2010/01-2013/01		●	●	4	S	433Mhz	Schrader	20925925	60518416	20925925
143	EU	Chevrolet	Corvette	2004/07-2010/01		●	●	4	S	433Mhz	Schrader	25758221	90518046	25758221
146	EU	Chevrolet	Cruze	2008/10-2015/12		●	●	4	S	433Mhz	Schrader	22853740	90518185	22853740
147	EU	Chevrolet	Express	2002/07-2015/12		●	●	4	S	433Mhz	Schrader	22853740	90518185	22853740
149	EU	Chevrolet	Malibu	2014/07-2015/06		○	●	4	S	433Mhz	Schrader	13581561	90518185	13581561
148	EU	Chevrolet	Malibu	2011/07-2014/06		●	●	4	S	433Mhz	Schrader	22853740	90518185	22853740
150	EU	Chevrolet	Matiz	2014/06-2015/12		○	●	4	O	433Mhz	Schrader	22853740	90518185	22853740
151	EU	Chevrolet	Orlando	2010/09-2015/12		●	●	4	S	433Mhz	Schrader	22853740	90518185	22853740
152	EU	Chevrolet	Spark	2009/07-2015/12		●	●	4	O	433Mhz	Schrader	22853740	90518185	22853740
153	EU	Chevrolet	Suburban	2006/03-2008/07		●	●	4	S	433Mhz	Schrader	22853740	90518185	22853740
154	EU	Chevrolet	Trailblazer	2007/01-2008/12		●	●	4	S	433Mhz	Schrader	25774007	90518110	25774007
155	EU	Chevrolet	Trax	2012/03-2015/12		●	●	4	S	433Mhz	Schrader	20922901	90518390	20922901
156	EU	Chevrolet	Volt	2010/11-2015/12		●	●	4	S	433Mhz	Schrader	13348393	90518352	13348393
158	EU	Chrysler	300	2011/01-2015/12		●	●	4	A	433Mhz	Schrader	56029398	90518291	56029400AC/ 56029400AD
157	EU	Chrysler	300	2009/01-2010/12		●	●	4	A	433Mhz	Schrader	56029400	90518291	56029400AC/ 56029400AD
161	EU	Chrysler	300C	2014/06-2015/12		○	●	4	A	433Mhz	Schrader	56029400AD		56029400AD

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
160	EU	Chrysler	300C	2010/06-2014/05		●	●	4	A	433Mhz	Schrader	56029398		56029398
162	EU	Chrysler	Delta	2011/01-2014/12		●	●	4	O	433Mhz	TRW	51839114		51839114
164	EU	Chrysler	Grand Voyager	2011/01-2015/12		●	●	4	S	433Mhz	Schrader	56029398		56029398
163	EU	Chrysler	Grand Voyager	2007/01-2010/12		●	●	4	S	433Mhz	Schrader	56029359		56029359
165	EU	Chrysler	Pacifica	2005/01-2006/12		●	●	4	A	433Mhz	Continental	68001698AB/ 68078768AA		56029527AA
167	EU	Chrysler	Sebring	2006/06-2015/12		●	●	4	A	433Mhz	Schrader	56029359	90518155/ 90518434	56029359AA-AB/ 56053031AC/ 56029481AA-AB
166	EU	Chrysler	Sebring	2005/01-2006/05		●	●	4	A	433Mhz	Continental	68001698AB/ 68078768AA		56029527AA
169	EU	Chrysler	Town&Country	2011/04-2015/12		●	●	4	A	433Mhz	Schrader	53104671	90518358	53104671
168	EU	Chrysler	Town&Country	2007/01-2011/03		●	●	4	A	433Mhz	Schrader	68001698AB		56029359
170	EU	Chrysler	Viper	2012/09-2015/12		●	●	4	A	433Mhz	Schrader	53104671	90518358	53104671
172	EU	Chrysler	Voyager	2011/01-2015/12		●	●	4	S	433Mhz	Schrader	56029398	90518358	56029398AA-AB
171	EU	Chrysler	Voyager	2007/07-2010/12		●	●	4	A	433Mhz	Schrader	68001698AB	90518155/ 90518434	56029359AA-AB/ 56053031AC/ 56029481AA-AB
173	EU	Chrysler	Ypsilon	2011/04-2015/12		●	●	4	A	433Mhz	Schrader	56029398/ 53104671		56029398/ 53104671
175	EU	Citroen	Berlingo	2013/10-2015/12		○	●	4	O	433Mhz	Schrader	9802003680		9802003680
174	EU	Citroen	Berlingo	2008/05-2013/09		●	●	4	O	433Mhz	Schrader	9683420380		
176	EU	Citroen	Berlingo(LCV)	2008/05-2013/09		○	●	4	O	433Mhz	Schrader	9673860880		
2651	EU	Citroen	C3	2014/01-2015/12		○	●	4	S	433Mhz	Schrader	9802003680		9802003680
177	EU	Citroen	C3	2013/01-2013/12		○	●	4	A	433Mhz	Schrader	9802003680		9802003680
180	EU	Citroen	C4	2013/10-2015/12		○	●	4	O	433Mhz	Schrader	9802003680		9802003680
179	EU	Citroen	C4	2008/08-2013/09		●	●	4	O	433Mhz	Schrader	9683420380		
178	EU	Citroen	C4	2004/11-2008/07		●	●	4	O	433Mhz	Continental	5430T4	S180014805Z	S120120001
181	EU	Citroen	C4 Aircross	2014/04-2015/12		○	●	4	S	433Mhz	Continental	1612477080	S180052094Z	S180052094
182	EU	Citroen	C4 Picasso	2006/05-2013/12		●	●	4		433Mhz	Schrader	5430W0	90818333	9673860880
185	EU	Citroen	C5	2013/09-2015/12		○	●	4	O	433Mhz	Schrader	9802003680		9802003680
184	EU	Citroen	C5	2004/08-2013/08		●	●	4	O	433Mhz	Continental	5430T4/ 543093	S180014805Z	S120120001
183	EU	Citroen	C5	2001/03-2004/07		●	●	4	S	433Mhz	Schrader	9634866180		
186	EU	Citroen	C5(LCV)	2007/10-2015/12		○	●	4		433Mhz	Schrader	9802003680		9802003680
187	EU	Citroen	C6	2005/09-2013/05		●	●	4	O	433Mhz	Continental	5430T4/ 543093	S180014805Z	S120120001
190	EU	Citroen	C8	2014/06-2015/06		○	●	4		433Mhz	SCHRADER	9802003680/ 9811536380		9802003680/ 9811536380
189	EU	Citroen	C8	2005/10-2014/06		●	●	4	O	433Mhz	Continental	5430T4	S180014805Z	S120120001
188	EU	Citroen	C8	2002/06-2005/09		●	●	4	S	433Mhz	Schrader	9634866180		
191	EU	Citroen	C-Cactus	2014/07-2015/12		○	●	4	S	433Mhz	Schrader	9802003680		9802003680
192	EU	Citroen	C-Elysee	2012/09-2015/12		○	●	4	S	433Mhz	Schrader	9802003680		9802003680
2767	EU	Citroen	DS3	2015/01-2015/12		○	●	4	O	433Mhz	Schrader	9802003680		9802003680
193	EU	Citroen	DS3	2009/12-2014/12		○	●	4	O	433Mhz	Schrader	9802003680		9802003680
195	EU	Citroen	DS4	2014/01-2015/12		○	●	4	O	433Mhz	Schrader	9802003680		9802003680
194	EU	Citroen	DS4	2010/12-2014/01		○	●	4	O	433Mhz	Schrader	9683420380		
196	EU	Citroen	DS4(LCV)	2010/12-2014/01		○	●	4		433Mhz	Schrader	9802003680		9802003680

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, 0=OBD)	Frequency	Sensor Manufactuer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
198	EU	Citroen	DS5	2014/01-2015/12		○	●	4	0	433Mhz	Schrader	9802003680		9802003680
197	EU	Citroen	DS5	2011/01-2014/01		○	●	4	0	433Mhz	Schrader	9683420380		
199	EU	Citroen	DS5(LCV)	2011/06-2015/12		○	●	4		433Mhz	Schrader	9802003680		9802003680
200	EU	Citroen	Jumper	2014/06-2015/12		○	●	4	A	433Mhz	Schrader	9802003680		9802003680
203	EU	Citroen	Jumpy van	2014/10-2015/12		○	●	4	0	433Mhz	Schrader	9802003680		9802003680
202	EU	Citroen	Jumpy van	2011/01-2014/09		○	●	4	0	433Mhz	Schrader	9677130580	70503487	9677130580
2650	EU	Citroen	Nemo	2014/10-2015/12		○	●	4	S	433Mhz	Schrader	53104671		53104671
205	EU	Dacia	Dokker	2014/01-2015/12		○	●	4	0	433Mhz	SCHRADER	407001628R		407001628R-B RDE024/RDE026
206	EU	Dacia	Duster	2010/02-2015/12		○	●	4	0	433Mhz	SCHRADER	407001628R		407001628R-B RDE024/RDE026
207	EU	Dacia	Lodgy	2012/01-2015/12		○	●	4	0	433Mhz	SCHRADER	407001628R		407001628R-B RDE024/RDE026
208	EU	Dacia	Logan	2012/11-2015/12		○	●	4	0	433Mhz	SCHRADER	407001628R		407001628R-B RDE024/RDE026
209	EU	Dacia	Logan MCV	2013/04-2015/12		○	●	4		433Mhz	SCHRADER	407001628R		407001628R-B RDE024/RDE026
211	EU	Dacia	Sandero Pro	2012/10-2015/12		○	●	4	0	433Mhz	SCHRADER	407001628R		407001628R-B RDE024/RDE026
213	EU	Daewoo	Gentra	2013/08-2015/12		○	●	4		433Mhz	Schrader	25789964	90518185	25789964/ 22853740/ 13581561
214	EU	Daewoo	Nexia	2014/06-2015/12		○	●	4		433Mhz	Schrader	25789964	90518185	25789964/ 22853740/ 13581561
215	EU	Dodge	Avenger	2006/01-2013/12		●	●	4	A	433Mhz	Schrader	56029359	90518155/ 90518434	56029359AA-AB/ 56053031AC/ 56029481AA-AB
216	EU	Dodge	Caliber	2007/01-2011/12		●	●	4	A	433Mhz	Schrader	56029359	90518155/ 90518434	56029359AA-AB/ 56053031AC/ 56029481AA-AB
217	EU	Dodge	Caravan	2011/06-2014/12		●	●	4		433Mhz	Schrader	56029398		
219	EU	Dodge	Challenger	2010/01-2015/12		●	●	4	A	433Mhz	Schrader	56029398	90518291	56029400AB-AD
218	EU	Dodge	Challenger	2008/01-2009/12		●	●	4	A	433Mhz	Schrader	56029400	90518291	56029400AB-AD
222	EU	Dodge	Charger	2014/10-2015/12		○	●	4	0	433Mhz	Schrader	68241067AA	90518291/ 90518358	68241067AA
221	EU	Dodge	Charger	2010/01-2014/09		●	●	4	A	433Mhz	Schrader	56029398AB	90518291/ 90518358	56029398AB
220	EU	Dodge	Charger	2009/01-2009/12		●	●	4	A	433Mhz	Schrader	56029400	90518291/ 90518358	56029398AA-AB
223	EU	Dodge	Dakota	2009/01-2015/12		●	●	4	A	433Mhz	Schrader	56029359	90518155/ 90518434	56029359AA-AB/ 56053031AC/ 56029481AA-AB
224	EU	Dodge	Durango	2011/01-2015/12		●	●	4	A	433Mhz	Schrader	56029398	90518358	56029398AA-AB
225	EU	Dodge	Grand Caravan	2011/01-2015/12		●	●	4	A	433Mhz	Schrader	56029398	90518358	56029398AA-AB
227	EU	Dodge	Journey	2011/01-2015/12		●	●	4	A	433Mhz	Schrader	56029398	90518358	56029398AA-AB
226	EU	Dodge	Journey	2010/01-2010/12		●	●	4	A	433Mhz	Schrader	56029359		56029359
228	EU	Dodge	Nitro	2007/01-2011/12		●	●	4	A	433Mhz	Schrader	56029359	90518155/ 90518434	56029359AA-AB/ 56053031AC/ 56029481AA-AB
230	EU	Dodge	Ram	2014/01-2015/12		○	●	4	A	433Mhz	TRW	68239720AA		68239720A

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
229	EU	Dodge	Ram	2010/01-2013/12		●	●	4	A	433Mhz	Schrader	56029398	90518358	56029398AA-AB
231	EU	Dodge	Viper	2013/01-2015/12		●	●	4	A	433Mhz	Schrader	56029400	90518358	56029398AA-AB
232	EU	Ferrari	458 Italia	2009/11-2015/10		○	●	4	A	433Mhz	Huf/Beru	228887	0532207011	RDE011
233	EU	Ferrari	550 Maranello	2002/03-2014/12		○	●	4	A	433Mhz	Huf/Beru	224549	0532207001	RDE001
234	EU	Ferrari	575 M-Maranello	2002/09-2006/02		○	●	4	A	433Mhz	Huf/Beru	224549	0532207001	RDE001
235	EU	Ferrari	599 GTB	2006/04-2012/06		○	○	4	A	433Mhz	Huf/Beru	224549	0532207001	RDE001
236	EU	Ferrari	612 Scaglietti	2004/03-2011/01		○	●	4	A	433Mhz	Huf/Beru	224549	0532207001	RDE001
237	EU	Ferrari	California	2008/10-2014/10		○	●	4	S	433Mhz	Huf/Beru	228887	0532207011	RDE011
238	EU	Ferrari	Enzo	2003/01-2006/11		○	●	4	A	433Mhz	Huf/Beru	193867	0532207005	RDE005
239	EU	Ferrari	F12 Berlinetta	2012/10-2015/12		○	●	4	A	433Mhz	Huf/Beru	282189	0532207011	RDE011
241	EU	Ferrari	F430	2007/07-2009/10		○	●	4	A	433Mhz	Huf/Beru	282189	0532207011	RDE011
240	EU	Ferrari	F430	2004/09-2007/06		○	●	4	A	433Mhz	Huf/Beru	224549	0532207001	RDE001
242	EU	Ferrari	FF	2011/06-2015/12		○	●	4	A	433Mhz	Huf/Beru	282189	0532207011	RDE011
243	EU	Ferrari	FXX	2005/07-2006/12		○	●	4	A	433Mhz	Huf/Beru	193867	0532207005	RDE005
244	EU	Fiat	500	2007/01-2015/12		○	●	4	A	433Mhz	Schrader	53104671	90518358	53104671
245	EU	Fiat	500L	2007/01-2015/12		○	●	4	A	433Mhz	Schrader	56029398AB	90518358	56029398AB
246	EU	Fiat	500X	2015/01-2015/12		○	●	4	A	433Mhz	Continental	53305555		
247	EU	Fiat	Bravo	2007/01-2014/09		○	●	4	A	433Mhz	TRW	51839114		51839114
248	EU	Fiat	Croma	2005/02-2011/12		○	●	4	A	433Mhz	TRW	51839114		51839114
249	EU	Fiat	Doblo	2012/12-2015/12		○	●	4	A	433Mhz	Schrader	53104671	90518358	53104671
250	EU	Fiat	Ducato	2014/06-2015/12		○	●	4	A	433Mhz	Schrader	05154876AA		670002790
252	EU	Fiat	Freemont	2014/07-2015/09		○	●	4	A	433Mhz	Schrader	68241067AA	90518358	68241067AA
251	EU	Fiat	Freemont	2011/03-2014/06		○	●	4	A	433Mhz	Schrader	56029398AB	90518358	56029398AB
253	EU	Fiat	Grande Punto	2005/01-2015/12		○	●	4	A	433Mhz	TRW	51839114		51839114
255	EU	Fiat	Linea	2007/03-2015/12		○	●	4	A	433Mhz	Schrader	53104671	90518358	53104671
256	EU	Fiat	Punto	2005/09-2015/12		○	●	4	A	433Mhz	TRW	51839114		51839114
257	EU	Fiat	Punto Evo	2009/01-2012/12		○	●	4	A	433Mhz	TRW	51839114		51839114
258	EU	Fiat	Qubo	2007/10-2015/12		○	●	4	A	433Mhz	Schrader	53104671	90518358	53104671
259	EU	Fiat	Scudo	2006/01-2015/12		○	●	4		433Mhz	Schrader	9802003680		9802003680
260	EU	Fiat	Strada	2012/01-2015/12		○	●	4	A	433Mhz	Schrader	53104671	90518358	53104671
262	EU	Fiat	Ulysse	2005/10-2010/12		○	●	4	O	433Mhz	Continental	9681102280	S180014805Z	S120123004
261	EU	Fiat	Ulysse	2002/06-2005/09		○	●	4	O	433Mhz	Schrader	9634866180	9634866180	
266	EU	Ford	Ecosport	2012/07-2014/09		○	●	4	S	433Mhz	Schrader	DR3V1A180BB		
269	EU	Ford	Escape	2012/05-2015/12		●	●	4	S	433Mhz	Schrader	BB5T1A180AA		
270	EU	Ford	Explorer	2011/01-2015/12		●	●	4	S	433Mhz	Schrader	BB5T1A180AA	90518346	BB5T1A180AA
271	EU	Ford	Fiesta	2014/05-2015/12		○	●	4	S	433Mhz	Schrader	EV6T1A180CB/ EV6T1A150CB/ EV6T1A180DB/		EV6T-1A180-CB
272	EU	Ford	Fiesta ST	2014/01-2015/12		○	●	4	S	433Mhz	SCHRADER	DR3V1A180DA/ BB5T1A180AA/ DV6T1A180AA	90518346	DR3V-1A180-DA
2653	EU	Ford	Focus ST	2015/03-2015/12		○	●	4	S	433Mhz	Schrader	DR3V1A180DA/ BB5T1A180AA/ DV6T1A180AA	90518346	DR3V-1A180-DA
274	EU	Ford	Focus ST	2010/12-2015/03		○	●	4	S	433Mhz	SCHRADER	DR3V1A180DA/ BB5T1A180AA/ DV6T1A180AA	90518346	DR3V-1A180-DA

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, 0=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
2655	EU	Ford	F-Series	2010/01-2015/12		○	●	4	S	433Mhz	Schrader	BB5T1A180AA		
275	EU	Ford	F-Series	2008/09-2009/12		○	●	4	S	433Mhz	Schrader	BB5T1A180AA		
2654	EU	Ford	Ka	2014/12-2015/12		○	●	4	S	433Mhz	Schrader	56029398		53104671
277	EU	Ford	Ka	2008/09-2013/12		○	●	4	S	433Mhz	Schrader	56029398		53104671
279	EU	Ford	Mondeo	2007/03-2014/10		●	●	4	S	433Mhz	Continental	8G921A159AC/ 8G921A189KB	S180084730Z	S180052020
282	EU	Ford	Mustang	2014/05-2015/12		○	●	4	S	433Mhz	Schrader	EV6T1A180CB		
281	EU	Ford	Mustang	2004/09-2014/04		○	●	4	S	433Mhz	Schrader	DR3V1A180BB		
287	EU	Ford	Tourneo Courier	2014/03-2014/09		○	●	4	S	433Mhz	Schrader	DR3V1A180BB		
2652	EU	Ford	Transit	2014/03-2015/12		○	●	4	S	433Mhz	Schrader	BB5T1A180AA	90518346	BB5T1A180AA/ BB5T1A180BA
289	EU	Ford	Transit	2013/01-2014/03		○	●	4	S	433Mhz	Schrader	BB5T1A180AA	90518346	BB5T1A180AA/ BB5T1A180BA
292	EU	Ford	Transit Courier	2014/02-2015/12		○	●	4	S	433Mhz	Schrader	DR3V1A180BB/ EV6T1A180CB		
2787	EU	Foton	Tunland	2011/01-2015/12		○	●	4				P1311220001A0		
294	EU	GMC	Sierra	2013/04-2019/06		●	●	4		433Mhz	Schrader	22853740	90518185	22853740
295	EU	GMC	Yukon	2005/01-2013/12		●	●	4	S	433Mhz	Schrader	22853740	90518185	22853740
296	EU	Holden	WM Caprice	2007/01-2015/12		○	●	4		433Mhz	Schrader	25789964	90518185	25789964/ 22853740/ 13581561
297	EU	Honda	Accord	2014/01-2015/12		●	●	4	0	433Mhz	Continental	42753TLOG52	S180052059Z	S180052059
298	EU	Honda	Civic	2015/01-2015/12		●	●	4		433Mhz	Continental	42753TLOG520		
299	EU	Honda	Jazz	2014/11-2015/12		●	●	4	0	433Mhz	Continental	42753TLOG52	S180052059Z	S180052059
300	EU	HSV	ClubSport GXP	2010/01-2010/12		○	●	4		433Mhz	Schrader	25789964/ 22853740/ 13581561	90518185	25789964/ 22853740/ 13581561
301	EU	HSV	Gange	2007/01-2012/12		○	●	4		433Mhz	Schrader	25789964	90518185	25789964/ 22853740/ 13581561
302	EU	HSV	GTS	2007/01-2012/12		○	●	4		433Mhz	Schrader	25789964	90518185	25789964/ 22853740/ 13581561
303	EU	HSV	Maloo GXP	2010/01-2010/12		○	●	4		433Mhz	Schrader	25789964	90518185	25789964/ 22853740/ 13581561
304	EU	HSV	R8	2007/01-2012/12		○	●	4		433Mhz	Schrader	25789964	90518185	25789964/ 22853740/ 13581561
305	EU	HSV	Senator	2007/01-2012/12		○	●	4		433Mhz	Schrader	25789964	90518185	25789964/ 22853740/ 13581561
306	EU	Hummer	H2	2002/01-2008/12		○	●	4	S	433Mhz	Schrader	25789964/ 22853740/ 13581561	90518185	25789964/ 22853740/ 13581561
308	EU	Hummer	H3	2007/01-2012/12		●	●	4	S	433Mhz	Schrader	25789964/ 22853740/ 13581561	90518185	25789964/ 22853740/ 13581561
307	EU	Hummer	H3	2005/03-2006/12		●	●	4	S	433Mhz	Schrader	25789964/ 22853740/ 13581561	90518185	25789964/ 22853740/ 13581561

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, 0=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
309	EU	Hyundai	Accent	2014/03-2015/12		●	●	4	0	433Mhz	Continental	529331J000	S180084710Z	S180052012
310	EU	Hyundai	Azera	2011/01-2015/12		●	●	4	0	433Mhz	TRW	529333V100		52933-3V100
2587	EU	Hyundai	Centennial	2013/07-2015/12		○	●	4	0	433Mhz	TRW	529333M000	220916-101	220916-101
311	EU	Hyundai	Elantra	2014/01-2015/12		●	●	4	0	433Mhz	TRW	529333X305		52933-3X305
2588	EU	Hyundai	Elantra Neos	2008/01-2012/12		○	●	4	0	433Mhz	Continental	529332L600/ 529332L000	S180014820Z	S180030002
313	EU	Hyundai	Equus	2014/01-2015/12		●	●	4	0	433Mhz	TRW	529333M000		52933-3M000
315	EU	Hyundai	Genesis Coupe	2014/01-2015/12		●	●	4	0	433Mhz	Continental	529333N100	S180052092Z	S180052092
316	EU	Hyundai	Grand SantaFe	2013/05-2015/12		●	●	4	0	433Mhz	Continental	529333N100	S180052092Z	S180052092
318	EU	Hyundai	Grandeur	2014/01-2015/12		●	●	4	0	433Mhz	TRW	529333V100		52933-3V100
317	EU	Hyundai	Grandeur	2012/01-2013/12		●	●	4	0	433Mhz	TRW	529333V100		52933-3V100
320	EU	Hyundai	i10	2011/01-2015/12		●	●	4	0	433Mhz	Schrader	529332V100	90518481	52933-2V100
2749	EU	Hyundai	i20	2014/11-2015/12	IB	○	●	4	0	433Mhz	Schrader	52933C8000/ 52933C1100		
323	EU	Hyundai	i20	2014/01-2015/12	GB	●	●	4	0	433Mhz	Schrader	52933C8000/ 52933C1100		
322	EU	Hyundai	i20	2008/09-2014/05		●	●	4	0	433Mhz	Continental	529331J000	S180084710Z	S180052012
326	EU	Hyundai	i30	2014/04-2015/12		●	●	4	0	433Mhz	Continental	529333N100	S180052092Z	S180052092
325	EU	Hyundai	i30	2011/01-2014/03		●	●	4	0	433Mhz	Continental	52933A5100	S180052092Z	S180052092
324	EU	Hyundai	i30	2007/01-2012/12		●	●	4	0	433Mhz	Continental	529332L600/ 529332L000	S180014820Z	S180030002
327	EU	Hyundai	i30 cw	2009/01-2013/13		●	●	4	0	433Mhz	Continental	529332L600/ 529332L000	S180014820Z	S180030002
329	EU	Hyundai	i40	2013/08-2015/12		●	●	4	0	433Mhz	TRW	529333V600		52933-3V600
328	EU	Hyundai	i40	2011/01-2013/07		●	●	4	0	433Mhz	TRW	529333V100		52933-3V100
332	EU	Hyundai	ix20	2013/05-2015/12		●	●	4	0	433Mhz	Continental	529333N100	S180052092Z	S180052092
331	EU	Hyundai	ix20	2010/09-2013/04		●	●	4	0	433Mhz	Continental	529333N100	S180052092Z	S180052092
330	EU	Hyundai	ix20	2008/01-2010/09		○	●	4	0	433Mhz	Continental	529331J000	S180084710Z	S180052012
334	EU	Hyundai	ix35	2013/01-2015/12	Lo Line	●	●	4	0	433Mhz	TRW	529332S410/ 529332S400		52933-2S400
335	EU	Hyundai	ix35	2013/01-2015/12	Hi Line	●	●	4	0	433Mhz	TRW	529332Y450		52933-2Y450
333	EU	Hyundai	ix35	2010/01-2012/12	Lo Line	●	●	4	0	433Mhz	TRW	529333M000		52933-3M000
2750	EU	Hyundai	ix35(LCV)	2015/10-2015/12	TL	○	●	4	0	433Mhz	Schrader	52933C8000/ 52933C1100		
338	EU	Hyundai	ix55	2014/01-2015/12		○	●	4	0	433Mhz	Lear	529333J000		52933-3J000
337	EU	Hyundai	ix55	2009/01-2013/12		●	●	4	0	433Mhz	Lear	529333J000	701002	52933-3J000
336	EU	Hyundai	ix55	2006/01-2008/12		○	●	4	0	433Mhz	Lear	529333J000		52933-3J000
341	EU	Hyundai	Santa Fe	2012/08-2015/12		●	●	4	0	433Mhz	Continental	529333N100	S180052092Z	S180052092
340	EU	Hyundai	Santa Fe	2010/01-2012/07		●	●	4	0	433Mhz	Lear	529332B000		52933-2B000
339	EU	Hyundai	Santa Fe	2005/01-2009/12		○	●	4	0	433Mhz	Lear	529332B000		52933-2B000
342	EU	Hyundai	Santa Fe(LCV)	2014/03-2015/12		●	●	4	0	433Mhz	Continental	529333N100	S180052092Z	S180052092
343	EU	Hyundai	Solaris	2014/01-2015/12		●	●	4	0	433Mhz	Continental	529331J000	S180084710Z	S180052012
344	EU	Hyundai	Sonata	2014/01-2015/12		●	●	4	0	433Mhz	Continental	529331J000	S180084710Z	S180052012
345	EU	Hyundai	Tucson	2006/01-2010/12		●	●	4	0	433Mhz	TRW	529333M000		52933-3M000
347	EU	Hyundai	Veloster	2014/01-2015/12		●	●	4	0	433Mhz	Schrader	529332V100	90518481	52933-2V100
346	EU	Hyundai	Veloster	2011/03-2013/12		●	●	4	0	433Mhz	Schrader	529332V100	90518481	52933-2V100
348	EU	Infiniti	EX	2008/01-2015/12		●	●	4	0	433Mhz	Schrader	40700JY00C	90518394	40700-JY00C

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
349	EU	Infiniti	FX	2008/03-2014/12		●	●	4	0	433Mhz	Schrader	40700JY00C	90518295/ 90518394	40700-JY00C
350	EU	Infiniti	G37 Coupe	2008/06-2014/03		●	●	4	0	433Mhz	Schrader	40700JY00C	90518295/ 90518394	40700-JY00C
351	EU	Infiniti	G37 Sedan	2008/06-2013/03		●	●	4	0	433Mhz	Schrader	40700JY00C	90518295/ 90518394	40700-JY00C
353	EU	Infiniti	M30D	2010/01-2013/12		●	●	4	0	433Mhz	Pacific	407001LLOC	PMV-107U	40700-1LLOC
354	EU	Infiniti	M35H	2012/01-2014/12		●	●	4	0	433Mhz	Pacific	407001LLOC	PMV-107U	40700-1LLOC
355	EU	Infiniti	Q50	2014/01-2015/12		●	●	4	S	433Mhz	Continental	407003JA0A	S180052036Z	S180052036
356	EU	Infiniti	Q60	2014/01-2015/12		●	●	4	0	433Mhz	Schrader	407001AY0A	90518295	40700-1AY0A
357	EU	Infiniti	Q70	2014/01-2015/12		●	●	4	0	433Mhz	Pacific	407001LLOC	PMV-107U	40700-1LLOC
358	EU	Infiniti	QX50	2014/01-2015/12		●	●	4	0	433Mhz	Schrader	407001AY0A		40700-1AY0A
359	EU	Infiniti	QX56	2004/01-2012/12		●	●	4	0	433Mhz	Schrader	40700JY00C	90518295	40700-JY00C
360	EU	Infiniti	QX57	2004/01-2012/12		●	●	4	0	433Mhz	Schrader	40700JY00C	90518295	40700-JY00C
361	EU	Infiniti	QX70	2014/01-2015/12		●	●	4	0	433Mhz	Schrader	407001AY0A		40700-1AY0A
363	EU	Jaguar	F-Type	2013/03-2015/12		○	●	4	A	433Mhz	Continental	C2D21599	S180052028Z	S180052028
364	EU	Jaguar	XF	2007/01-2015/12		○	●	4	A	433Mhz	Continental	C2Z15016	S180084770Z	S180052022
366	EU	Jaguar	XJ	2010/01-2015/12		○	●	4	A	433Mhz	Continental	C2Z15016	S180084770Z	S180052022
365	EU	Jaguar	XJ	2005/01-2009/12		○	●	4	A	433Mhz	Continental	C2Z15016	S180084770Z	S180052022
367	EU	Jaguar	XK	2006/01-2015/12		○	●	4	A	433Mhz	Continental	C2Z15016	S180084770Z	S180052022
368	EU	Jaguar	X-Type	2007/01-2015/12		○	●	4	A	433Mhz	Continental	C2Z15016	S180084770Z	S180052022
370	EU	Jeep	Cherokee	2014/01-2015/12		●	●	4	A/O	433Mhz	TRW	68157568AB		68239720AA
369	EU	Jeep	Cherokee	2007/01-2013/12		●	●	4		433Mhz	Schrader	56029359		56029359
371	EU	Jeep	Cherokee KL	2014/01-2015/12		●	○	4	A	433Mhz	TRW	68239720AB		68157568AB
372	EU	Jeep	Commander	2006/01-2010/12		●	●	4	A	433Mhz	Schrader	56029359	90518155/ 90518434	56029359AA-AB/ 56053031AC/ 56029481AA-AB
373	EU	Jeep	Compass	2011/01-2015/12		●	●	4	A	433Mhz	Schrader	56029359	90518434	56029481AB
375	EU	Jeep	Grand Cherokee	2011/01-2015/12		●	●	4	A	433Mhz	Schrader	56029398AB	90518358	56029398AB
374	EU	Jeep	Grand Cherokee	2006/06-2010/12		●	●	4	A	433Mhz	Schrader	56029359	90518155/ 90518434	56029359AA-AB/ 56053031AC/ 56029481AA-AB
377	EU	Jeep	Liberty	2007/01-2015/12		●	●	4	A	433Mhz	Schrader	56029359	90518434	56029359
376	EU	Jeep	Liberty	2005/01-2006/12		●	●	4	A	433Mhz	Continental	68001698AB		
378	EU	Jeep	Patriot	2006/12-2015/12		●	●	4	A	433Mhz	Schrader	56029359	90518434	56029359
379	EU	Jeep	Renegade	2015/01-2015/12		○	●	4	A/O	433Mhz	Continental	53305555	S180150008B	S180150008
381	EU	Jeep	Wrangler	2010/09-2015/12		●	●	4	A	433Mhz	Schrader	56029398AB	90518358	56029398AB
380	EU	Jeep	Wrangler	2007/07-2010/08		●	●	4	A	433Mhz	Schrader	56029359	90518155/ 90518434	56029359AA-AB/ 56053031AC/ 56029481AA-AB
382	EU	KIA	Cadenza	2013/01-2015/12		●	●	4		433Mhz	Continental	529333N100	S180052092Z	S180052092
384	EU	KIA	Carens	2014/01-2015/12		●	●	4	0	433Mhz	Continental	529333N100	S180052092Z	S180052092
383	EU	KIA	Carens	2012/12-2013/12		○	●	4	0	433Mhz	Continental	529333N100	S180052092Z	S180052092
386	EU	KIA	Cee'd	2012/03-2015/12		●	●	4	0	433Mhz	Continental	529333N100	S180052092Z	S180052092
385	EU	KIA	Cee'd	2006/01-2012/02		●	●	4	0	433Mhz	Continental	529332L600	S180014820Z	S180030002
388	EU	KIA	Ceed-Proceed	2012/09-2015/12		●	●	4	0	433Mhz	Continental	529333N100	S180052092Z	S180052092
387	EU	KIA	Ceed-Proceed	2009/07-2012/08		●	●	4	0	433Mhz	Continental	529332L600/ 529332L000	S180014820Z	S180030002

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
390	EU	KIA	Optima	2013/08-2015/12		●	●	4	0	433Mhz	Continental	529333N100	S180052092Z	S180052092
389	EU	KIA	Optima	2011/01-2013/07		●	●	4	0	433Mhz	Continental	529331J000	S180084710Z	S180052012
391	EU	KIA	Picanto	2014/04-2015/12		●	●	4	0	433Mhz	Continental	529333N100	S180052092Z	S180052092
394	EU	KIA	Rio	2014/07-2015/12	Hi line	●	●	4	0	433Mhz	TRW	529333V600		52933-3V600
395	EU	KIA	Rio	2014/07-2015/12	Lo line	●	●	4	0	433Mhz	TRW	529333X305		52933-3X305
393	EU	KIA	Rio	2012/01-2014/06		●	●	4	0	433Mhz	TRW	529333X300		52933-3X300
398	EU	KIA	Sorento	2014/07-2015/12		●	●	4	0	433Mhz	Continental	529332M650	S180052092Z	S180052092
397	EU	KIA	Sorento	2012/07-2014/07		●	●	4	0	433Mhz	Continental	52933A5100	S180052092Z	S180052092
396	EU	KIA	Sorento	2009/01-2012/09		●	●	4	0	433Mhz	Continental	529331J000	S180084710Z	S180052012
400	EU	KIA	Soul	2013/11-2015/12		●	●	4	0	433Mhz	Schrader	52933B2100		52933-B2100
399	EU	KIA	Soul	2009/02-2013/12		●	●	4	0	433Mhz	Continental	529331J000	S180084710Z	S180052012
403	EU	KIA	Sportage	2014/01-2015/12		●	●	4	0	433Mhz	TRW	529332S410		52933-2S410
402	EU	KIA	Sportage	2012/01-2013/12	Lo line	●	●	4	0	433Mhz	TRW	529333X300		52933-3X300
401	EU	KIA	Sportage	2010/01-2013/12	Hi line	●	●	4	0	433Mhz	TRW	529333M000		52933-3M000
405	EU	KIA	Venga	2014/04-2015/12		●	●	4	A	433Mhz	Continental	529333N100	S180052092Z	S180052092
404	EU	KIA	Venga	2010/06-2014/04		●	●	4	0	433Mhz	Continental	529331J000	S180084710Z	S180052012
406	EU	Lamborghini	Aventador	2011/05-2015/12		○	●	4	A	433Mhz	Huf/Beru	7PP907275F	0532207011	RDE011
407	EU	Lamborghini	Gallardo	2007/01-2015/12		○	●	4	A	433Mhz	Huf/Beru	7PP907275F	0532207011	RDE011
408	EU	Lamborghini	Murcielago	2007/01-2013/12		○	●	4	A	433Mhz	Huf/Beru	7PP907275F	0532207011	RDE011
409	EU	Lancia	Delta	2008/01-2014/05		○	●	4		433Mhz	TRW	51839114		51839114
2780	EU	Lancia	Flavia	2012/01-2013/12		○	●	4	A	433Mhz	Continental	68078768AA		SE57773
410	EU	Lancia	Flavia	2010/10-2011/12		○	●	4	0	433Mhz	Continental	68078768AA		SE57773
413	EU	Lancia	Phedra	2005/10-2010/12		○	●	4		433Mhz	Continental	9681102280	S180014805Z	S120123004
412	EU	Lancia	Phedra	2002/06-2005/09		○	●	4	S	433Mhz	Schrader	9634866180	9634866180	9634866180
414	EU	Lancia	Thema	2011/01-2015/12		○	●	4	A	433Mhz	Schrader	53104671	90518358	53104671
416	EU	Lancia	Voyager	2014/09-2015/12		○	●	4	A	433Mhz	Schrader	53104671	90518358	53104671
415	EU	Lancia	Voyager	2011/01-2014/08		○	●	4	A	433Mhz	Schrader	68001698AB	90518155/ 90518434	56029359AA-AB/ 56053031AC/ 56029481AA-AB
417	EU	Landrover	Discovery 3	2005/01-2009/12		●	●	4	A	433Mhz	Continental	LR031712	A2C59511308	T120123002
418	EU	Landrover	Discovery 3	2005/01-2009/12		●	●	5	A	433Mhz	Continental	LR031712	A2C59511308	T120123002
419	EU	Landrover	Discovery 4	2010/01-2014/05		●	●	4	A	433Mhz	Continental	LR031712	A2C59511308	T120123002
420	EU	Landrover	Discovery 4	2010/01-2014/05		●	●	5	A	433Mhz	Continental	LR031712	A2C59511308	T120123002
421	EU	Landrover	Evoque	2011/07-2015/12		●	●	4	A	433Mhz	Continental	LR031712	A2C59511308	T120123002
422	EU	Landrover	Evoque	2011/07-2015/12		●	●	5	A	433Mhz	Continental	LR031712	A2C59511308	T120123002
423	EU	Landrover	FreeLander	2005/01-2014/12		●	●	4	A	433Mhz	Continental	LR021935	S180084770Z	S180052022
424	EU	Landrover	FreeLander	2005/01-2014/12		●	●	5	A	433Mhz	Continental	LR021935	S180084770Z	S180052022
2747	EU	Landrover	Range Rover	2010/01-2012/12		●	●	4	A	433Mhz	Continental	LR021935	S180084770Z	S180052022
2748	EU	Landrover	Range Rover	2010/01-2012/12		●	●	5	A	433Mhz	Continental	LR021935	S180084770Z	S180052022
427	EU	Landrover	Range Rover	2005/01-2009/12		●	●	4	A	433Mhz	Continental	LR021935	S180084770Z	S180052022
428	EU	Landrover	Range Rover	2005/01-2009/12		●	●	5	A	433Mhz	Continental	LR021935	S180084770Z	S180052022
425	EU	Landrover	Range Rover	2002/03-2003/02		●	●	4	A	433Mhz	Huf/Beru	YDB000061	0532207003	RDE003
426	EU	Landrover	Range Rover	2002/03-2003/02		●	●	5	A	433Mhz	Huf/Beru	YDB000061	0532207003	RDE003
431	EU	Landrover	Range Rover Sport	2014/06-2015/12		●	●	4	A	433Mhz	Continental	LR031712	A2C59511308	T120123002
432	EU	Landrover	Range Rover Sport	2014/06-2015/12		●	●	5	A	433Mhz	Continental	LR031712	A2C59511308	T120123002
433	EU	Landrover	Range Rover Vogue	2005/01-2013/12		●	●	4	A	433Mhz	Continental	LR021935	S180084770Z	S180052022

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, 0=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
434	EU	Landrover	Range Rover Vogue	2005/01-2013/12		●	●	5	A	433Mhz	Continental	LR021935	S180084770Z	S180052022
435	EU	Lexus	C-CUV	2014/11-2015/12		●	●	4	0	433Mhz	Pacific	4260742020/ 4260702030/ 4260702031	PMV-C210	
436	EU	Lexus	CT	2014/06-2015/12		●	●	4	0	433Mhz	Pacific	4260742020/ 4260702030/ 4260702031	PMV-C210	
437	EU	Lexus	CT 200h	2014/05-2015/12		●	●	4	0	433Mhz	Pacific	4260742020/ 4260702030/ 4260702031	PMV-C210	
439	EU	Lexus	ES 250	2014/05-2015/12		●	●	4	0	433Mhz	Pacific	4260742020/ 4260702030/ 4260702031	PMV-C210	
438	EU	Lexus	ES 250	2013/06-2014/04		●	●	4	0	433Mhz	Pacific	4260730070	PMV-107J	42607-30070
441	EU	Lexus	ES 300h	2014/05-2015/12		●	●	4	0	433Mhz	Pacific	4260742020/ 4260702030/ 4260702031	PMV-C210	
440	EU	Lexus	ES 300h	2013/06-2014/04		●	●	4	0	433Mhz	Pacific	4260730070	PMV-107J	42607-30070
444	EU	Lexus	ES 350	2014/05-2015/12		●	●	4	0	433Mhz	Pacific	4260742020/ 4260702030/ 4260702031	PMV-C210	
443	EU	Lexus	ES 350	2012/06-2014/04		●	●	4	0	433Mhz	Pacific	4260730070	PMV-107J	42607-30070
442	EU	Lexus	ES 350	2008/10-2012/05		●	●	4	0	433Mhz	Pacific	4260750011	PMV-107K	
446	EU	Lexus	GS 250	2014/09-2015/12		●	●	4	0	433Mhz	Pacific	4260742020/ 4260702030/ 4260702031	PMV-C210	
445	EU	Lexus	GS 250	2012/01-2014/08		●	●	4	0	433Mhz	Pacific	4260730070	PMV-107J	42607-30070
447	EU	Lexus	GS 300	2006/08-2011/12		●	●	4	0	433Mhz	Pacific	4260750011	PMV-107K	
449	EU	Lexus	GS 300h	2014/09-2015/12		●	●	4	0	433Mhz	Pacific	4260742020/ 4260702030/ 4260702031	PMV-C210	
448	EU	Lexus	GS 300h	2013/10-2014/08		●	●	4	0	433Mhz	Pacific	4260750011	PMV-107K	
452	EU	Lexus	GS 350	2014/09-2015/12		●	●	4	0	433Mhz	Pacific	4260742020/ 4260702030/ 4260702031	PMV-C210	
451	EU	Lexus	GS 350	2012/01-2014/08		●	●	4	0	433Mhz	Pacific	4260750011	PMV-107K	
450	EU	Lexus	GS 350	2006/08-2011/12		●	●	4	0	433Mhz	Pacific	4260750011	PMV-107K	
453	EU	Lexus	GS 430	2006/08-2011/12		●	●	4	0	433Mhz	Pacific	4260750011	PMV-107K	
456	EU	Lexus	GS 450h	2014/09-2015/12		●	●	4	0	433Mhz	Pacific	4260742020/ 4260702030/ 4260702031	PMV-C210	
455	EU	Lexus	GS 450h	2012/01-2014/08		●	●	4	0	433Mhz	Pacific	4260730070	PMV-107J	42607-30070
454	EU	Lexus	GS 450h	2006/02-2011/12		●	●	4	0	433Mhz	Pacific	4260750011	PMV-107K	
457	EU	Lexus	GS 460	2006/08-2011/12		●	●	4	0	433Mhz	Pacific	4260750011	PMV-107K	
459	EU	Lexus	GX 400	2014/05-2015/12		●	●	4	0	433Mhz	Pacific	4260742020/ 4260702030/ 4260702031	PMV-C210	
458	EU	Lexus	GX 400	2013/08-2014/04		●	●	4	0	433Mhz	Pacific	4260730070	PMV-107J	42607-30070
461	EU	Lexus	GX 460	2014/05-2015/12		●	●	4	0	433Mhz	Pacific	4260742020/ 4260702030/ 4260702031	PMV-C210	

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, 0=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
460	EU	Lexus	GX 460	2013/08-2014/04		●	●	4	0	433Mhz	Pacific	4260730070	PMV-107J	42607-30070
462	EU	Lexus	GX 470	2004/01-2009/12		●	●	4	0	433Mhz	Pacific	4260750011	PMV-107K	
463	EU	Lexus	HS 250h	2009/03-2015/12		●	●	4	0	433Mhz	Pacific	4260775010	PMV-107J	42607-75010
465	EU	Lexus	IS 250/IS 250C	2014/06-2015/12		●	●	4	0	433Mhz	Pacific	4260742020/ 4260702030/ 4260702031/ 4260730070	PMV-C210/ PMV-107J	
464	EU	Lexus	IS 250/IS 250C	2006/08-2014/05		●	●	4	0	433Mhz	Pacific	4260750011	PMV-107K	
467	EU	Lexus	IS 300C	2014/06-2015/12		●	●	4	0	433Mhz	Pacific	4260742020/ 4260702030/ 4260702031/ 4260730070	PMV-C210/ PMV-107J	
466	EU	Lexus	IS 300C	2006/08-2014/05		●	●	4	0	433Mhz	Pacific	4260750011	PMV-107K	
468	EU	Lexus	IS 300h	2013/08-2015/12		●	●	4	0	433Mhz	Pacific	4260742020/ 4260702030/ 4260702031/ 4260730070	PMV-C210/ PMV-107J	
470	EU	Lexus	IS 350/IS 350C	2014/06-2015/12		●	●	4	0	433Mhz	Pacific	4260742020/ 4260702030/ 4260702031/ 4260730070	PMV-C210/ PMV-107J	
469	EU	Lexus	IS 350/IS 350C	2006/08-2014/05		●	●	4	0	433Mhz	Pacific	4260750011	PMV-107K	
472	EU	Lexus	IS F	2014/06-2015/12		●	●	4	0	433Mhz	Pacific	4260742020/ 4260702030/ 4260702031/ 4260730070	PMV-C210/ PMV-107J	
471	EU	Lexus	IS F	2010/08-2014/05		●	●	4	0	433Mhz	Pacific	4260750011	PMV-107K	
473	EU	Lexus	LFA	2010/01-2012/12		●	●	4	0	433Mhz	Pacific	4260750011	PMV-107K	
475	EU	Lexus	LS 460/LS 460L	2014/05-2015/12		●	●	4	0	433Mhz	Pacific	4260742020/ 4260702030/ 4260702031	PMV-C210	
474	EU	Lexus	LS 460/LS 460L	2007/10-2014/04		●	●	4	0	433Mhz	Pacific	4260750011	PMV-107K	
477	EU	Lexus	LS 600h/LS 600hL	2014/05-2015/12		●	●	4	0	433Mhz	Pacific	4260742020/ 4260702030/ 4260702031	PMV-C210	
476	EU	Lexus	LS 600h/LS 600hL	2007/10-2014/04		●	●	4	0	433Mhz	Pacific	4260750011	PMV-107K	
479	EU	Lexus	LX 460	2014/06-2015/12		●	●	4	0	433Mhz	Pacific	4260742020/ 4260702030/ 4260702031	PMV-C210	
478	EU	Lexus	LX 460	2008/01-2014/05		●	●	4	0	433Mhz	Pacific	4260750011	PMV-107K	
480	EU	Lexus	LX 470	2005/01-2007/12		●	●	4	0	433Mhz	Pacific	4260750011	PMV-107K	
482	EU	Lexus	LX 570	2014/06-2015/12		●	●	4	0	433Mhz	Pacific	4260742020/ 4260702030/ 4260702031/ 4260730070	PMV-C210	
481	EU	Lexus	LX 570	2008/01-2014/05		●	●	4	0	433Mhz	Pacific	4260750011	PMV-107K	
2785	EU	Lexus	NX200	2014/07-2015/12		●	●	4	0	433Mhz	Pacific	4260730070	PMV-107J	42607-30070
483	EU	Lexus	NX300H	2014/03-2015/12		●	●	4	0	433Mhz	Pacific	4260730070	PMV-107J	42607-30070
485	EU	Lexus	RX 270	2014/06-2015/12		●	●	4	0	433Mhz	Pacific	4260702020/ 4260702030/ 4260702031	PMV-C210	

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
484	EU	Lexus	RX 270	2009/01-2014/05		●	●	4	0	433Mhz	Pacific	4260750011	PMV-107K	
488	EU	Lexus	RX 350	2014/06-2015/12		●	●	4	0	433Mhz	Pacific	4260702020/ 4260702030/ 4260702031	PMV-C210	
487	EU	Lexus	RX 350	2009/01-2014/05		●	●	4	0	433Mhz	Pacific	4260750011	PMV-107K	
486	EU	Lexus	RX 350	2004/02-2008/12		●	●	4	0	433Mhz	Pacific	4260750011	PMV-107K	
489	EU	Lexus	RX 400h	2004/02-2008/12		●	●	4	0	433Mhz	Pacific	4260750011	PMV-107K	
491	EU	Lexus	RX 450h	2014/06-2015/12		●	●	4	0	433Mhz	Pacific	4260702020/ 4260702030/ 4260702031	PMV-C210	
490	EU	Lexus	RX 450h	2009/01-2014/05		●	●	4	0	433Mhz	Pacific	4260750011	PMV-107K	
492	EU	Lexus	SC 430	2001/10-2010/12		●	●	4	0	433Mhz	Pacific	4260750011	PMV-107K	
283	EU	Lincoln	Navigator	2011/01-2014/12		●	●	4	S	433Mhz	Schrader	BB5T1A180AA	90518346	BB5T1A180AA
493	EU	Lotus	Elise	2008/01-2015/12		○	●	4	A	433Mhz	Schrader	13227143	90518150/ 90518408	13227143/ 12825085
494	EU	Lotus	Evora	2010/01-2015/12		○	●	4	A	433Mhz	Schrader	13227143	90518150/ 90518408	13227143/ 12825085
495	EU	Lotus	Exige	2008/01-2015/12		○	●	4	A	433Mhz	Schrader	13227143	90518150/ 90518408	13227143/ 12825085
497	EU	Maserati	Coupe	2009/07-2013/12		○	●	4	A	433Mhz	Huf/Beru	248887	0532207011	RDE011
496	EU	Maserati	Coupe	2002/01-2009/06		○	●	4	A	433Mhz	Huf/Beru	185189	0532207001	RDE001
498	EU	Maserati	Ghibli	2013/11-2015/12		○	●	4	A	433Mhz	Schrader	05154876AA/ A0009050030		670002790
501	EU	Maserati	GranTurismo	2011/01-2013/12		○	●	4	A	433Mhz	Huf/Beru	282189	0532207011	RDE011
500	EU	Maserati	GranTurismo	2008/01-2010/12		○	●	4	A	433Mhz	Huf/Beru	224549	0532207001	RDE001
504	EU	Maserati	Quattroporte	2013/01-2015/12		○	●	4		433Mhz	Schrader	05154876AA/ A0009050030		670002790
503	EU	Maserati	Quattroporte	2010/01-2015/12		○	●	4	A	433Mhz	Huf/Beru	248887	0532207011	RDE011
502	EU	Maserati	Quattroporte	2004/04-2009/12		○	●	4	S	433Mhz	Huf/Beru	185189/ 224549	0532207001	RDE001
505	EU	Maybach	Landaulet	2008/10-2014/12		○	●	4	S	433Mhz	Huf/Beru	A0055422318	0532207001	RDE001
506	EU	Maybach	Maybach 57	2002/02-2012/12		○	●	4	S	433Mhz	Huf/Beru	A0055422318	0532207001	RDE001
507	EU	Maybach	Maybach 62	2002/02-2012/12		○	●	4	S	433Mhz	Huf/Beru	A0055422318	0532207001	RDE001
508	EU	Mazda	BT-50	2011/05-2015/12		○	●	4		433Mhz	Schrader	BB5T1A180AA/ DV6T1A180AA		
509	EU	Mazda	CX-5	2011/11-2015/12		○	●	4	A	433Mhz	Continental	BBP337140B/ BHB637140	S180084720Z	S180052018
510	EU	Mazda	CX-7	2009/10-2015/12		○	●	4	A	433Mhz	Continental	BBP337140B/ BHB637140	S180084720Z	S180052018
511	EU	Mazda	CX-9	2006/10-2015/12		○	●	4	A	433Mhz	Continental	BBP337140B/ BHB637140	S180084720Z	S180052018
512	EU	Mazda	Mazda 2	2007/12-2015/12		○	●	4	A	433Mhz	Continental	BBP337140B/ BHB637140	S180084720Z	S180052018
513	EU	Mazda	Mazda 3	2009/06-2014/03		●	●	4	A	433Mhz	Continental	BBP337140B/ BHB637140	S180084720Z	S180052018
514	EU	Mazda	Mazda 5	2010/01-2015/12		●	●	4	A	433Mhz	Continental	BBP337140B/ BHB637140	S180084720Z	S180052018
515	EU	Mazda	Mazda 6	2008/02-2015/12		●	●	4	A	433Mhz	Continental	BBP337140B/ BHB637140	S180084720Z	S180052018
516	EU	Mazda	MX-5	2005/06-2015/03		●	●	4	A	433Mhz	Continental	BBP337140B/ BHB637140	S180084720Z	S180052018

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufactuer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
521	EU	Mercedes	A Class	2014/04-2015/12		●	●	4	A	433Mhz	Schrader	A0009050030		
520	EU	Mercedes	A Class	2012/12-2014/03		●	●	4	A	433Mhz	Schrader	A0009057200		A0025409017
522	EU	Mercedes	B Class	2012/12-2015/12		●	●	4	A	433Mhz	Schrader	A0009050030		A0025409017
524	EU	Mercedes	C Class	2014/03-2015/12		●	●	4	A	433Mhz	Schrader	A0009050030		
523	EU	Mercedes	C Class	2008/01-2014/02		●	●	4	A	433Mhz	Schrader	A0009050030		
530	EU	Mercedes	CL Class	2009/06-2015/12		●	●	4	A	433Mhz	Schrader	A0025409017		
529	EU	Mercedes	CL Class	1998/01-2006/02		●	●	4	A	433Mhz	Huf/Beru	A0055422318	0532207001	RDE001
527	EU	Mercedes	CLA Class	2014/06-2015/12		●	●	4	A	433Mhz	Schrader	A0009050030		
526	EU	Mercedes	CLA Class	2012/12-2014/06		●	●	4	A	433Mhz	Schrader	A0025409017		
528	EU	Mercedes	CLC Class	2008/06-2011/12		●	●	4	A	433Mhz	Schrader	A0025409017		
533	EU	Mercedes	CLK Class	2014/06-2014/12		○	●	4	S	433Mhz	Schrader	A0009050030/ A0009054100/ A0009057200		A 000 905 00 30
532	EU	Mercedes	CLK Class	2009/10-2015/12		●	●	4	A	433Mhz	Schrader	A0025409017		
531	EU	Mercedes	CLK Class	2007/04-2009/09		●	●	4	A	433Mhz	Schrader	A0025409017		
536	EU	Mercedes	CLS Class	2009/07-2015/12		●	●	4	A	433Mhz	Schrader	A0025409017		
535	EU	Mercedes	CLS Class	2005/01-2009/06		●	●	4	A	433Mhz	Continental	A0025408017	S180014730Z	S122228002
534	EU	Mercedes	CLS Class	2004/10-2005/06		●	●	4	A	433Mhz	Huf/Beru	A0055422318	0532207001	RDE001
540	EU	Mercedes	E Class	2014/06-2015/12		●	●	4	A	433Mhz	Schrader	A0009050030		
539	EU	Mercedes	E Class	2009/07-2014/05		●	●	4	A	433Mhz	Schrader	A0025409017		
538	EU	Mercedes	E Class	2005/06-2009/06		●	●	4	A	433Mhz	Continental	A0025408017	S180014730Z	S122228002
537	EU	Mercedes	E Class	2002/03-2005/05		●	●	4	A	433Mhz	Huf/Beru	A0055422318	0532207001	RDE001
542	EU	Mercedes	G Class	2007/04-2015/12		●	●	4	A	433Mhz	Schrader	A0025409017		
546	EU	Mercedes	GL Class	2013/01-2015/12		●	●	4	S	433Mhz	Schrader	A0009050030/ A0009054100/ A0009057200		A 000 905 00 30 002
545	EU	Mercedes	GL Class	2009/06-2012/12		●	●	4	A	433Mhz	Schrader	A0025409017		
544	EU	Mercedes	GL Class	2006/10-2009/05		●	●	4	A	433Mhz	Continental	A0025408017	S180014730Z	S122228002
543	EU	Mercedes	GLA Class	2014/06-2015/12		●	●	4	A	433Mhz	Schrader	A0009050030		
547	EU	Mercedes	GLK Class	2008/01-2015/12		●	●	4	A	433Mhz	Schrader	A0025409017		
549	EU	Mercedes	M Class	2011/06-2014/12		●	●	4	A	433Mhz	Schrader	A0025409017		
548	EU	Mercedes	M Class	2005/01-2011/05		●	●	4	A	433Mhz	Continental	A0025408017	S180014730Z	S122228002
552	EU	Mercedes	ML Class	2011/06-2015/12		●	●	4	A	433Mhz	Schrader	A0025409017		
551	EU	Mercedes	ML Class	2009/08-2011/05		○	●	4	S	433Mhz	Schrader	A0009054100 A0009057200 A0009050030		A 000 905 41 00
550	EU	Mercedes	ML Class	2005/07-2009/06		●	●	4	A	433Mhz	Continental	A0025408017	S180014730Z	S122228002
554	EU	Mercedes	R Class	2009/08-2015/12		●	●	4	A	433Mhz	Schrader	A0025409017		
553	EU	Mercedes	R Class	2006/01-2009/07		●	●	4	A	433Mhz	Continental	A0025408017	S180014730Z	S122228002
558	EU	Mercedes	S Class	2013/07-2015/12		●	●	4	S	433Mhz	SCHRADER	A0009054100/ A0009057200/ A0009050030	90518279/ 90518384	A0025409017/ A0035400217/ A0009054100
557	EU	Mercedes	S Class	2009/06-2013/06		●	●	4	A	433Mhz	Schrader	A0025409017		
556	EU	Mercedes	S Class	2005/10-2009/05		●	●	4	A	433Mhz	Continental	A0025408017	S180014730Z	S122228002
555	EU	Mercedes	S Class	1999/07-2005/09		●	●	4	A	433Mhz	Huf/Beru	A0055422318	0532207001	RDE001
561	EU	Mercedes	SL Class	2012/01-2015/12		●	●	4	A	433Mhz	Schrader	A0025409017		
560	EU	Mercedes	SL Class	2005/06-2011/12		●	●	4	A	433Mhz	Continental	A0025408017	S180014730Z	S122228002

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
564	EU	Mercedes	SL Roadster	2001/08-2005/06		●	●	4	A	433Mhz	Huf/Beru	A0055422318	0532207001	RDE001
562	EU	Mercedes	SLK Class	2007/04-2015/12		●	●	4	A	433Mhz	Schrader	A0025409017		
563	EU	Mercedes	SLR Class	2004/04-2015/12		●	●	4	A	433Mhz	Huf/Beru	A0055422318	0532207001	RDE001
565	EU	Mercedes	SLS Class	2010/01-2015/12		●	●	4	A	433Mhz	Schrader	A0025409017		
566	EU	Mercedes	Sprinter	2011/06-2015/12		●	●	4	A	433Mhz	Schrader	A0009050030		
568	EU	Mercedes	Sprinter Combi	2011/11-2015/12		●	●	4	A	433Mhz	Schrader	A0025409017		
567	EU	Mercedes	Sprinter Combi	2006/01-2011/10		●	●	4	A	433Mhz	Continental	A0025408017	S180014730Z	S122228002
569	EU	Mercedes	V Class	2014/02-2015/12		●	●	4	S	433Mhz	Schrader	A4479050500		A4479050500
571	EU	Mercedes	Viano	2014/06-2015/12		●	●	4	S	433Mhz	Schrader	A4479050500		A4479050500
570	EU	Mercedes	Viano	2011/01-2014/05		●	●	4	A	433Mhz	Continental	A0025408017	S180014730Z	S122228002
573	EU	Mercedes	Vito	2014/07-2015/12		○	●	4	S	433Mhz	Schrader	A4479050500		A447 905 0500 01
572	EU	Mercedes	Vito	2006/01-2014/06		●	●	4	A	433Mhz	Continental	A0025409517	A2C59511309	S122228004
574	EU	Mercedes	Vito Combi	2012/12-2015/12		●	●	4	A	433Mhz	Schrader	A0025409017		
575	EU	Mini	Cabrio	2014/07-2015/12		●	●	4	A	433Mhz	Huf/Beru	36106798872	0532207017	RDE017
578	EU	Mini	Clubman	2013/11-2015/12		○	●	4		433Mhz	Continental	36106856209		
577	EU	Mini	Clubman	2009/09-2015/12		●	●	4	A	433Mhz	Huf/Beru	36106798872	0532207017	RDE017
576	EU	Mini	Clubman	2007/08-2009/08		●	●	4	A	433Mhz	Huf/Beru	36236781847	0532207008	RDE008
579	EU	Mini	Clubvan	2012/07-2015/12		●	●	4		433Mhz	Huf/Beru	36106798872	0532207017	RDE017
581	EU	Mini	Cooper	2014/03-2014/12		●	●	4	A	433Mhz	Continental	36106856209	S180052056Z	S180052056
580	EU	Mini	Cooper	2007/09-2009/09		●	●	4	A	433Mhz	Huf/Beru	36236781847	0532207008	RDE008
583	EU	Mini	Countryman	2014/07-2015/12		●	●	4	A	433Mhz	Huf/Beru	36106798872	0532207017	RDE017
584	EU	Mini	Coupe	2011/07-2015/08		●	●	4		433Mhz	Huf/Beru	36106798872	0532207017	RDE017
585	EU	Mini	Hatchback	2013/11-2015/12		○	●	4		433Mhz	Continental	36106856209		
587	EU	Mini	Mini	2014/03-2015/12		●	●	4	A	433Mhz	Continental	36106856209	S180052056F	S180052056
586	EU	Mini	Mini	2010/01-2013/12		●	●	4	A	433Mhz	Huf/Beru	36106790054	0532207012	RDE012
588	EU	Mini	Paceman	2012/11-2015/12		●	●	4	A	433Mhz	Huf/Beru	36106798872	0532207017	RDE017
589	EU	Mini	Roadster	2011/12-2015/12		●	●	4	A	433Mhz	Huf/Beru	36106798872	0532207017	RDE017
590	EU	Mini	SAV Studie	2014/07-2014/12		●	●	4	A	433Mhz	Huf/Beru	36106798872	0532207017	RDE017
591	EU	Mitsubishi	ASX	2014/03-2015/12		●	●	4	O	433Mhz	Continental	4250C477	S180052094Z	S180052094
592	EU	Mitsubishi	Attrage	2014/08-2015/12		●	●	4	O	433Mhz	Continental	4250C275	S180052094Z	S180150004
593	EU	Mitsubishi	i-Miev	2014/08-2015/12		●	●	4	O	433Mhz	Continental	4250C477	S180052094Z	S180052094
594	EU	Mitsubishi	L200	2014/08-2015/12		●	●	4	O	433Mhz	Continental	4250C477	S180052094Z	S180052094
595	EU	Mitsubishi	Lancer	2014/08-2015/12		●	●	4	O	433Mhz	Continental	4250C477	S180052094Z	S180052094
596	EU	Mitsubishi	Mirage	2014/08-2015/12		●	●	4	O	433Mhz	Continental	4250C275	S180052094Z	S180150004
598	EU	Mitsubishi	Outlander	2014/08-2015/12		●	●	4	O	433Mhz	Continental	4250C477	S180052094Z	S180052094
599	EU	Mitsubishi	Pajero	2014/07-2015/12		●	●	4	O	433Mhz	Continental	4250C275	S180052094Z	S180150004
600	EU	Mitsubishi	Shogun	2014/08-2015/12		●	●	4	O	433Mhz	Continental	4250C275	S180052094Z	S180150004
601	EU	Mitsubishi	Spacestar	2014/07-2015/12		●	●	4	O	433Mhz	Continental	4250C275	S180052094Z	S180150004
603	EU	Nissan	370Z	2014/07-2015/12		○	●	4	O	433Mhz	Pacific	407006WY0A/ 407003HN0B	PMV-CA14	40700-6WY0A/ 40700-3HN0B
602	EU	Nissan	370Z	2008/10-2014/06		●	●	4	O	433Mhz	Schrader	40700JY00C	90518295	40700-JY00C
604	EU	Nissan	Almera	2013/05-2015/12		●	○	4	O	433Mhz	Continental	407003VU0A	S180052048Z	S180052048
605	EU	Nissan	B-EV	2014/01-2015/12		●	○	4	O	433Mhz	Continental	407003VU0A	S180052048Z	S180052048
606	EU	Nissan	C-Hatch	2014/10-2015/12		●	○	4	O	433Mhz	Continental	407003VU0A	S180052048Z	S180052048
607	EU	Nissan	Cube	2008/10-2015/12		●	●	4	O	433Mhz	Schrader	40700JY00B	90518295	40700-JY00B
609	EU	Nissan	GT-R	2014/01-2015/12	Other	●	●	4	O	433Mhz	Schrader	40700JY00C	PMV-CA14	40700-62BOA

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
610	EU	Nissan	GT-R	2014/01-2015/12	Russia	●	●	4	0	433Mhz	Pacific	4070062B0A		
608	EU	Nissan	GT-R	2007/01-2013/12		●	●	4	0	433Mhz	Schrader	40700JY00C	90518295	40700-JY00C
611	EU	Nissan	Juke	2010/06-2015/12		●	●	4	0	433Mhz	Pacific	407006WY0B	PMV-CA14	40700-6WY0B
612	EU	Nissan	Leaf	2014/05-2015/12		●	●	4	S	433Mhz	Pacific	407006WY0B	PMV-CA14	40700-6WY0B
614	EU	Nissan	Micra	2014/07-2015/12		●	●	4		433Mhz	Pacific	407006WY0A/ 407003HNOB	PMV-CA14	40700-6WY0A/ 40700-3HNOB
613	EU	Nissan	Micra	2010/03-2014/06		●	●	4	0	433Mhz	Pacific	407001LLOC	PMV-107U	40700-1LLOC
616	EU	Nissan	Murano	2014/06-2015/12		●	●	4	0	433Mhz	Pacific	407006WY0A	PMV-CA14	40700-6WY0A
615	EU	Nissan	Murano	2007/10-2014/05		●	●	4	0	433Mhz	Schrader	40700JY00B	90518295	40700-JY00B
618	EU	Nissan	Navara	2014/09-2015/12		●	○	4	0	433Mhz	Continental	407003VU0A	S180052048Z	S180052048
619	EU	Nissan	Navara	2014/09-2015/12		●	●	4	0	433Mhz	Schrader	40700JY00B	90518295	40700-JY00B
617	EU	Nissan	Navara	2004/10-2014/08		●	●	4	0	433Mhz	Schrader	40700JY00B	90518295	40700-JY00B
621	EU	Nissan	Note	2013/08-2015/12		●	○	4	S	433Mhz	Continental	407003VU0A	S180052048Z	S180052048
620	EU	Nissan	Note	2012/10-2013/07		●	○	4	0	433Mhz	Continental	407003VU0A	S180052048Z	S180052048
622	EU	Nissan	NV200	2013/08-2015/12		●	○	4	0	433Mhz	Continental	407003VU0A	S180052048Z	S180052048
2777	EU	Nissan	Pathfinder	2013/06-2015/12		●	●	4		433Mhz	Continental	407003JA0A		40700-3JA0A
623	EU	Nissan	Pathfinder	2004/01-2013/05		●	●	4	0	433Mhz	Schrader	40700JY00B		40700-JY00B
624	EU	Nissan	Patrol	2008/01-2010/12		●	●	4	0	433Mhz	Pacific	407001LLOC	PMV-107U	40700-1LLOC
625	EU	Nissan	Pixo	2009/01-2014/12		●	●	4		433Mhz	Schrader	40700JY00B	90518295	40700-JY00B
626	EU	Nissan	Primera	2002/01-2007/05		●	●	4	0	433Mhz	Schrader	40700AV600		40700-AV600
627	EU	Nissan	Pulsar	2014/07-2015/12		●	○	4	0	433Mhz	Continental	407003VU0A	S180052048Z/ S180052048E	S180052048
628	EU	Nissan	Qashqai	2013/12-2015/12		●	○	4	0	433Mhz	Continental	407003VU0A	S180052048Z	S180052048
629	EU	Nissan	Sentra	2014/08-2015/12		●	○	4	0	433Mhz	Continental	407003VU0A	S180052048Z	S180052048
630	EU	Nissan	Teana	2014/01-2015/12		●	●	4	S	433Mhz	Continental	407003JA0A	S180052036Z	S180052036
631	EU	Nissan	Tiida/Versa	2014/07-2015/12		●	○	4	0	433Mhz	Continental	407003VU0A	S180052048Z	S180052048
632	EU	Nissan	X-Trail	2013/11-2015/12		●	○	4	0	433Mhz	Continental	407003VU0A	S180052048Z	S180052048
2754	EU	Opel/Vauxhall	Adam	2015/01-2015/12		○	●	4	0	433Mhz	Schrader	13581561		13581561
635	EU	Opel/Vauxhall	Adam	2014/08-2014/12		○	●	4	A	433Mhz	Schrader	13581561		13581561
2768	EU	Opel/Vauxhall	Adam	2014/01-2014/07		○	●	4	A	433Mhz	Schrader	13581562		13581562
633	EU	Opel/Vauxhall	Adam	2012/01-2013/12		○	●	4		433Mhz	Schrader	13581562		13581562
2755	EU	Opel/Vauxhall	Adam (LCV)	2015/01-2015/12		○	●	4	0	433Mhz	Schrader	13581561		13581561
636	EU	Opel/Vauxhall	Adam (LCV)	2014/03-2014/12		○	●	4	A	433Mhz	Schrader	13581561		13581561
2764	EU	Opel/Vauxhall	Ampera	2013/02-2015/12		○	●	4		433Mhz	Schrader	13348393	90518407	13348393
2756	EU	Opel/Vauxhall	Ampera	2012/05-2013/01		○	●	4	A	433Mhz	Schrader	13348393	90518407	13348393
637	EU	Opel/Vauxhall	Ampera	2011/09-2012/04		○	●	4	A	433Mhz	Schrader	13348393	90518407	13348393
640	EU	Opel/Vauxhall	Antara	2014/06-2015/12		○	●	4	0	433Mhz	Schrader	13581560		13581560
639	EU	Opel/Vauxhall	Antara	2010/11-2014/05		○	●	4	A	433Mhz	Schrader	20922901	90518390	20922901
638	EU	Opel/Vauxhall	Antara	2006/01-2010/10		○	●	4		433Mhz	Schrader	25789964		25789964
641	EU	Opel/Vauxhall	Astra H	2004/01-2009/09		○	●	4	S/A	433Mhz	Schrader	13354312		13354312
2757	EU	Opel/Vauxhall	Astra J	2015/01-2015/12		○	●	4	0	433Mhz	Schrader	13581560		13581560
644	EU	Opel/Vauxhall	Astra J	2014/06-2014/12		○	●	4	A	433Mhz	Schrader	13581560		13581560
643	EU	Opel/Vauxhall	Astra J	2011/09-2014/05		○	●	4	A/O	433Mhz	Schrader	13348393		
642	EU	Opel/Vauxhall	Astra J	2009/10-2011/09		○	●	4	0	433Mhz	Schrader	13327259		
2758	EU	Opel/Vauxhall	Cascada	2015/01-2015/12		○	●	4	0	433Mhz	Schrader	13581560		13581560
646	EU	Opel/Vauxhall	Cascada	2014/06-2014/12		○	●	4	A	433Mhz	Schrader	13581560		13581560

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow: Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, 0=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
645	EU	Opel/Vauxhall	Cascada	2013/01-2014/05		○	●	4	A	433Mhz	Schrader	1331134/ 13348393/ 13327259	90518407	1331134/ 13348393/ 13327259
647	EU	Opel/Vauxhall	Corsa D	2014/06-2014/10		○	●	4	A	433Mhz	Schrader	13581562		13581562
648	EU	Opel/Vauxhall	Corsa E	2014/11-2015/12		○	●	4	0	433Mhz	Schrader	13581561		13581561
651	EU	Opel/Vauxhall	Insigna	2014/05-2015/12		○	●	4	A	433Mhz	Schrader	13581560		13581560
2769	EU	Opel/Vauxhall	Insigna	2013/01-2014/04		○	●	4	A	433Mhz	Schrader	13348393		13348393
650	EU	Opel/Vauxhall	Insigna	2011/09-2012/12		○	●	4		433Mhz	Schrader	13348393		13348393
649	EU	Opel/Vauxhall	Insigna	2008/01-2011/09		○	●	4	A	433Mhz	Schrader	1331134/ 13348393/ 13327259		1331134/ 13348393/ 13327259
2751	EU	Opel/Vauxhall	Karl/Viva	2015/01-2015/12		○	●	4	S	433Mhz	Schrader	13589601/ 13598773		
2759	EU	Opel/Vauxhall	Meriva B	2015/01-2015/12		○	●	4	0	433Mhz	Schrader	13581561		13581561
652	EU	Opel/Vauxhall	Meriva B	2014/08-2014/12		○	●	4	A	433Mhz	Schrader	13581561		13581561
653	EU	Opel/Vauxhall	Mokka	2012/06-2015/12		○	●	4	0	433Mhz	Schrader	25789964		25789964
656	EU	Opel/Vauxhall	Signum	2002/08-2009/08		○	●	4	A	433Mhz	Schrader	13172567	13172567/ 24437708	13172567
657	EU	Opel/Vauxhall	Vectra	2002/08-2008/08		○	●	4	A	433Mhz	Schrader	13172567	13172567/ 24437708	13172567
659	EU	Opel/Vauxhall	Vectra Estate	2009/08-2014/01		○	●	4	A	433Mhz	Schrader	PA66CF35	13172567 /24437708	
658	EU	Opel/Vauxhall	Vectra Estate	2002/10-2009/07		○	●	4		433Mhz	Schrader	13172567	13172567/ 24437708	13172567
661	EU	Opel/Vauxhall	Vivaro	2014/03-2015/12		○	●	4	0	433Mhz	SCHRADER	407001628R		407001628R-B RDE024/RDE026
663	EU	Opel/Vauxhall	Zafira B	2009/09-2015/12		○	●	4	A	433Mhz	Schrader	13581560		13581560
2760	EU	Opel/Vauxhall	Zafira B	2009/01-2009/08		○	●	4	A	433Mhz	Schrader	13354312		13354312
662	EU	Opel/Vauxhall	Zafira B	2004/01-2008/12		○	●	4	0	433Mhz	Schrader	13354312		13354312
2765	EU	Opel/Vauxhall	Zafira tourer	2013/01-2014/05		○	●	4	A	433Mhz	Schrader	1331134/ 13327259/ 13348393		1331134/ 13327259/ 13348393
664	EU	Opel/Vauxhall	Zafira tourer	2011/09-2012/12		○	●	4		433Mhz	Schrader	1331134/ 13327259/ 13348393		1331134/ 13327259/ 13348393
2762	EU	Opel/Vauxhall	Zafira Tourer C	2015/01-2015/12		○	●	4	0	433Mhz	Schrader	13581560		13581560
666	EU	Opel/Vauxhall	Zafira Tourer C	2014/06-2014/12		○	●	4	A	433Mhz	Schrader	13581560		13581560
2761	EU	Opel/Vauxhall	Zafira Tourer C	2013/01-2014/05		○	●	4	A	433Mhz	Schrader	1331134		
665	EU	Opel/Vauxhall	Zafira Tourer C	2009/09-2012/12		○	●	4	0	433Mhz	Schrader	1331134		
685	EU	Peugeot	1007	2005/01-2009/12		●	●	4	0	433Mhz	Continental	543093/ 5430T4	S180014805Z	S120120001
668	EU	Peugeot	108	2014/08-2015/12		○	●	4	S	433Mhz	Pacific	4260742020	PMV-C210	42607-42020
2660	EU	Peugeot	2008	2014/05-2015/12		○	●	4	S	433Mhz	Schrader	9802003680/ 9811536380		9802003680/ 9811536380
686	EU	Peugeot	2008	2013/02-2014/04		○	●	4		433Mhz	Schrader	9802003680/ 9811536380		9802003680/ 9811536380
670	EU	Peugeot	207	2013/10-2015/12		○	●	4	0	433Mhz	Schrader	9802003680/ 9811536380		9802003680/ 9811536380
669	EU	Peugeot	207	2006/01-2013/09		●	●	4	0	433Mhz	Continental	543093/ 5430T4	S180014805Z	S120120001

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow: Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
2661	EU	Peugeot	208	2015/01-2015/12		○	●	4	S	433Mhz	Schrader	9802003680/ 9811536380		9802003680/ 9811536380
671	EU	Peugeot	208	2014/01-2014/12		○	●	4	S	433Mhz	Schrader	9802003680/ 9811536380		9802003680/ 9811536380
2662	EU	Peugeot	208	2012/01-2013/12		○	●	4		433Mhz	Schrader	9802003680/ 9811536380		9802003680/ 9811536380
688	EU	Peugeot	3008	2013/10-2015/12		○	●	4	O	433Mhz	Schrader	9802003680/ 9811536380		9802003680/ 9811536380
687	EU	Peugeot	3008	2008/11-2013/09		●	●	4	O	433Mhz	Schrader	5430W0	90818333	9673860880
692	EU	Peugeot	3008 (LCV)	2008/01-2015/12		○	●	4		433Mhz	Schrader	5430W0	90818333	9673860880
672	EU	Peugeot	301	2012/10-2015/12		○	●	4	S	433Mhz	Schrader	9802003680		9802003680
674	EU	Peugeot	307	2007/03-2007/12		●	●	4	O	433Mhz	Schrader	5430W0	90818333	9673860880
673	EU	Peugeot	307	2003/12-2007/02		●	●	4	O	433Mhz	Continental	543093/ 5430T4	S180014805Z	S120120001
676	EU	Peugeot	308	2013/09-2016/01		○	●	4	S	433Mhz	Schrader	9802003680		9802003680
675	EU	Peugeot	308	2007/01-2013/09		●	●	4	O	433Mhz	Schrader	5430W0	90818333	9673860880
689	EU	Peugeot	4008	2014/06-2015/12		○	●	4	S	433Mhz	Continental	1612477080	S180052094Z	S180052094
677	EU	Peugeot	407	2004/01-2011/08		●	●	4	O	433Mhz	Continental	543093/ 5430T4	S180014805Z	S120120001
678	EU	Peugeot	408	2014/06-2015/12		○	●	4	S	433Mhz	Schrader	9802003680		9802003680
691	EU	Peugeot	5008	2013/10-2015/12		○	●	4	O	433Mhz	Schrader	9802003680		9802003680
690	EU	Peugeot	5008	2009/08-2013/09		○	●	4	O	433Mhz	Schrader	5430W0	90818333	9673860880
694	EU	Peugeot	5008 (LCV)	2009/09-2015/12		○	●	4		433Mhz	Schrader	9802003680		9802003680
680	EU	Peugeot	508	2013/10-2015/12		○	●	4	O	433Mhz	Schrader	9811536380/ 9802003680		9811536380
679	EU	Peugeot	508	2011/01-2013/09		○	●	4	O	433Mhz	Continental	5430T4	S180014805Z	S120120001
695	EU	Peugeot	508 (LCV)	2010/09-2015/12		○	●	4		433Mhz	Schrader	9811536380		9811536380
682	EU	Peugeot	607	2004/10-2010/10		●	●	4	O	433Mhz	Continental	543093/ 5430T4	S180014805Z	S120120001
681	EU	Peugeot	607	2000/03-2004/09		●	●	4	O	433Mhz	Schrader	9811536380	9634866180	9634866180
684	EU	Peugeot	807	2005/10-2015/12		●	●	4	O	433Mhz	Continental	5430T4	S180014805Z	S120120001
683	EU	Peugeot	807	2002/07-2005/09		●	●	4	O	433Mhz	Schrader	543002	9634866180	9634866180
696	EU	Peugeot	Boxer Combi	2014/01-2015/12		○	●	4	A	433Mhz	Schrader	9802003680		9802003680
698	EU	Peugeot	Expert	2014/06-2015/12		○	●	4		433Mhz	Schrader	9808859080		9808859080
697	EU	Peugeot	Expert	2011/01-2014/05		○	●	4	O	433Mhz	Schrader		70503487	9677130580
699	EU	Peugeot	iON	2014/01-2016/12		○	●	4	S	433Mhz	Schrader	9802003680/ 9811536380		9802003680/ 9811536380
701	EU	Peugeot	Partner	2014/06-2016/12		○	●	4	O	433Mhz	Schrader	9808859080		9808859080
700	EU	Peugeot	Partner	2008/01-2014/05		●	●	4	O	433Mhz	Schrader	5430W0	90818333	9673860880
703	EU	Peugeot	RCZ	2013/10-2016/12		○	●	4	O	433Mhz	Schrader	9802003680		9802003680
702	EU	Peugeot	RCZ	2010/02-2013/09		○	●	4	O	433Mhz	Schrader	5430W0	90818333	9673860880
706	EU	Porsche	911	2012/02-2015/12		●	●	4	A	433Mhz	Huf/Beru	99760602120	0532207011	RDE011
705	EU	Porsche	911	2008/04-2012/10		●	●	4	A	433Mhz	Huf/Beru	99760602120	0532207011	RDE011
704	EU	Porsche	911	2005/02-2008/05		●	●	4	A	433Mhz	Huf/Beru	99760602101	0532207001	RDE001
711	EU	Porsche	911 Turbo	2010/01-2015/12		●	●	4	A	433Mhz	Huf/Beru	99760602120	0532207011	RDE011
710	EU	Porsche	911 Turbo	2007/01-2009/12		●	●	4	A	433Mhz	Huf/Beru	99760602101	0532207001	RDE001
712	EU	Porsche	918 Spyder	2013/01-2015/12		●	●	4	A	433Mhz	Huf/Beru	7PP907275F	0532207011	RDE011
707	EU	Porsche	991	2012/01-2015/12		●	●	4	A	433Mhz	Huf/Beru	99760602120	0532207011	RDE011

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
709	EU	Porsche	997	2010/01-2015/12		●	●	4	A	433Mhz	Huf/Beru	99760602120	0532207011	RDE011
708	EU	Porsche	997	2007/01-2009/12		●	●	4	A	433Mhz	Huf/Beru	99760602101	0532207001	RDE001
715	EU	Porsche	Boxster	2013/09-2015/12		○	●	4	A	433Mhz	Huf/Beru	7PP907275F	0532207011	RDE011
714	EU	Porsche	Boxster	2008/11-2014/01		●	●	4	A	433Mhz	Huf/Beru	99760602120	0532207011	RDE011
713	EU	Porsche	Boxster	2005/02-2008/10		●	●	4	A	433Mhz	Huf/Beru	99760602101	0532207001	RDE001
716	EU	Porsche	Carrera GT	2003/09-2006/12		●	●	4	A	433Mhz	Huf/Beru	99760602101	0532207001	RDE001
720	EU	Porsche	Cayenne	2014/05-2015/12		●	●	4	A	433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018
719	EU	Porsche	Cayenne	2011/01-2014/04		●	●	4	A	433Mhz	Huf/Beru	95836166100	0532207011	RDE011
718	EU	Porsche	Cayenne	2007/01-2010/12		●	●	4	A	433Mhz	Huf/Beru	95560602100	0532207011	RDE011
717	EU	Porsche	Cayenne	2002/01-2006/12		●	●	4	A	433Mhz	Huf/Beru	95536166100	0532207005	RDE005
721	EU	Porsche	Cayman	2013/04-2015/12	981	●	●	4	A	433Mhz	Huf/Beru	7PP907275F	0532207011	RDE011
723	EU	Porsche	Cayman	2009/01-2014/03	987	●	●	4	A	433Mhz	Huf/Beru	95836166100	0532207011	RDE011
722	EU	Porsche	Cayman	2005/01-2008/12	987	●	●	4	A	433Mhz	Huf/Beru	99760602101	0532207001	RDE001
725	EU	Porsche	GT3	2010/01-2014/12		●	●	4	A	433Mhz	Huf/Beru	7PP907275F	0532207011	RDE011
724	EU	Porsche	GT3	2006/03-2009/12		●	●	4	A	433Mhz	Huf/Beru	99760602100	0532207001	RDE001
726	EU	Porsche	Macan	2014/01-2015/12		○	●	4	A	433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018
728	EU	Porsche	Panamera	2013/07-2015/12		●	●	4	A	433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018
727	EU	Porsche	Panamera	2009/01-2013/06		●	●	4	A	433Mhz	Huf/Beru	99760602120	0532207011	RDE011
729	EU	Renault	Captur	2013/01-2015/12		○	●	4	A	433Mhz	Schrader Huf/Beru	407001628R		407001628R RDE024/RDE026
730	EU	Renault	Clio III	2005/05-2014/05		●	●	4	O	433Mhz	Schrader	8200253215/ 8200924614/ 7701476638/ 7701478868	8200253215	
732	EU	Renault	Clio Van	2012/07-2015/12		○	●	4	A	433Mhz	Schrader Huf/Beru	407001628R		407001628R RDE024/RDE026
733	EU	Renault	Espace IV	2002/07-2014/12		●	●	4	O	433Mhz	Schrader	8200023746	8200023746/ 8200169160	400012631R
734	EU	Renault	Espace V	2015/01-2015/12		○	●	4	A	433Mhz	Continental	407004CB0A	S180150006	S180150006
735	EU	Renault	Fluence	2009/10-2015/12		○	●	4	O	433Mhz	Continental	407000435R	S180084700Z	S180052004
736	EU	Renault	Kangoo	2007/10-2015/12		○	●	4	O	433Mhz	Schrader Huf/Beru	407001628R		407001628R RDE024/RDE026
738	EU	Renault	Koleos	2014/01-2015/12		●	○	4	O	433Mhz	Continental	407003VU0A	S180052048Z	S180052048
737	EU	Renault	Koleos	2008/01-2013/12		●	●	4	O	433Mhz	Schrader	40700JY00C	90518295	40700-JY00C
741	EU	Renault	Laguna II	2005/03-2007/09		●	●	4	A	433Mhz	Schrader	8200023746	8200023746/ 8200169160	400012631R
740	EU	Renault	Laguna II	2001/11-2005/02		●	●	4	A	433Mhz	Schrader	8200023746	8200023746/ 8200169160	400012631R
742	EU	Renault	Laguna III	2007/10-2015/12		●	●	4	O	433Mhz	Continental	407003743R/ 407000435R	S180052064A/ S180084700Z	S180052064/ S180052004
743	EU	Renault	Latitude	2010/09-2015/12		●	●	4	O	433Mhz	Continental	407003743R/ 407000435R	S180052064A/ S180084700Z	S180052064/ S180052004
744	EU	Renault	Master	2009/11-2015/12		○	●	4	O	433Mhz	Schrader Huf/Beru	407001628R		407001628R-B RDE024/RDE026
745	EU	Renault	Megane I	2001/01-2002/08		●	●	4	A	433Mhz	Schrader	8200023746	8200023746/ 8200169160	400012631R
746	EU	Renault	Megane II	2002/09-2007/12		●	●	4	A	433Mhz	Continental	407005578R	S180014810Z	S120123006

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
747	EU	Renault	Megane III	2008/09-2015/12		●	●	4	0	433Mhz	Continental	407003743R/ 407000435R	S180052064A/ S180084700Z	S180052064/ S180052004
748	EU	Renault	Modus	2004/04-2012/12		●	●	4	0	433Mhz	Schrader	7701478868/ 8200924614	8200253215	
749	EU	Renault	Scenic I	2001/01-2003/04		●	●	4	A	433Mhz	Schrader	407002425R	8200023746/ 8200169160	400012631R
750	EU	Renault	Scenic II	2003/05-2008/12		●	●	4	A	433Mhz	Continental	407005578R	S180014810Z	S120123006
751	EU	Renault	Scenic II restyle	2006/01-2008/12		●	●	4	A	433Mhz	Continental	407005578R	S180014810Z	S120123006
752	EU	Renault	Scenic III	2009/01-2015/12		●	●	4	0	433Mhz	Continental	407003743R/ 407000435R	S180052064A/ S180084700Z	S180052064/ S180052004
753	EU	Renault	Scenic RX4	2001/01-2003/06		○	●	4	A	433Mhz	Schrader	407002138R	8200023746/ 8200169160	400012631R
754	EU	Renault	Symbol/Thalia	2013/04-2015/12		○	●	4	0	433Mhz	Schrader Huf/Beru	407001628R		407001628R-B RDE024/RDE026
755	EU	Renault	Trafic	2014/01-2015/12		○	●	4	A	433Mhz	Schrader Huf/Beru	407001628R		407001628R-B RDE024/RDE026
756	EU	Renault	Twingo	2007/01-2015/12		○	●	4	A	433Mhz	Schrader Huf/Beru	407001628R		407001628R-B RDE024/RDE026
757	EU	Renault	Vel Satis	2001/09-2009/12		●	●	4	A	433Mhz	Schrader	8200023746	8200023746/ 8200169160	400012631R
758	EU	Renault	Wind	2010/06-2015/12		○	●	4	0	433Mhz	Schrader Huf/Beru	407001628R		407001628R-B RDE024/RDE026
759	EU	Renault	Zoe	2012/09-2016/03		○	●	4	0	433Mhz	Continental	407003743R/ 407000435R	S180052064A/ S180084700Z	S180052064/ S180052004
760	EU	Rolls-Royce	Cabrio	2009/06-2011/12		○	●	4	A	433Mhz	Huf/Beru	36236798726	0532207008	RDE008
763	EU	Rolls-Royce	Ghost	2010/01-2015/12		○	●	4		433Mhz	Huf/Beru	36106790054/ 36106856227	0532207012	RDE012
765	EU	Rolls-Royce	Phantom	2012/01-2015/12		○	●	4	A	433Mhz	Huf/Beru	36106790054/ 36106856227	0532207012	RDE012
764	EU	Rolls-Royce	Phantom	2007/08-2011/12		○	●	4	A	433Mhz	Huf/Beru	36236781847	0532207008	RDE008
766	EU	Rolls-Royce	Wraith	2013/08-2015/12		○	●	4		433Mhz	Huf/Beru	36106790054/ 36106856227	0532207012	RDE012
769	EU	Saab	9-3	2009/06-2012/12		○	●	4	A	433Mhz	Schrader	13327259	90518407/ 90515382	13348393/ 13327259
768	EU	Saab	9-3	2006/10-2009/05		○	●	4	A	433Mhz	Schrader	13227143	90518150/ 90518408	13227143/ 12825085
767	EU	Saab	9-3	2003/01-2006/09		○	●	4	A	433Mhz	Schrader	13172567	24437708/ 13172567	13172567
773	EU	Saab	9-4X	2011/03-2014/01		○	●	4	S	433Mhz	Schrader	20922901	90518390	20922901
772	EU	Saab	9-5	2009/10-2012/12		○	●	4	A	433Mhz	Schrader	13327259	90518407/ 90515382	13348393/ 13327259
771	EU	Saab	9-5	2006/11-2009/09		○	●	4	A	433Mhz	Schrader	13227143	90518150/ 90518408	13227143/ 12825085
770	EU	Saab	9-5	2003/01-2006/10		○	●	4	A	433Mhz	Schrader	13172567	24437708/ 13172567	13172567
774	EU	Saab	9-7X	2007/01-2008/12		○	●	4	S	433Mhz	Schrader	25774007	90518110	25774007
2773	EU	Skoda	Citigo	2014/05-2015/12		○	●	4	A	433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018
775	EU	Skoda	Citigo	2011/01-2014/04		○	●	4		433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018
2774	EU	Skoda	Fabia	2015/01-2015/12		○	●	4	A	433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
776	EU	Skoda	Fabia	2013/10-2014/12		○	●	4	A	433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018
2766	EU	Skoda	Octavia	2015/01-2015/12		○	●	4	S	433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018
777	EU	Skoda	Octavia	2012/10-2014/12		○	●	4	S	433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018
2775	EU	Skoda	Rapid	2015/05-2015/12		○	●	4	A	433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018
778	EU	Skoda	Rapid	2012/05-2015/04		○	●	4	A	433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018
779	EU	Skoda	Roomster	2006/01-2015/12		○	●	4	A	433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018
2776	EU	Skoda	Superb	2015/05-2015/12		○	●	4	A	433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018
780	EU	Skoda	Superb	2008/03-2015/04		○	●	4	A	433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018
781	EU	Skoda	Yeti	2009/06-2015/12		○	●	4	A	433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018
782	EU	Smart	Forfour	2014/07-2015/12		○	●	4		433Mhz	Schrader Huf/Beru	407001628R		407001628R RDE024/RDE026
784	EU	Smart	Fortwo	2014/03-2015/12		○	●	4		433Mhz	Schrader Huf/Beru	407001628R		407001628R RDE024/RDE026
783	EU	Smart	Fortwo	2007/01-2014/02		○	●	4	A	433Mhz	Schrader	A0009054100	90518384	
794	EU	Subaru	BRZ	2014/01-2015/12		●	●	4	O	433Mhz	Pacific	28103CA101/ 28103CA010		
795	EU	Subaru	C-Concept	2014/06-2015/12		●	●	4	O	433Mhz	Schrader	28103FJ000		
796	EU	Subaru	Forester	2014/01-2015/12		●	●	4	O	433Mhz	Schrader	28103FJ000		
797	EU	Subaru	Impreza	2014/01-2015/12		●	●	4	O	433Mhz	Schrader	28103FJ000		
798	EU	Subaru	Justy	2014/01-2015/12		●	●	4	O	433Mhz	Schrader	28103FJ000		
799	EU	Subaru	Legacy	2014/10-2015/12		●	●	4	O	433Mhz	Schrader	28103FJ000		
800	EU	Subaru	Outback	2014/01-2015/12		●	●	4	O	433Mhz	Schrader	28103FJ001/ 28103FJ000		
801	EU	Subaru	Trezia	2014/01-2015/12		●	●	4	O	433Mhz	Schrader	28103FJ000		
802	EU	Subaru	Tribeca	2014/01-2015/12		●	●	4	O	433Mhz	Schrader	28103FJ000		
803	EU	Subaru	WRX	2014/01-2014/12		○	●	4	O	433Mhz	Schrader	28103FJ000		
804	EU	Subaru	XV	2014/01-2015/12		●	●	4	O	433Mhz	Schrader	28103FJ000		
805	EU	Suzuki	Alto	2014/06-2015/12		○	○	4	O	433Mhz	Continental	4313961M00/ 4313061M00	S180052024Z	S180052024
806	EU	Suzuki	Alto succ.	2015/01-2015/12		○	○	4		433Mhz	Continental	4313961M00/ 4313061M00	S180052024Z	S180052024
2778	EU	Suzuki	Grand Vitara	2014/06-2015/12		○	○	4	A	433Mhz	Continental	4313961M00/ 4313061M00	S180052024Z	S180052024
807	EU	Suzuki	Jimny	2014/06-2015/12		○	○	4		433Mhz	Continental	4313961M00	S180052024Z	S180052024
808	EU	Suzuki	Swift	2013/08-2015/12		○	○	4	O	433Mhz	Continental	4313961M00	S180052024Z	S180052024
809	EU	Suzuki	SX4	2014/08-2015/12		○	○	4	S	433Mhz	Continental	4313961M00	S180052024Z	S180052024
810	EU	Suzuki	SX4 S-Cross	2013/08-2015/12		○	○	4	O	433Mhz	Continental	4313961M00	S180052024Z	S180052024
2779	EU	Suzuki	Vitara	2015/01-2015/12		○	○	4	A	433Mhz	Continental	4313961M00/ 4313061M00	S180052024Z	S180052024
812	EU	Tesla	Model S	2014/10-2015/12		○	●	4	A	433Mhz	Continental	103460200A	S180052068Z	S180052068
811	EU	Tesla	Model S	2013/01-2014/09		○	●	4	A	433Mhz	Baolong	FS1511130317		FS1511-130317
814	EU	Toyota	Alphard	2014/10-2015/12		●	●	4	O	433Mhz	Pacific	4260742020	PMV-C210	42607-42020
815	EU	Toyota	Auris	2014/08-2015/12		●	●	4	O	433Mhz	Pacific	4260702030/ 4260702031	PMV-C210	42607-02030/ 42607-02031
816	EU	Toyota	Avensis	2014/08-2015/12		●	●	4	S	433Mhz	Pacific	4260702030/ 4260702031	PMV-C210	42607-02030/ 42607-02031
817	EU	Toyota	Aygo	2014/01-2015/12		●	●	4	O	433Mhz	Pacific	4260742020	PMV-C210	42607-42020
818	EU	Toyota	Camry	2014/06-2015/12		●	●	4	O	433Mhz	Pacific	4260742020	PMV-C210	42607-42020
820	EU	Toyota	Corolla	2014/08-2015/12		●	●	4	O	433Mhz	Pacific	4260702031	PMV-C210	42607-02031

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
819	EU	Toyota	Corolla	2013/09-2014/07		●	●	4	0	433Mhz	Pacific	4260742020	PMV-C210	42607-42020
822	EU	Toyota	Land Cruiser	2014/08-2015/12		●	●	4	S	433Mhz	Pacific	4260730070/ 4260702031	PMV-107J/ PMV-C210	42607-30070/ 42607-02031
821	EU	Toyota	Land Cruiser	2005/01-2014/07		●	●	4	0	433Mhz	Pacific	4260750011	PMV-107K	
823	EU	Toyota	Prius	2014/05-2015/12		●	●	4	0	433Mhz	Pacific	4260742020/ 4260742021	PMV-C210	
825	EU	Toyota	Proace	2014/06-2015/12		●	●	4		433Mhz	Schrader	9808859080		9808859080
824	EU	Toyota	Proace	2013/01-2014/05		●	●	4	0	433Mhz	Schrader	9677130580		9677130580
827	EU	Toyota	RAV4	2012/12-2015/12		●	●	4	0	433Mhz	Pacific	4260742020/ 4260742021	PMV-C210	
826	EU	Toyota	RAV4	2006/01-2012/12		●	●	4	0	433Mhz	Pacific	4260750011	PMV-107K	
829	EU	Toyota	Verso	2014/08-2015/12		●	●	4	S	433Mhz	PACIFIC	4260702031	PMV-C210	42607-02031
828	EU	Toyota	Verso	2013/01-2014/07		●	●	4	S	433Mhz	Pacific	4260702030	PMV-C210	42607-02030
831	EU	Toyota	Yaris	2014/05-2015/12		●	●	4	0	433Mhz	Pacific	4260742020/ 4260702031	PMV-C210	
832	EU	Volkswagen	Caravelle	2012/01-2015/12		●	●	4		433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018
833	EU	Volkswagen	CC	2012/01-2014/08		●	●	4	S	433Mhz	Huf/Beru	3AA907275	0532207013	RDE013
834	EU	Volkswagen	Crafter	2006/04-2015/12		●	●	4		433Mhz	Schrader	A0025409017		
835	EU	Volkswagen	EOS	2006/02-2015/12		●	●	4	A	433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018
836	EU	Volkswagen	Golf	2009/01-2015/12		●	●	4	S	433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018
837	EU	Volkswagen	Jetta	2010/07-2015/12		●	●	4	A	433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018
839	EU	Volkswagen	New Beetle	2011/08-2015/12		●	●	4	S	433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018
838	EU	Volkswagen	New Beetle	2006/01-2011/07		●	●	4	A	433Mhz	Continental	1K0907253C	S180014701Z	C122215002
842	EU	Volkswagen	Passat	2014/09-2015/12		●	●	4		433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018
841	EU	Volkswagen	Passat	2010/09-2014/08		●	●	4	A	433Mhz	Huf/Beru	3AA907275D	0532207013	RDE013
840	EU	Volkswagen	Passat	2006/01-2010/08		●	●	4	A	433Mhz	Continental	1K0907253C	S180014701Z	C122215002
844	EU	Volkswagen	Passat CC	2014/09-2015/12		●	●	4		433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018
843	EU	Volkswagen	Passat CC	2008/03-2014/08		●	●	4	A	433Mhz	Huf/Beru	3AA907275D	0532207013	RDE013
847	EU	Volkswagen	Phaeton	2010/06-2015/12		●	●	4	A	433Mhz	Huf/Beru	4F0907275E	0532207011	RDE011
846	EU	Volkswagen	Phaeton	2007/06-2010/05		●	●	4	A	433Mhz	Huf/Beru	4F0907275D	0532207011	RDE011
845	EU	Volkswagen	Phaeton	2002/01-2007/05		●	●	4	A	433Mhz	Huf/Beru	4D0907275	0532207001	RDE001
848	EU	Volkswagen	Scirocco	2008/01-2015/12		●	●	4		433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018
849	EU	Volkswagen	Sharan	2008/01-2015/12		●	●	4		433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018
850	EU	Volkswagen	Tiguan	2011/05-2015/12		●	●	4	A	433Mhz	Huf/Beru	3AA907275	0532207013	RDE013
855	EU	Volkswagen	Touareg	2014/08-2015/12		●	●	4		433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018
854	EU	Volkswagen	Touareg	2010/01-2014/07		●	●	4	A	433Mhz	Huf/Beru	4F0907275E	0532207011	RDE011
853	EU	Volkswagen	Touareg	2007/01-2010/12		●	●	4	A	433Mhz	Huf/Beru	4F0907275D	0532207011	RDE011
852	EU	Volkswagen	Touareg	2002/02-2006/12		●	●	4	A	433Mhz	Huf/Beru	7L0907275B	0532207005	RDE005
856	EU	Volkswagen	Touran	2010/07-2015/12		●	●	4		433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018
857	EU	Volkswagen	Touran (LCV)	2010/07-2015/12		●	●	4	A	433Mhz	Huf/Beru	3AA907275D	0532207013	RDE013
858	EU	Volkswagen	Transporter	2012/01-2015/12		●	●	4		433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018
864	EU	Volvo	C30	2012/01-2013/12		●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
863	EU	Volvo	C30	2011/01-2011/12		●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
862	EU	Volvo	C30	2010/01-2010/12		●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
861	EU	Volvo	C30	2009/01-2009/12		●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
860	EU	Volvo	C30	2008/01-2008/12		●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
859	EU	Volvo	C30	2007/01-2007/12		○	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
2793	EU	Volvo	C30 Electric	2010/12-2015/12		○	●	4	A	433Mhz	Continental	31341893/ 31341171	S180052050Z	S180052050
870	EU	Volvo	C70	2012/01-2014/06		●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
869	EU	Volvo	C70	2011/01-2011/12		●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
868	EU	Volvo	C70	2010/01-2010/12		●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
867	EU	Volvo	C70	2009/01-2009/12		●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
866	EU	Volvo	C70	2008/01-2008/12		●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
865	EU	Volvo	C70	2006/01-2007/12		○	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
876	EU	Volvo	S40	2012/01-2014/06		●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
875	EU	Volvo	S40	2011/01-2011/12		●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
874	EU	Volvo	S40	2010/01-2010/12		●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
873	EU	Volvo	S40	2009/01-2009/12		●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
872	EU	Volvo	S40	2008/01-2008/12		●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
871	EU	Volvo	S40	2004/01-2007/12		○	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
880	EU	Volvo	S60	2014/07-2015/12		○	●	4	S	433Mhz	Continental	31341893/ 31341171/ 31414189	S180052050Z	S180052050
879	EU	Volvo	S60	2010/03-2014/06		●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
878	EU	Volvo	S60	2007/01-2010/02		●	●	4	A	433Mhz	Schrader	31329981/ 30748354	90518149	30748354
877	EU	Volvo	S60	2000/07-2006/12		●	●	4	A	433Mhz	Schrader	31329981/ 30748354	90518149	30748354
888	EU	Volvo	S80	2014/07-2015/12		○	●	4	S	433Mhz	Continental	31341893/ 31341171/ 31414189	S180052050Z	S180052050
887	EU	Volvo	S80	2012/01-2014/06		●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
886	EU	Volvo	S80	2011/01-2011/12		●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
885	EU	Volvo	S80	2010/01-2010/12		●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
884	EU	Volvo	S80	2009/01-2009/12		●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
883	EU	Volvo	S80	2008/01-2008/12		●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
882	EU	Volvo	S80	2007/01-2007/12		●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
881	EU	Volvo	S80	2006/01-2006/12		●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
889	EU	Volvo	V40	2014/01-2015/12		○	●	4	A	433Mhz	Continental	31341893/ 31341171	S180052050Z	S180052050
895	EU	Volvo	V50	2012/01-2013/12		●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
894	EU	Volvo	V50	2011/01-2011/12		●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
893	EU	Volvo	V50	2010/01-2010/12		●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
892	EU	Volvo	V50	2009/01-2009/12		●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
891	EU	Volvo	V50	2008/01-2008/12		●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
890	EU	Volvo	V50	2004/01-2007/12		○	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
899	EU	Volvo	V60	2014/07-2015/12		○	●	4	S	433Mhz	Continental	31341893/ 31341171/ 31414189	S180052050Z	S180052050
898	EU	Volvo	V60	2012/01-2014/06		●	●	4	A	433Mhz	Continental	31302096/ 31341893	S180052020	S180052020
897	EU	Volvo	V60	2011/01-2011/12		●	●	4	A	433Mhz	Continental	31302096/ 31341893	S180052020	S180052020
896	EU	Volvo	V60	2010/09-2010/12		○	●	4	A	433Mhz	Continental	31302096/ 31341893	S180052020	S180052020

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
907	EU	Volvo	V70	2014/07-2015/12		○	●	4	S	433Mhz	Continental	31341893/ 31341171/ 31414189	S180052050Z	S180052050
906	EU	Volvo	V70	2012/01-2014/06		●	●	4	A	433Mhz	Continental	31302096/ 31341893	S180052020	S180052020
905	EU	Volvo	V70	2011/01-2011/12		●	●	4	A	433Mhz	Continental	31302096/ 31341893	S180052020	S180052020
904	EU	Volvo	V70	2010/01-2010/12		●	●	4	A	433Mhz	Continental	31302096/ 31341893	S180052020	S180052020
903	EU	Volvo	V70	2009/01-2009/12		●	●	4	A	433Mhz	Continental	31302096/ 31341893	S180052020	S180052020
902	EU	Volvo	V70	2008/01-2008/12		●	●	4	A	433Mhz	Continental	31302096/ 31341893	S180052020	S180052020
901	EU	Volvo	V70	2007/01-2007/12		●	●	4	A	433Mhz	Schrader	31329981/ 30748354	90518149	30748354
900	EU	Volvo	V70	2006/03-2006/12		●	●	4	A	433Mhz	Schrader	31329981/ 30748354	90518149	30748354
913	EU	Volvo	XC60	2014/07-2015/12		○	●	4	S	433Mhz	Continental	31341893/ 31341171/ 31414189	S180052050Z	S180052050
912	EU	Volvo	XC60	2012/01-2014/06		●	●	4	A	433Mhz	Continental	31302096/ 31341893	S180052020	S180052020
911	EU	Volvo	XC60	2011/01-2011/12		●	●	4	A	433Mhz	Continental	31302096/ 31341893	S180052020	S180052020
910	EU	Volvo	XC60	2010/01-2010/12		●	●	4	A	433Mhz	Continental	31302096/ 31341893	S180052020	S180052020
909	EU	Volvo	XC60	2009/01-2009/12		●	●	4	A	433Mhz	Continental	31302096/ 31341893	S180052020	S180052020
908	EU	Volvo	XC60	2008/05-2008/12		○	●	4	A	433Mhz	Continental	31302096/ 31341893	S180052020	S180052020
920	EU	Volvo	XC70	2014/07-2015/12		○	●	4	S	433Mhz	Continental	31341893/ 31341171/ 31414189	S180052050Z	S180052050
919	EU	Volvo	XC70	2012/01-2014/06		●	●	4	A	433Mhz	Continental	31302096/ 31341893	S180052020	S180052020
918	EU	Volvo	XC70	2011/01-2011/12		●	●	4	A	433Mhz	Continental	31302096/ 31341893	S180052020	S180052020
917	EU	Volvo	XC70	2010/01-2010/12		●	●	4	A	433Mhz	Continental	31302096/ 31341893	S180052020	S180052020
916	EU	Volvo	XC70	2009/01-2009/12		●	●	4	A	433Mhz	Continental	31302096/ 31341893	S180052020	S180052020
915	EU	Volvo	XC70	2008/01-2008/12		●	●	4	A	433Mhz	Continental	31302096/ 31341893	S180052020	S180052020
914	EU	Volvo	XC70	2007/02-2007/12		●	●	4	A	433Mhz	Schrader	31329981/ 30748354	90518149	30748354
922	EU	Volvo	XC90	2007/01-2010/12		●	●	4	A	433Mhz	Schrader	31329981/ 30748354	90518149	30748354
921	EU	Volvo	XC90	2006/01-2006/12		●	●	4	A	433Mhz	Schrader	31329981/ 30748354	90518149	30748354
925	US	Acura	CSX	2012/01-2012/12	315MHz	●	●	4	O	315Mhz	TRW	42753TROA81	217652-114	217652-114
924	US	Acura	CSX	2008/01-2011/12	315MHz	●	●	4	O	315Mhz	TRW	42753SNAA83	217652-114	217652-114
926	US	Acura	ILX	2013/01-2015/12	315MHz	●	●	4	O	315Mhz	Continental	42573TX6A81	S180052044G	S180052044
928	US	Acura	MDX	2007/01-2013/12	315MHz	●	●	4	A	315Mhz	Pacific	42753STKA04	PMV-107G	42753-STK-A04

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
927	US	Acura	MDX	2004/01-2006/12	315MHz	●	●	4	A	315Mhz	TRW	06421S3VA04	218898-101	218898-101
930	US	Acura	RDX	2007/01-2012/12	315MHz	●	●	4	A	315Mhz	Pacific	42753STKA04	PMV-107G	42753-STK-A04
933	US	Acura	RL	2009/01-2013/12	315MHz	●	●	4	A	315Mhz	TRW	42753SHJA53	217652-116	217652-116
932	US	Acura	RL	2005/01-2008/12	315MHz	●	●	4	A	315Mhz	TRW	06421S3VA04	218898-101	218898-101
936	US	Acura	TL	2009/01-2013/12	315MHz	●	●	4	A	315Mhz	TRW	42753TK4A01	217652-112	217652-112
935	US	Acura	TL	2005/01-2008/12	315MHz	●	●	4	A	315Mhz	TRW	06421S3VA04	218898-101	218898-101
940	US	Acura	TSX	2009/01-2014/12	315MHz	●	●	4	A	315Mhz	Pacific	42753TL2A52	PMV-107G	42753-TL2-A52
939	US	Acura	TSX	2007/01-2008/12	315MHz	●	●	4	A	315Mhz	Pacific	42753STKA04	PMV-107G	42753-STK-A04
941	US	Acura	ZDX	2010/01-2015/12	315MHz	●	●	4	A	315Mhz	TRW	42753TK4A01	217652-112	217652-112
943	US	Audi	A3	2012/10-2014/12	315MHz	●	●	4	S	315Mhz	Continental	1K0907253D	S122215001C	
942	US	Audi	A3	2006/01-2012/10	315MHz	●	●	4	S	315Mhz	Continental	1K0907253D	S122215001C	
945	US	Audi	A4	2009/01-2012/12	315MHz	●	●	4	S	315Mhz	Continental	1K0907253D	S122215001C	
944	US	Audi	A4	2002/01-2008/12	433MHz	●	●	4	S	433Mhz	Huf/Beru	4F0907275B	0532207011	RDE011
946	US	Audi	A4 Cabriolet	2003/01-2012/12	433MHz	●	●	4	S	433Mhz	Huf/Beru	4F0907275D	0532207011	RDE011
947	US	Audi	A5	2008/01-2012/12	315MHz	●	●	4	A	315Mhz	Continental	1K0907253D	S122215001C	
950	US	Audi	A6	2010/01-2015/12	433MHz	●	●	4	S	433Mhz	Huf/Beru	4F0907275D	0532207011	RDE011
949	US	Audi	A6	2005/01-2009/12	433MHz	●	●	4	S	433Mhz	Huf/Beru	4F0907275B	0532207011	RDE011
948	US	Audi	A6	2002/01-2004/12	315MHz	●	●	4	S	315Mhz	Huf/Beru	4D0907275A	0532107001	RDE004
953	US	Audi	A6 Allroad	2010/01-2011/12	433MHz	●	●	4	S	433Mhz	Huf/Beru	4F0907275D	0532207011	RDE011
952	US	Audi	A6 Allroad	2007/01-2009/12	433MHz	●	●	4	S	433Mhz	Huf/Beru	4F0907275B	0532207011	RDE011
951	US	Audi	A6 Allroad	2001/01-2005/12	315MHz	●	●	4	S	315Mhz	Huf/Beru	4D0907275A	0532107001	RDE004
958	US	Audi	A8	2004/01-2015/12	433MHz	●	●	4	S	433Mhz	Huf/Beru	4D0907275C	0532107001	RDE001
956	US	Audi	A8	2003/01-2012/12	315MHz	●	●	4	S	315Mhz	Huf/Beru	4D0907275A	0532107001	RDE004
957	US	Audi	A8	2003/01-2003/12	433MHz	●	●	4	S	433Mhz	Huf/Beru	4D0907275C	0532107001	RDE001
955	US	Audi	A8	2000/01-2002/12	315MHz	●	●	4	S	315Mhz	Huf/Beru	4D0907275A	0532107001	RDE004
959	US	Audi	Q5	2009/01-2015/12	315MHz	●	●	4	S	315Mhz	Continental	1K0907253D	S122215001C	
961	US	Audi	Q7	2010/01-2015/12	433MHz	●	●	4	S	433Mhz	Huf/Beru	4F0907275D	0532207011	RDE011
960	US	Audi	Q7	2005/01-2009/12	433MHz	●	●	4	S	433Mhz	Huf/Beru	4F0907275B	0532207011	RDE011
963	US	Audi	R8	2010/01-2015/12	433MHz	●	●	4	S	433Mhz	Huf/Beru	4F0907275D	0532207011	RDE011
962	US	Audi	R8	2008/01-2009/12	433MHz	●	●	4	S	433Mhz	Huf/Beru	4F0907275B	0532207011	RDE011
964	US	Audi	RS4	2007/01-2008/12	433MHz	●	●	4	S	433Mhz	Huf/Beru	4F0907275B	0532207011	RDE011
965	US	Audi	RS4 Cabriolet	2008/01-2009/12	433MHz	●	●	4	S	433Mhz	Huf/Beru	4F0907275B	0532207011	RDE011
966	US	Audi	RS6	2000/01-2005/12	315MHz	●	●	4	S	315Mhz	Huf/Beru	4D0907275A	0532107001	RDE004
967	US	Audi	RS6	2000/01-2005/12	433MHz	●	●	4	S	433Mhz	Huf/Beru	4D0907275C	0532207001	RDE001
969	US	Audi	S4	2010/01-2014/12	315MHz	●	●	4	A	315Mhz	Continental	1K0907253D	S122215001C	
970	US	Audi	S5	2008/01-2014/12	315MHz	●	●	4	A	315Mhz	Continental	1K0907253D	S122215001C	
972	US	Audi	S6	2010/01-2011/12	433MHz	●	●	4	S	433Mhz	Huf/Beru	4F0907275D	0532207011	RDE011
971	US	Audi	S6	2004/01-2009/12	433MHz	●	●	4	S	433Mhz	Huf/Beru	4F0907275B	0532207011	RDE011
977	US	Audi	S8	2008/01-2009/12	433MHz	●	●	4	S	433Mhz	Huf/Beru	4D0907275C	0532207001	RDE001
976	US	Audi	S8	2004/01-2007/12	433MHz	●	●	4	S	433Mhz	Huf/Beru	4D0907275C	0532207001	RDE001
974	US	Audi	S8	2003/01-2003/12	315MHz	●	●	4	S	315Mhz	Huf/Beru	4D0907275A	0532107001	RDE004
975	US	Audi	S8	2003/01-2003/12	433MHz	●	●	4	S	433Mhz	Huf/Beru	4D0907275C	0532207001	RDE001
973	US	Audi	S8	2000/01-2002/12	315MHz	●	●	4	S	315Mhz	Huf/Beru	4D0907275A	0532107001	RDE004
978	US	Audi	TT	2007/01-2014/12	315MHz	●	●	4	S	315Mhz	Continental	1K0907253D	S122215001C	
979	US	Bentley	Arnage	2008/01-2008/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	4F0907275B	0532207011	RDE011

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow: Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufactuer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
981	US	Bentley	Azure	2010/01-2015/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	4F0907275B	0532207011	RDE011
980	US	Bentley	Azure	2007/01-2009/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	4F0907275B	0532207011	RDE011
986	US	Bentley	Continental	2012/01-2015/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	4F0907275D	0532207011	RDE011
985	US	Bentley	Continental	2006/01-2011/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	4F0907275B	0532207011	RDE011
984	US	Bentley	Continental	2005/06-2005/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	4F0907275B	0532207011	RDE011
983	US	Bentley	Continental	2005/01-2005/05	433MHz	●	●	4	A	433Mhz	Huf/Beru	4D0907275C	0532207001	RDE001
982	US	Bentley	Continental	2003/01-2004/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	4D0907275C	0532207001	RDE001
988	US	Bentley	Flying Spur	2011/01-2015/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	4F0907275D	0532207011	RDE011
987	US	Bentley	Flying Spur	2005/01-2010/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	4F0907275B	0532207011	RDE011
990	US	Bentley	Mulsanne	2013/01-2015/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	4F0907275D	0532207011	RDE011
989	US	Bentley	Mulsanne	2011/01-2012/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	4F0907275B	0532207011	RDE011
992	US	BMW	1 Series	2010/10-2015/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	36106790054	0532207012	RDE012
991	US	BMW	1 Series	2007/01-2010/09	433MHz	●	●	4	A	433Mhz	Huf/Beru	36236781847	0532207008	RDE008
994	US	BMW	2 SERIES	2014/03-2015/12	433MHz	●	●	4	A	433Mhz	Continental	36106856209	S180052056Z	S180052056
993	US	BMW	2 SERIES	2014/01-2014/12	433MHz	○	●	4	A	433Mhz	Huf/Beru	36106798872	0532207017	RDE017
1000	US	BMW	3 Series	2010/01-2013/06	433MHz	●	●	4	A	433Mhz	Huf/Beru	36106790054	0532207012	RDE012
999	US	BMW	3 Series	2007/01-2009/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	36236781847	0532207008	RDE008
996	US	BMW	3 Series	2000/01-2002/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	36118378681	0532107001	RDE004
995	US	BMW	3 Series	1999/01-1999/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	36118378681	0532107001	RDE004
1001	US	BMW	3 Series GT	2014/01-2015/12	433MHz	○	●	4	A	433Mhz	Huf/Beru	36106798872	0532207017	RDE017
1003	US	BMW	3 Series Sedan	2014/03-2015/12	433MHz	●	●	4	A	433Mhz	Continental	36106856209	S180052056Z	S180052056
1004	US	BMW	3 Series Wagon	2013/01-2015/12	433MHz	○	●	4	A	433Mhz	Huf/Beru	36106798872	0532207017	RDE017
1006	US	BMW	4 Series	2014/01-2015/12	433MHz	●	●	4	A	433Mhz	Continental	36106856209	S180052056Z	S180052056
1005	US	BMW	4 Series	2005/01-2013/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	36106798872	0532207017	RDE017
1012	US	BMW	5 Series	2010/10-2015/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	36106790054	0532207012	RDE012
1011	US	BMW	5 Series	2006/01-2010/09	433MHz	●	●	4	A	433Mhz	Huf/Beru	36236781847	0532207008	RDE008
1010	US	BMW	5 Series	2003/01-2005/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	36118378682	0532207002	RDE002
1008	US	BMW	5 Series	2002/01-2002/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	36118378681	0532107001	RDE004
1009	US	BMW	5 Series	2002/01-2002/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	36118378682	0532207002	RDE002
1007	US	BMW	5 Series	2000/01-2001/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	36118378681	0532107001	RDE004
1016	US	BMW	6 Series	2015/01-2015/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	36106798872	0532207017	RDE017
1015	US	BMW	6 Series	2011/01-2014/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	36106790054	0532207012	RDE012
1014	US	BMW	6 Series	2006/01-2010/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	36236781847	0532207008	RDE008
1021	US	BMW	7 Series	2010/10-2015/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	36106790054	0532207012	RDE012
1020	US	BMW	7 Series	2006/01-2010/09	433MHz	●	●	4	A	433Mhz	Huf/Beru	36236781847	0532207008	RDE008
1017	US	BMW	7 Series	2000/01-2001/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	36118378681	0532107001	RDE004
1018	US	BMW	7 Series	2000/01-2001/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	36118378682	0532207002	RDE002
1022	US	BMW	I3	2015/01-2015/12	433MHz	●	●	4	A	433Mhz	Continental	36106856209	S180052056Z	S180052056
1023	US	BMW	I8	2015/01-2015/12	433MHz	●	●	4	A	433Mhz	Continental	36106856209	S180052056Z	S180052056
1024	US	BMW	M1	2011/01-2012/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	36106790054	0532207012	RDE012
1026	US	BMW	M3	2010/01-2014/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	36106790054	0532207012	RDE012
1025	US	BMW	M3	2008/01-2009/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	36236781847	0532207008	RDE008
1028	US	BMW	M5	2011/06-2015/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	36106790054	0532207012	RDE012
1027	US	BMW	M5	2006/01-2011/05	433MHz	●	●	4	A	433Mhz	Huf/Beru	36236781847	0532207008	RDE008
1030	US	BMW	M6	2011/06-2015/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	36106790054	0532207012	RDE012

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, 0=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
1029	US	BMW	M6	2006/01-2011/05	433MHz	●	●	4	A	433Mhz	Huf/Beru	36236781847	0532207008	RDE008
1031	US	BMW	X1	2012/01-2015/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	36106790054	0532207012	RDE012
1033	US	BMW	X3	2011/05-2015/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	36106790054	0532207012	RDE012
1032	US	BMW	X3	2006/01-2011/04	433MHz	●	●	4	A	433Mhz	Huf/Beru	36236781847	0532207008	RDE008
1037	US	BMW	X5	2014/01-2015/12	433MHz	●	●	4	A	433Mhz	Continental	36106856209	S180052056Z	S180052056
1036	US	BMW	X5	2011/05-2013/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	36106790054	0532207012	RDE012
1035	US	BMW	X5	2006/01-2011/04	433MHz	●	●	4	A	433Mhz	Huf/Beru	36236781847	0532207008	RDE008
1034	US	BMW	X5	2000/01-2005/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	36146752128	0532207003	RDE003
1039	US	BMW	X6	2011/05-2015/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	36106790054	0532207012	RDE012
1038	US	BMW	X6	2008/01-2011/04	433MHz	●	●	4	A	433Mhz	Huf/Beru	36236781847	0532207008	RDE008
1040	US	BMW	X6 HYBRID	2009/01-2011/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	36236781847	0532207008	RDE008
1043	US	BMW	Z Series	2015/01-2015/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	36106798872	0532207017	RDE017
1042	US	BMW	Z Series	2011/05-2014/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	36106790054	0532207012	RDE012
1041	US	BMW	Z Series	2006/01-2011/04	433MHz	●	●	4	A	433Mhz	Huf/Beru	36236781847	0532207008	RDE008
1048	US	Buick	Allure	2011/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	12768826/ 20922900/ 22854866		12768826/ 20922900/ 22854866
1047	US	Buick	Allure	2010/01-2010/12	315MHz	●	●	4	S	315Mhz	Schrader	12768826/ 20922900/ 22854866		12768826/ 20922900/ 22854866
1046	US	Buick	Allure	2009/01-2009/12	315MHz	●	●	4	S	315Mhz	Schrader	12768826/ 20922900/ 22854866		12768826/ 20922900/ 22854866
1045	US	Buick	Allure	2008/01-2008/12	315MHz	●	●	4	S	315Mhz	Continental	15921013	S120123009A	
1044	US	Buick	Allure	2007/01-2007/12	315MHz	●	●	4	S	315Mhz	Continental	15921013	S120123009A	
1050	US	Buick	Enclave	2009/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615		25920615
1049	US	Buick	Enclave	2008/01-2008/12	315MHz	●	●	4	S	315Mhz	Continental	15921013	S120123009A	
1051	US	Buick	Encore	2013/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	22854866		22854866
1058	US	Buick	LaCrosse	2014/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	12768826/ 20922900/ 22854866		12768826/ 20922900/ 22854866
1057	US	Buick	LaCrosse	2013/01-2013/12	315MHz	●	●	4	S	315Mhz	Schrader	12768826/ 20922900/ 22854866		12768826/ 20922900/ 22854866
1056	US	Buick	LaCrosse	2012/01-2012/12	315MHz	●	●	4	S	315Mhz	Schrader	12768826/ 20922900/ 22854866		12768826/ 20922900/ 22854866
1055	US	Buick	LaCrosse	2011/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	12768826/ 20922900/ 22854866		12768826/ 20922900/ 22854866
1054	US	Buick	LaCrosse	2010/01-2010/12	315MHz	●	●	4	S	315Mhz	Schrader	12768826/ 20922900/ 22854866		12768826/ 20922900/ 22854866
1053	US	Buick	LaCrosse	2009/01-2009/12	315MHz	●	●	4	S	315Mhz	Schrader	12768826/ 20922900/ 22854866		12768826/ 20922900/ 22854866
1052	US	Buick	LaCrosse	2007/01-2008/12	315MHz	●	●	4	S	315Mhz	Continental	15921013	S120123009A	
1059	US	Buick	LeSabre	2007/01-2007/12	315MHz	○	●	4	S	315Mhz	Schrader	25799331		25799331
1064	US	Buick	Lucerne	2011/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615		25920615
1063	US	Buick	Lucerne	2010/01-2010/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615		25920615

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufactuer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
1062	US	Buick	Lucerne	2009/01-2009/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615		25920615
1061	US	Buick	Lucerne	2008/01-2008/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615		25920615
1060	US	Buick	Lucerne	2007/01-2007/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615		25920615
1065	US	Buick	Rainier	2006/01-2007/12	Clamp	●	●	4	S	315Mhz	Schrader	25774006		25774006
1066	US	Buick	Rainier	2006/01-2007/12	Snap	●	●	4	S	315Mhz	Schrader	25799331		25799331
1069	US	Buick	Regal	2013/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	12768826/ 20922900/ 22854866		12768826/ 20922900/ 22854866
1068	US	Buick	Regal	2012/01-2012/12	315MHz	●	●	4	S	315Mhz	Schrader	12768826/ 20922900/ 22854866		12768826/ 20922900/ 22854866
1067	US	Buick	Regal	2011/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	12768826/ 20922900/ 22854866		12768826/ 20922900/ 22854866
1071	US	Buick	Verano	2012/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	12768826/ 20922900/ 22854866		12768826/ 20922900/ 22854866
1073	US	Cadillac	ATS	2014/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	13581558		13581558
1072	US	Cadillac	ATS	2013/01-2013/12	315MHz	●	●	4	S	315Mhz	Continental	22959744		
1075	US	Cadillac	ATS-V	2014/01-2015/12	315MHz	○	●	4	S	315Mhz	Schrader	20964159		20964159
1081	US	Cadillac	CTS	2013/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615		25920615
2658	US	Cadillac	CTS	2012/01-2012/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615		25920615
1080	US	Cadillac	CTS	2009/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	13586335/ 25920615/ 20923680/ 25799331		25920615/20923680
1079	US	Cadillac	CTS	2008/01-2008/12	315MHz	●	●	4	S	315Mhz	Schrader	13586335/ 25920615/ 20923680/ 25799331		25920615/20923680
1078	US	Cadillac	CTS	2007/01-2007/12	315MHz	●	●	4	S	315Mhz	Schrader	25774006		25774006
1077	US	Cadillac	CTS	2006/01-2006/12	315MHz	●	●	4	S	315Mhz	Schrader	25774006		25774006
1076	US	Cadillac	CTS	2004/01-2005/12	315MHz	○	●	4	S	315Mhz	Schrader	25774006		25774006
1082	US	Cadillac	CTS-V	2009/01-2015/12	315MHz	○	●	4	S	315Mhz	Schrader	15268606		15268606
1083	US	Cadillac	CTS-V(Sport)	2014/01-2014/12	315MHz	○	●	4	S	315Mhz	Schrader	15268606		15268606
1086	US	Cadillac	Deville	2005/01-2005/12	315MHz	●	●	4	S	315Mhz	Schrader	25773946		25773946
1085	US	Cadillac	Deville	2004/01-2004/12	315MHz	●	●	4	S	315Mhz	Schrader	25773946		25773946
1084	US	Cadillac	Deville	2001/01-2003/12	315MHz	●	●	4	S	315Mhz	Schrader	25773946		25773946
1090	US	Cadillac	DTS	2009/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	13586335/ 25920615/ 20923680/ 25799331		25920615/20923680
1089	US	Cadillac	DTS	2008/01-2008/12	315MHz	●	●	4	S	315Mhz	Schrader	13586335/ 25920615/ 20923680/ 25799331		25920615/20923680
1088	US	Cadillac	DTS	2007/01-2007/12	315MHz	●	●	4	S	315Mhz	Schrader	13586335/ 25920615/ 20923680/ 25799331		25920615/20923680

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufactuer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
1087	US	Cadillac	DTS	2006/01-2006/12	315MHz	○	●	4	S	315Mhz	Schrader	15268606		15268606
1091	US	Cadillac	ELR	2014/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	22854866/ 20922900		22854866/ 20922900
1098	US	Cadillac	Escalade	2013/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	13586335/ 25920615/ 20923680/ 25799331		25920615/20923680
2657	US	Cadillac	Escalade	2012/01-2012/12	315MHz	●	●	4	S	315Mhz	Schrader	13586335/ 25920615/ 20923680/ 25799331		25920615/ 20923680
1097	US	Cadillac	Escalade	2009/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	13586335/ 25920615/ 20923680/ 25799331		25920615/20923680
1096	US	Cadillac	Escalade	2008/01-2008/12	315MHz	●	●	4	S	315Mhz	Schrader	13586335/ 25920615/ 20923680/ 25799331		25920615/20923680
1094	US	Cadillac	Escalade	2007/01-2007/12	Clamp in	●	●	4	S	315Mhz	TRW	15825475		
1095	US	Cadillac	Escalade	2007/01-2007/12	Snap in	●	●	4	S	315Mhz	Schrader	20923680		20923680
1093	US	Cadillac	Escalade	2005/01-2006/12	315MHz	●	●	4	S	315Mhz	Schrader	15114379		15114379
1092	US	Cadillac	Escalade	2004/01-2004/12	315MHz	●	●	4	S	315Mhz	Schrader	15136883		15136883
1100	US	Cadillac	Seville	2004/01-2004/12	315MHz	●	●	4	S	315Mhz	Schrader	25773946		25773946
1099	US	Cadillac	Seville	2001/01-2003/12	315MHz	●	●	4	S	315Mhz	Schrader	25773946		25773946
1106	US	Cadillac	SRX	2015/01-2015/12	433MHz	○	●	4	S	433Mhz	Schrader	13581561		13581561
1105	US	Cadillac	SRX	2012/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	12768826		12768826
1104	US	Cadillac	SRX	2010/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	12768826		12768826
1103	US	Cadillac	SRX	2009/01-2009/12	315MHz	●	●	4	S	315Mhz	Schrader	12768826/ 20923680		12768826/20923680
1102	US	Cadillac	SRX	2007/01-2008/12	315MHz	●	●	4	S	315Mhz	Schrader	12768826/ 20923680		12768826/20923680
1101	US	Cadillac	SRX	2004/01-2006/12	315MHz	●	●	4	S	315Mhz	Schrader	25774006		25774006
1111	US	Cadillac	STS	2010/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	20923680		20923680
1109	US	Cadillac	STS	2009/01-2009/12	Clamp in	●	●	4	S	315Mhz	Schrader	25920615		25920615
1110	US	Cadillac	STS	2009/01-2009/12	Snap in	●	●	4	S	315Mhz	Schrader	25920615		25920615
1108	US	Cadillac	STS	2008/01-2008/12	315MHz	●	●	4	S	315Mhz	Schrader	25758220		25758220
1107	US	Cadillac	STS	2005/01-2007/12	315MHz	●	●	4	S	315Mhz	Schrader	25758220		25758220
1114	US	Cadillac	XLR	2010/01-2011/12	315MHz	○	●	4	S	315Mhz	Schrader	25758220		25758220
1113	US	Cadillac	XLR	2006/01-2009/12	315MHz	●	●	4	S	315Mhz	Schrader	25758220		25758220
1112	US	Cadillac	XLR	2004/01-2005/12	315MHz	○	●	4	S	315Mhz	Schrader	25758220		25758220
1116	US	Cadillac	XTS	2015/01-2015/12	433MHz	○	●	4	S	433Mhz	Schrader	22853740	90518185	22853740
1115	US	Cadillac	XTS	2013/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	22854866/ 20922900/ 12768826		22854866/ 20922900/ 12768826
1123	US	Chevrolet	Avalanche	2012/01-2013/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/20923680
1122	US	Chevrolet	Avalanche	2009/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/20923680

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
1121	US	Chevrolet	Avalanche	2008/01-2008/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/20923680
1119	US	Chevrolet	Avalanche	2007/01-2007/12	Clamp in	●	●	4	S	315Mhz	TRW	15825475		
1120	US	Chevrolet	Avalanche	2007/01-2007/12	Snap in	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/20923680
1118	US	Chevrolet	Avalanche	2005/01-2006/12	315MHz	○	●	4	S	315Mhz	Schrader	15114379		15114379
1117	US	Chevrolet	Avalanche	2004/01-2004/12	315MHz	○	●	4	S	315Mhz	Schrader	15136883		15136883
1125	US	Chevrolet	Aveo	2008/01-2011/12	315MHz	●	●	4	O	315Mhz	Schrader	25920615/ 20923680		25920615/20923680
1124	US	Chevrolet	Aveo	2007/01-2007/12	315MHz	○	●	4	O	315Mhz	Schrader	25920615/ 20923680		25920615/20923680
1129	US	Chevrolet	Camaro	2014/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	12768826/ 20922900/ 22854866		22854866 20922900/ 12768826
1130	US	Chevrolet	Camaro	2014/01-2015/12	433MHz	○	●	4	S	433Mhz	Schrader	22853740	90518185	22853740
1128	US	Chevrolet	Camaro	2012/01-2013/12	315MHz	●	●	4	S	315Mhz	Schrader	12768826/ 20922900/ 22854866		22854866 20922900/ 12768826
1127	US	Chevrolet	Camaro	2011/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	12768826/ 20922900/ 22854866		22854866 20922900/ 12768826
1126	US	Chevrolet	Camaro	2010/01-2010/12	315MHz	●	●	4	S	315Mhz	Schrader	12768826/ 20922900/ 22854866		22854866 20922900/ 12768826
1131	US	Chevrolet	Camaro ZL1	2012/01-2015/12	315MHz	○	●	4	S	315Mhz	Schrader	20964159		20964159
1133	US	Chevrolet	Caprice	2014/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	13581559		13581559
1134	US	Chevrolet	Captiva sport	2013/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	12768826/20923680		12768826/20923680
2647	US	Chevrolet	Captiva sport	2009/01-2012/12	315MHz	●	●	4	S	315Mhz	Schrader	12768826/20923680		12768826/ 20923680
1135	US	Chevrolet	Cheyenne	2014/01-2014/12	Snap in	○	●	4		315Mhz	Schrader	13581558		13581558
1140	US	Chevrolet	Cobalt	2010/01-2010/12	315MHz	●	●	4	S	315Mhz	Schrader	22854866/ 20922900/ 12768826		22854866 20922900/ 12768826
1138	US	Chevrolet	Cobalt	2009/01-2009/12	Clamp in	●	●	4	S	315Mhz	Continental	15921013	S120123009A	
1139	US	Chevrolet	Cobalt	2009/01-2009/12	Snap in	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/20923680
1136	US	Chevrolet	Cobalt	2008/01-2008/12	Clamp in	●	●	4	S	315Mhz	Continental	15921013	S120123009A	
1137	US	Chevrolet	Cobalt	2008/01-2008/12	Snap in	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/20923680
1143	US	Chevrolet	Colorado	2012/01-2012/12	315MHz	●	●	4	S	315Mhz	Schrader	15122618		15122618
1142	US	Chevrolet	Colorado	2011/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	15122618		15122618
1141	US	Chevrolet	Colorado	2007/01-2010/12	315MHz	●	●	4	S	315Mhz	Schrader	15122618		15122618
1151	US	Chevrolet	Corvette	2014/01-2015/12	433MHz	●	●	4	A	433Mhz	Schrader	13581560		13581560
1150	US	Chevrolet	Corvette	2013/01-2013/12	315MHz	●	●	4	S	315Mhz	Schrader	20925924		20925924
2670	US	Chevrolet	Corvette	2012/01-2012/12	315MHz	●	●	4	S	315Mhz	Schrader	20925924		20925924
1149	US	Chevrolet	Corvette	2010/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	15268606		15268606
1148	US	Chevrolet	Corvette	2006/01-2009/12	315MHz	●	●	4	S	315Mhz	Schrader	25758220		25758220
1147	US	Chevrolet	Corvette	2005/01-2005/12	315MHz	●	●	4	S	315Mhz	Schrader	25758220		25758220
1146	US	Chevrolet	Corvette	2003/01-2004/12	315MHz	●	●	4	S	315Mhz	Schrader	25773946		25773946
1145	US	Chevrolet	Corvette	2001/01-2002/12	315MHz	●	●	4	S	315Mhz	Schrader	25773946		25773946

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
1144	US	Chevrolet	Corvette	1997/01-2000/12	315MHz	○	●	4	S	315Mhz	Schrader	10438853		10438853
1153	US	Chevrolet	Corvette C5	2003/01-2004/12	315MHz	●	●	4	S	315Mhz	Schrader	25773946		25773946
1152	US	Chevrolet	Corvette C5	2001/01-2002/12	315MHz	●	●	4	S	315Mhz	Schrader	25773946		25773946
1154	US	Chevrolet	Corvette C6	2005/01-2009/12	315MHz	●	●	4	S	315Mhz	Schrader	25758220		25758220
1159	US	Chevrolet	Corvette Z06	2012/01-2012/12	315MHz	●	●	4	S	315Mhz	Schrader	20925924		20925924
1158	US	Chevrolet	Corvette Z06	2010/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	15268606		15268606
1157	US	Chevrolet	Corvette Z06	2005/01-2009/12	315MHz	●	●	4	S	315Mhz	Schrader	25758220		25758220
1156	US	Chevrolet	Corvette Z06	2003/01-2004/12	315MHz	●	●	4	S	315Mhz	Schrader	25773946		25773946
1155	US	Chevrolet	Corvette Z06	2001/01-2002/12	315MHz	●	●	4	S	315Mhz	Schrader	25773946		25773946
1161	US	Chevrolet	Cruze	2012/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	20922900/ 12768826/ 22854866		20922900
1160	US	Chevrolet	Cruze	2011/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	20922900/ 12768826/ 22854866		20922900
1166	US	Chevrolet	Equinox	2012/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	12768826/ 20922900/ 22854866/ 13589597		12768826/ 20922900/ 22854866/ 13589597
1165	US	Chevrolet	Equinox	2010/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	12768826/ 20922900/ 22854866/		12768826/ 20922900/ 22854866/
1164	US	Chevrolet	Equinox	2009/01-2009/12	315MHz	●	●	4	S	315Mhz	Continental	15921013	S120123009A	
1163	US	Chevrolet	Equinox	2008/01-2008/12	315MHz	●	●	4	S	315Mhz	Continental	15921013	S120123009A	
1162	US	Chevrolet	Equinox	2007/01-2007/12	315MHz	●	●	4	S	315Mhz	Continental	15921013	S120123009A	
1170	US	Chevrolet	Express Series	2012/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/ 20923680
1169	US	Chevrolet	Express Series	2010/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/ 20923680
1168	US	Chevrolet	Express Series	2009/01-2009/12	315MHz	●	●	4	S	315Mhz	Continental	15921013	S120123009A	
1167	US	Chevrolet	Express Series	2008/01-2008/12	315MHz	●	●	4	S	315Mhz	Continental	15921013	S120123009A	
1171	US	Chevrolet	G Series	2008/01-2011/12	315MHz	○	●	4	S	315Mhz	Continental	15921013	S120123009A	
1175	US	Chevrolet	HHR	2010/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	12768826/ 25920615/ 20923680		12768826/ 25920615/ 20923680
1173	US	Chevrolet	HHR	2009/01-2009/12	Clamp in	●	●	4	S	315Mhz	Schrader	25920615/ 13586335		25920615/ 13586335
1174	US	Chevrolet	HHR	2009/01-2009/12	Snap in	●	●	4	S	315Mhz	Schrader	20923680/ 25920615/ 13586335/ 15254101/ 25799331		20923680
1172	US	Chevrolet	HHR	2008/01-2008/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615/ 13586335		25920615/ 13586335
1182	US	Chevrolet	Impala	2014/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/ 20923680
1181	US	Chevrolet	Impala	2013/01-2013/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/ 20923680
2646	US	Chevrolet	Impala	2012/01-2012/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/ 20923680

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufactuer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
1180	US	Chevrolet	Impala	2009/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/ 20923680
1179	US	Chevrolet	Impala	2008/01-2008/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/ 20923680
1177	US	Chevrolet	Impala	2007/01-2007/12	Clamp in	●	●	4	S	315Mhz	Schrader	15268606		15268606
1178	US	Chevrolet	Impala	2007/01-2007/12	Snap in	●	●	4	S	315Mhz	Schrader	25920615/ 20923680/ 13586335		25920615/ 20923680/ 13586335
1176	US	Chevrolet	Impala	2006/01-2006/12	315MHz	●	●	4	S	315Mhz	Schrader	15268606		20923680
1188	US	Chevrolet	Malibu	2014/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	22854866/ 20922900/ 12768826		22854866 20922900/ 12768826
1187	US	Chevrolet	Malibu	2012/01-2013/12	315MHz	●	●	4	S	315Mhz	Schrader	22854866/ 20922900/ 12768826		22854866 20922900/ 12768826
1186	US	Chevrolet	Malibu	2010/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	12768826/ 25920615/ 20923680		12768826/ 25920615/ 20923680
1185	US	Chevrolet	Malibu	2009/01-2009/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/ 20923680
1183	US	Chevrolet	Malibu	2008/01-2008/12	Clamp in	●	●	4	S	315Mhz	Continental	15921013	S120123009A	
1184	US	Chevrolet	Malibu	2008/01-2008/12	Snap in	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/ 20923680
1190	US	Chevrolet	Monte Carlo	2007/01-2007/12	Clamp in	●	●	4	S	315Mhz	Schrader	15268606		15268606
1191	US	Chevrolet	Monte Carlo	2007/01-2007/12	Snap in	●	●	4	S	315Mhz	Schrader	20923680/ 25920615/ 13586335/ 15254101/ 25799331		20923680
1189	US	Chevrolet	Monte Carlo	2006/01-2006/12	315MHz	●	●	4	S	315Mhz	Schrader	15268606		15268606
1192	US	Chevrolet	Orlando	2012/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	22854866/ 20922900/ 12768826		22854866 20922900/ 12768826
1199	US	Chevrolet	Silverado	2014/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	13581558		13581558
1198	US	Chevrolet	Silverado	2009/01-2013/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/ 20923680
1197	US	Chevrolet	Silverado	2008/01-2008/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/ 20923680
1195	US	Chevrolet	Silverado	2007/01-2007/12	Clamp in	●	●	4	S	315Mhz	TRW	15825475		
1196	US	Chevrolet	Silverado	2007/01-2007/12	Snap in	●	●	4	S	315Mhz	Schrader	20923680/ 25920615/ 13586335/ 15254101/ 25799331		20923680
1194	US	Chevrolet	Silverado	2005/01-2006/12	315MHz	●	●	4	S	315Mhz	Schrader	15114379		15114379
1193	US	Chevrolet	Silverado	2004/01-2004/12	315MHz	●	●	4	S	315Mhz	Schrader	15136883		15136883
1200	US	Chevrolet	Sonic	2012/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	12768826/ 20922900/ 22854866/ 22854866/		12768826/ 20922900/ 22854866/ 22854866/
1201	US	Chevrolet	Spark	2013/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	22854866/ 20922900/ 12768826		22854866 20922900/ 12768826

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufactuer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
1203	US	Chevrolet	SS	2014/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	20964159		20964159
1204	US	Chevrolet	SSR	2006/01-2007/12	315MHz	○	●	4	S	315Mhz	Schrader	25774006		25774006
1211	US	Chevrolet	Suburban	2014/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/ 20923680
1210	US	Chevrolet	Suburban	2009/01-2013/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/ 20923680
1209	US	Chevrolet	Suburban	2008/01-2008/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/ 20923680
1207	US	Chevrolet	Suburban	2007/01-2007/12	Clamp in	●	●	4	S	315Mhz	TRW	15825475		
1208	US	Chevrolet	Suburban	2007/01-2007/12	Snap in	●	●	4	S	315Mhz	Schrader	20923680/ 25920615/ 13586335/ 15254101/ 25799331		20923680
1206	US	Chevrolet	Suburban	2005/01-2006/12	315MHz	○	●	4	S	315Mhz	Schrader	15114379		15114379
1205	US	Chevrolet	Suburban	2004/01-2004/12	315MHz	○	●	4	S	315Mhz	Schrader	15136883		15136883
1218	US	Chevrolet	Tahoe	2014/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/ 20923680
1217	US	Chevrolet	Tahoe	2009/01-2013/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/ 20923680
1216	US	Chevrolet	Tahoe	2008/01-2008/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/ 20923680
1214	US	Chevrolet	Tahoe	2007/01-2007/12	Clamp in	●	●	4	S	315Mhz	TRW	15825475		
1215	US	Chevrolet	Tahoe	2007/01-2007/12	Snap in	●	●	4	S	315Mhz	Schrader	20923680/ 25920615/ 13586335/ 15254101/ 25799331		20923680
1213	US	Chevrolet	Tahoe	2005/01-2006/12	315MHz	○	●	4	S	315Mhz	Schrader	15114379		15114379
1212	US	Chevrolet	Tahoe	2004/01-2004/12	315MHz	○	●	4	S	315Mhz	Schrader	15136883		15136883
1220	US	Chevrolet	Trailblazer	2007/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	25774006		25774006
1219	US	Chevrolet	Trailblazer	2006/01-2006/12	315MHz	●	●	4	S	315Mhz	Schrader	25774006		25774006
1222	US	Chevrolet	Traverse	2014/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/ 20923680
1221	US	Chevrolet	Traverse	2009/01-2013/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/20923680
1223	US	Chevrolet	Trax	2013/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	22854866		22854866
1224	US	Chevrolet	Uplander	2008/01-2009/12	315MHz	●	●	4	S	315Mhz	Schrader	15268606		15268606
1228	US	Chevrolet	Volt	2014/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	12768826/ 20922900/ 22854866/		12768826/ 20922900/ 22854866/
1227	US	Chevrolet	Volt	2012/01-2013/12	315MHz	●	●	4	S	315Mhz	Schrader	12768826/ 20922900/ 22854866/		12768826/ 20922900/ 22854866/
1226	US	Chevrolet	Volt	2011/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	12768826/ 20922900/ 22854866/		12768826/ 20922900/ 22854866/
1225	US	Chevrolet	Volt	2010/01-2010/12	315MHz	○	●	4	S	315Mhz	Schrader	20923680/ 25920615/ 13586335/ 15254101/ 25799331		20923680

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
1231	US	Chrysler	200	2015/01-2015/12	433MHz	●	●	4	A	433Mhz	Schrader	68193586AC		68193586AC
1232	US	Chrysler	200	2015/01-2015/12	433MHz	●	●	5	A	433Mhz	Schrader	68193586AC		68193586AC
1229	US	Chrysler	200	2011/01-2014/12	315MHz	●	●	4	A	315Mhz	Continental	68078861AA/ 68001696AB		
1230	US	Chrysler	200	2011/01-2014/12	315MHz	●	●	5	A	315Mhz	Continental	68078861AA/ 68001696AB		
1245	US	Chrysler	300	2011/01-2015/12	433MHz	●	●	4	A	433Mhz	Schrader	56029398AB		56029398AB
1246	US	Chrysler	300	2011/01-2015/12	433MHz	●	●	5	A	433Mhz	Schrader	56029398AB		56029398AB
1243	US	Chrysler	300	2010/01-2010/12	433MHz	●	●	4	A	433Mhz	Schrader	56029398AB		56029398AB
1244	US	Chrysler	300	2010/01-2010/12	433MHz	●	●	5	A	433Mhz	Schrader	56029398AB		56029398AB
1241	US	Chrysler	300	2009/01-2009/12	433MHz	●	●	4	A	433Mhz	Schrader	56029400AE/ 56029400AD/ 56029400AC/ 56029400AB		56029400AE/ 56029400AD/ 56029400AC/ 56029400AB
1242	US	Chrysler	300	2009/01-2009/12	433MHz	●	●	5	A	433Mhz	Schrader	56029400AE/ 56029400AD/ 56029400AC/ 56029400AB		56029400AE/ 56029400AD/ 56029400AC/ 56029400AB
1239	US	Chrysler	300	2008/01-2008/12	433MHz	●	●	4	A	433Mhz	Continental	68001698AB/ 68078768AA		
1240	US	Chrysler	300	2008/01-2008/12	433MHz	●	●	5	A	433Mhz	Continental	68001698AB/ 68078768AA		
1235	US	Chrysler	300	2007/01-2007/12	315MHz	●	●	4	A	315Mhz	Continental	68001696AB		
1236	US	Chrysler	300	2007/01-2007/12	315MHz	●	●	5	A	315Mhz	Continental	68001696AB		
1237	US	Chrysler	300	2007/01-2007/12	433MHz	●	●	4	A	433Mhz	Continental	68078768AA		
1238	US	Chrysler	300	2007/01-2007/12	433MHz	●	●	5	A	433Mhz	Continental	68078768AA		
1233	US	Chrysler	300	2005/01-2006/12	315MHz	●	●	4	A	315Mhz	Continental	68111696AA		
1234	US	Chrysler	300	2005/01-2006/12	315MHz	●	●	5	A	315Mhz	Continental	68111696AA		
1247	US	Chrysler	300 SRT	2010/01-2014/12	433MHz	●	●	4	A	433Mhz	Schrader	56029400AE/ 56029400AD/ 56029400AC/ 56029400AB		56029400AE/ 56029400AD/ 56029400AC/ 56029400AB
1248	US	Chrysler	300 SRT	2010/01-2014/12	433MHz	●	●	5	A	433Mhz	Schrader	56029400AE/ 56029400AD/ 56029400AC/ 56029400AB		56029400AE/ 56029400AD/ 56029400AC/ 56029400AB
1249	US	Chrysler	300C	2007/06-2015/12	433MHz	●	●	4	S	433Mhz	Schrader	56029400AE/ 56029398AB		56029400AE/ 56029398AB
1250	US	Chrysler	300C	2007/06-2015/12	433MHz	●	●	5	S	433Mhz	Schrader	56029400AE/ 56029398AB		56029400AE/ 56029398AB
1251	US	Chrysler	300M	2002/01-2004/12	433MHz	●	●	4	A	433Mhz	Schrader	52088990AC/ 52088990AD		52088990AD/ 52088990AC
1252	US	Chrysler	300M	2002/01-2004/12	433MHz	●	●	5	A	433Mhz	Schrader	52088990AC/ 52088990AD		52088990AD/ 52088990AC
1255	US	Chrysler	Aspen	2008/01-2011/12	315MHz	●	●	4	A	315Mhz	Schrader	56029465AB		56029465AB
1256	US	Chrysler	Aspen	2008/01-2011/12	315MHz	●	●	5	A	315Mhz	Schrader	56029465AB		56029465AB
1253	US	Chrysler	Aspen	2007/01-2007/12	315MHz	●	●	4	A	315Mhz	Continental	68001696AB		
1254	US	Chrysler	Aspen	2007/01-2007/12	315MHz	●	●	5	A	315Mhz	Continental	68001696AB		
1257	US	Chrysler	Concorde	2002/01-2004/12	433MHz	●	●	4	S	433Mhz	Schrader	52088990AC/ 52088990AD		52088990AD/ 52088990AC

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
1258	US	Chrysler	Concorde	2002/01-2004/12	433MHz	●	●	5	S	433Mhz	Schrader	52088990AC/ 52088990AD		52088990AD/ 52088990AC
1261	US	Chrysler	Crossfire	2005/01-2011/12	315MHz	●	●	4	O	315Mhz	Continental	68001696AB		
1262	US	Chrysler	Crossfire	2005/01-2011/12	315MHz	●	●	5	O	315Mhz	Continental	68001696AB		
1263	US	Chrysler	Crossfire	2005/01-2011/12	433MHz	●	●	4	O	433Mhz	Schrader	52088990AD		52088990AD
1264	US	Chrysler	Crossfire	2005/01-2011/12	433MHz	●	●	5	O	433Mhz	Schrader	52088990AD		52088990AD
1259	US	Chrysler	Crossfire	2004/01-2004/12	433MHz	●	●	4	O	433Mhz	Schrader	52088990AC/ 52088990AD		52088990AD/ 52088990AC
1260	US	Chrysler	Crossfire	2004/01-2004/12	433MHz	●	●	5	O	433Mhz	Schrader	52088990AC/ 52088990AD		52088990AD/ 52088990AC
1265	US	Chrysler	Intrepid	2002/01-2004/12	433MHz	●	●	4	S	433Mhz	Schrader	52088990AC/ 52088990AD		52088990AD/ 52088990AC
1266	US	Chrysler	Intrepid	2002/01-2004/12	433MHz	●	●	5	S	433Mhz	Schrader	52088990AC/ 52088990AD		52088990AD/ 52088990AC
1275	US	Chrysler	Pacifica	2006/01-2008/12	315MHz	●	●	4	A	315Mhz	Continental	68001696AAAB		
1276	US	Chrysler	Pacifica	2006/01-2008/12	315MHz	●	●	5	A	315Mhz	Continental	68001696AAAB		
1273	US	Chrysler	Pacifica	2005/01-2005/12	315MHz	●	●	4	A	315Mhz	Continental	04727392AB/ 5127335AE		
1274	US	Chrysler	Pacifica	2005/01-2005/12	315MHz	●	●	5	A	315Mhz	Continental	04727392AB/ 5127335AE		
1269	US	Chrysler	Pacifica	2004/01-2004/12	315MHz	●	●	4	A	315Mhz	Continental	5127335AE/ 04727392AB		
1270	US	Chrysler	Pacifica	2004/01-2004/12	315MHz	●	●	5	A	315Mhz	Continental	5127335AE/ 04727392AB		
1271	US	Chrysler	Pacifica	2004/01-2004/12	433MHz	●	●	4	A	433Mhz	Schrader	52088990AD		52088990AD
1272	US	Chrysler	Pacifica	2004/01-2004/12	433MHz	●	●	5	A	433Mhz	Schrader	52088990AD		52088990AD
1267	US	Chrysler	Pacifica	2003/01-2003/12	433MHz	●	●	4	A	433Mhz	Schrader	52088990AD		52088990AD
1268	US	Chrysler	Pacifica	2003/01-2003/12	433MHz	●	●	5	A	433Mhz	Schrader	52088990AD		52088990AD
1277	US	Chrysler	Prowler	2002/01-2002/12	433MHz	●	●	4	O	433Mhz	Schrader	52088990AC/ 52088990AD		52088990AD/ 52088990AC
1278	US	Chrysler	Prowler	2002/01-2002/12	433MHz	●	●	5	O	433Mhz	Schrader	52088990AC/ 52088990AD		52088990AD/ 52088990AC
1279	US	Chrysler	PT Cruiser	2008/01-2010/12	315MHz	●	●	4	A	315Mhz	Continental	68001696AAAB		
1280	US	Chrysler	PT Cruiser	2008/01-2010/12	315MHz	●	●	5	A	315Mhz	Continental	68001696AAAB		
1287	US	Chrysler	Sebring	2010/01-2012/12	315MHz	●	●	4	A	315Mhz	Continental	68001696AB		
1288	US	Chrysler	Sebring	2010/01-2012/12	315MHz	●	●	5	A	315Mhz	Continental	68001696AB		
1283	US	Chrysler	Sebring	2008/01-2009/12	315MHz	●	●	4	A	315Mhz	Continental	68001696AAAB		
1284	US	Chrysler	Sebring	2008/01-2009/12	315MHz	●	●	5	A	315Mhz	Continental	68001696AAAB		
1285	US	Chrysler	Sebring	2008/01-2009/12	433MHz	●	●	4	A	433Mhz	Continental	68078768AA		
1286	US	Chrysler	Sebring	2008/01-2009/12	433MHz	●	●	5	A	433Mhz	Continental	68078768AA		
1281	US	Chrysler	Sebring	2007/01-2007/12	315MHz	●	●	4	A	315Mhz	Continental	68001696AAAB		
1282	US	Chrysler	Sebring	2007/01-2007/12	315MHz	●	●	5	A	315Mhz	Continental	68001696AAAB		
1301	US	Chrysler	Town & Country	2011/01-2015/12	433MHz	●	●	4	A	433Mhz	Schrader	56029398AB		56029398AB
1302	US	Chrysler	Town & Country	2011/01-2015/12	433MHz	●	●	5	A	433Mhz	Schrader	56029398AB		56029398AB
1299	US	Chrysler	Town & Country	2009/01-2010/12	433MHz	●	●	4	A	433Mhz	Continental	68078768AA		
1300	US	Chrysler	Town & Country	2009/01-2010/12	433MHz	●	●	5	A	433Mhz	Continental	68078768AA		
1295	US	Chrysler	Town & Country	2008/01-2008/12	315MHz	●	●	4	A	315Mhz	Continental	68001696AB		
1296	US	Chrysler	Town & Country	2008/01-2008/12	315MHz	●	●	5	A	315Mhz	Continental	68001696AB		
1297	US	Chrysler	Town & Country	2008/01-2008/12	433MHz	●	●	4	A	433Mhz	Continental	68078768AA		

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow: Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
1298	US	Chrysler	Town & Country	2008/01-2008/12	433MHz	●	●	5	A	433Mhz	Continental	68078768AA		
1293	US	Chrysler	Town & Country	2006/01-2007/12	315MHz	●	●	4	A	315Mhz	Continental	56053030ABAC		
1294	US	Chrysler	Town & Country	2006/01-2007/12	315MHz	●	●	5	A	315Mhz	Continental	56053030ABAC		
1291	US	Chrysler	Town & Country	2004/01-2005/12	315MHz	●	●	4	A	315Mhz	Continental	04727392AB/ 5127335AE		
1292	US	Chrysler	Town & Country	2004/01-2005/12	315MHz	●	●	5	A	315Mhz	Continental	04727392AB/ 5127335AE		
1289	US	Chrysler	Town & Country	2002/01-2003/12	433MHz	●	●	4	S	433Mhz	Schrader	52088990AC/ 52088990AD		52088990AD/ 52088990AC
1290	US	Chrysler	Town & Country	2002/01-2003/12	433MHz	●	●	5	S	433Mhz	Schrader	52088990AC/ 52088990AD		52088990AD/ 52088990AC
1303	US	Chrysler	Voyager	2002/01-2003/12	433MHz	●	●	4	S	433Mhz	Schrader	52088990AC/ 52088990AD		52088990AD/ 52088990AC
1304	US	Chrysler	Voyager	2002/01-2003/12	433MHz	●	●	5	S	433Mhz	Schrader	52088990AC/ 52088990AD		52088990AD/ 52088990AC
1305	US	Dodge	Avenger	2007/01-2014/12	315MHz	●	●	4	A	315Mhz	Continental	68001696AAAB		
1306	US	Dodge	Avenger	2007/01-2014/12	315MHz	●	●	5	A	315Mhz	Continental	68001696AAAB		
1315	US	Dodge	Caliber	2011/01-2012/12	315MHz	●	●	4	A	315Mhz	Continental	68078861AA/ 68078861AB/ 56053030AB		
1316	US	Dodge	Caliber	2011/01-2012/12	315MHz	●	●	5	A	315Mhz	Continental	68078861AA/ 68078861AB/ 56053030AB		
1313	US	Dodge	Caliber	2010/01-2010/12	315MHz	●	●	4	A	315Mhz	Continental	68001696AAAB		
1314	US	Dodge	Caliber	2010/01-2010/12	315MHz	●	●	5	A	315Mhz	Continental	68001696AAAB		
1311	US	Dodge	Caliber	2008/01-2009/12	315MHz	●	●	4	A	315Mhz	Continental	68001696AAAB		
1312	US	Dodge	Caliber	2008/01-2009/12	315MHz	●	●	5	A	315Mhz	Continental	68001696AAAB		
1309	US	Dodge	Caliber	2007/01-2007/12	315MHz	●	●	4	A	315Mhz	Continental	68001696AAAB		
1310	US	Dodge	Caliber	2007/01-2007/12	315MHz	●	●	5	A	315Mhz	Continental	68001696AAAB		
1321	US	Dodge	Caravan	2006/01-2007/12	315MHz	●	●	4	A	315Mhz	Continental	56053030ABAC		
1322	US	Dodge	Caravan	2006/01-2007/12	315MHz	●	●	5	A	315Mhz	Continental	56053030ABAC		
1319	US	Dodge	Caravan	2004/01-2005/12	315MHz	●	●	4	A	315Mhz	Continental	5127335AE/ 04727392AB		
1320	US	Dodge	Caravan	2004/01-2005/12	315MHz	●	●	5	A	315Mhz	Continental	5127335AE/ 04727392AB		
1317	US	Dodge	Caravan	2002/01-2003/12	433MHz	●	●	4	S	433Mhz	Schrader	52088990AC/ 52088990AD		52088990AD/ 52088990AC
1318	US	Dodge	Caravan	2002/01-2003/12	433MHz	●	●	5	S	433Mhz	Schrader	52088990AC/ 52088990AD		52088990AD/ 52088990AC
1329	US	Dodge	Challenger	2011/01-2015/12	433MHz	●	●	4	A	433Mhz	Schrader	56029398AA		56029398AA
1330	US	Dodge	Challenger	2011/01-2015/12	433MHz	●	●	5	A	433Mhz	Schrader	56029398AA		56029398AA
1327	US	Dodge	Challenger	2010/01-2010/12	433MHz	●	●	4	A	433Mhz	Schrader	56029398AA		56029398AA
1328	US	Dodge	Challenger	2010/01-2010/12	433MHz	●	●	5	A	433Mhz	Schrader	56029398AA		56029398AA
1325	US	Dodge	Challenger	2009/01-2009/12	433MHz	●	●	4	A	433Mhz	Schrader	56029398AA		56029398AA
1326	US	Dodge	Challenger	2009/01-2009/12	433MHz	●	●	5	A	433Mhz	Schrader	56029398AA		56029398AA
1323	US	Dodge	Challenger	2008/01-2008/12	433MHz	●	●	4	A	433Mhz	Schrader	56029400AD		56029400AD
1324	US	Dodge	Challenger	2008/01-2008/12	433MHz	●	●	5	A	433Mhz	Schrader	56029400AD		56029400AD
1341	US	Dodge	Charger	2011/01-2015/12	433MHz	●	●	4	A	433Mhz	Schrader	56029398AB/ 56029398AA		56029398AB/ 56029398AA

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
1342	US	Dodge	Charger	2011/01-2015/12	433MHz	●	●	5	A	433Mhz	Schrader	56029398AB/ 56029398AA		56029398AB/ 56029398AA
1339	US	Dodge	Charger	2010/01-2010/12	433MHz	●	●	4	A	433Mhz	Schrader	56029398AB/ 56029398AA		56029398AB/ 56029398AA
1340	US	Dodge	Charger	2010/01-2010/12	433MHz	●	●	5	A	433Mhz	Schrader	56029398AB/ 56029398AA		56029398AB/ 56029398AA
1337	US	Dodge	Charger	2009/01-2009/12	433MHz	●	●	4	A	433Mhz	Schrader	56029400AE/ 56029400AD/ 56029400AC/ 56029400AB		56029400AE/ 56029400AD/ 56029400AC/ 56029400AB
1338	US	Dodge	Charger	2009/01-2009/12	433MHz	●	●	5	A	433Mhz	Schrader	56029400AE/ 56029400AD/ 56029400AC/ 56029400AB		56029400AE/ 56029400AD/ 56029400AC/ 56029400AB
1335	US	Dodge	Charger	2008/01-2008/12	433MHz	●	●	4	A	433Mhz	Continental	68078768AA		
1336	US	Dodge	Charger	2008/01-2008/12	433MHz	●	●	5	A	433Mhz	Continental	68078768AA		
1333	US	Dodge	Charger	2007/01-2007/12	315MHz	●	●	4	A	315Mhz	Continental	68001696AB		
1334	US	Dodge	Charger	2007/01-2007/12	315MHz	●	●	5	A	315Mhz	Continental	68001696AB		
1331	US	Dodge	Charger	2005/01-2006/12	315MHz	●	●	4	A	315Mhz	Continental	56053030AC		
1332	US	Dodge	Charger	2005/01-2006/12	315MHz	●	●	5	A	315Mhz	Continental	56053030AC		
1347	US	Dodge	Charger SRT	2011/01-2012/12	433MHz	●	●	4	A	433Mhz	Schrader	56029400AE/ 56029400AD/ 56029400AC/ 56029400AB		56029400AE/ 56029400AD/ 56029400AC/ 56029400AB
1348	US	Dodge	Charger SRT	2011/01-2012/12	433MHz	●	●	5	A	433Mhz	Schrader	56029400AE/ 56029400AD/ 56029400AC/ 56029400AB		56029400AE/ 56029400AD/ 56029400AC/ 56029400AB
1345	US	Dodge	Charger SRT	2010/01-2010/12	433MHz	●	●	4	A	433Mhz	Schrader	56029400AE/ 56029400AD/ 56029400AC/ 56029400AB		56029400AE/ 56029400AD/ 56029400AC/ 56029400AB
1346	US	Dodge	Charger SRT	2010/01-2010/12	433MHz	●	●	5	A	433Mhz	Schrader	56029400AE/ 56029400AD/ 56029400AC/ 56029400AB		56029400AE/ 56029400AD/ 56029400AC/ 56029400AB
1343	US	Dodge	Charger SRT	2009/01-2009/12	433MHz	●	●	4	A	433Mhz	Schrader	56029400AE/ 56029400AD/ 56029400AC/ 56029400AB		56029400AE/ 56029400AD/ 56029400AC/ 56029400AB
1344	US	Dodge	Charger SRT	2009/01-2009/12	433MHz	●	●	5	A	433Mhz	Schrader	56029400AE/ 56029400AD/ 56029400AC/ 56029400AB		56029400AE/ 56029400AD/ 56029400AC/ 56029400AB
1351	US	Dodge	Dakota	2011/01-2011/12	315MHz	●	●	4	A	315Mhz	Schrader	56029479AA		56029479AA
1352	US	Dodge	Dakota	2011/01-2011/12	315MHz	●	●	5	A	315Mhz	Schrader	56029479AA		56029479AA
1349	US	Dodge	Dakota	2008/01-2010/12	315MHz	●	●	4	A	315Mhz	Schrader	56029319AC/ 56029319AB/ 56029319AA		56029319AC/ 56029319AB/ 56029319AA
1350	US	Dodge	Dakota	2008/01-2010/12	315MHz	●	●	5	A	315Mhz	Schrader	56029319AC/ 56029319AB/ 56029319AA		56029319AC/ 56029319AB/ 56029319AA

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
1353	US	Dodge	Dart	2013/01-2015/12	433MHz	●	●	4	A	433Mhz	Continental	68193586AA		
1354	US	Dodge	Dart	2013/01-2015/12	433MHz	●	●	5	A	433Mhz	Continental	68193586AA		
1359	US	Dodge	Durango	2011/01-2015/12	433MHz	●	●	4	A	433Mhz	Schrader	56029398AB/ 56029398AA		56029398AB/ 56029398AA
1360	US	Dodge	Durango	2011/01-2015/12	433MHz	●	●	5	A	433Mhz	Schrader	56029398AB/ 56029398AA		56029398AB/ 56029398AA
1357	US	Dodge	Durango	2009/01-2010/12	315MHz	●	●	4	A	315Mhz	Schrader	56029465AB		56029465AB
1358	US	Dodge	Durango	2009/01-2010/12	315MHz	●	●	5	A	315Mhz	Schrader	56029465AB		56029465AB
1355	US	Dodge	Durango	2007/01-2008/12	315MHz	●	●	4	A	315Mhz	Continental	56053030AC		
1356	US	Dodge	Durango	2007/01-2008/12	315MHz	●	●	5	A	315Mhz	Continental	56053030AC		
1371	US	Dodge	Grand Caravan	2011/01-2015/12	433MHz	●	●	4	A	433Mhz	Schrader	56029398AB/ 56029398AA		56029398AB/ 56029398AA
1372	US	Dodge	Grand Caravan	2011/01-2015/12	433MHz	●	●	5	A	433Mhz	Schrader	56029398AB/ 56029398AA		56029398AB/ 56029398AA
1369	US	Dodge	Grand Caravan	2008/01-2010/12	433MHz	●	●	4	A	433Mhz	Continental	68078768AA		
1370	US	Dodge	Grand Caravan	2008/01-2010/12	433MHz	●	●	5	A	433Mhz	Continental	68078768AA		
1367	US	Dodge	Grand Caravan	2007/01-2007/12	315MHz	●	●	4	A	315Mhz	Continental	56053030AC		
1368	US	Dodge	Grand Caravan	2007/01-2007/12	315MHz	●	●	5	A	315Mhz	Continental	56053030AC		
1365	US	Dodge	Grand Caravan	2006/01-2006/12	315MHz	●	●	4	A	315Mhz	Continental	56053030AC		
1366	US	Dodge	Grand Caravan	2006/01-2006/12	315MHz	●	●	5	A	315Mhz	Continental	56053030AC		
1363	US	Dodge	Grand Caravan	2004/01-2005/12	315MHz	●	●	4	A	315Mhz	Continental	5127335AE/ 04727392AB		
1364	US	Dodge	Grand Caravan	2004/01-2005/12	315MHz	●	●	5	A	315Mhz	Continental	5127335AE/ 04727392AB		
1361	US	Dodge	Grand Caravan	2002/01-2003/12	433MHz	●	●	4	S	433Mhz	Schrader	52088990AC/ 52088990AD		52088990AD/ 52088990AC
1362	US	Dodge	Grand Caravan	2002/01-2003/12	433MHz	●	●	5	S	433Mhz	Schrader	52088990AC/ 52088990AD		52088990AD/ 52088990AC
1373	US	Dodge	Intrepid	2002/01-2004/12	433MHz	●	●	4	A	433Mhz	Schrader	52088990AC/ 52088990AD		52088990AD/ 52088990AC
1374	US	Dodge	Intrepid	2002/01-2004/12	433MHz	●	●	5	A	433Mhz	Schrader	52088990AC/ 52088990AD		52088990AD/ 52088990AC
1380	US	Dodge	Journey	2011/01-2015/12	433MHz	●	●	4	A	433Mhz	Schrader	56029398AB/ 56029398AA		56029398AB/ 56029398AA
1381	US	Dodge	Journey	2011/01-2015/12	433MHz	●	●	5	A	433Mhz	Schrader	56029398AB/ 56029398AA		56029398AB/ 56029398AA
1377	US	Dodge	Journey	2010/01-2010/12	Lo Line	●	●	4	A	433Mhz	Continental	68001698AB/ 68078768AA		
1378	US	Dodge	Journey	2010/01-2010/12	Lo Line	●	●	5	A	433Mhz	Continental	68001698AB/ 68078768AA		
1375	US	Dodge	Journey	2009/01-2009/12	433MHz	●	●	4	A	433Mhz	Continental	68001698AB/ 68078768AA		
1376	US	Dodge	Journey	2009/01-2009/12	433MHz	●	●	5	A	433Mhz	Continental	68001698AB/ 68078768AA		
1392	US	Dodge	Magnum	2011/01-2011/12	433MHz	●	●	4	A	433Mhz	Schrader	56029398AB/ 56029398AA		56029398AB/ 56029398AA
1393	US	Dodge	Magnum	2011/01-2011/12	433MHz	●	●	5	A	433Mhz	Schrader	56029398AB/ 56029398AA		56029398AB/ 56029398AA
1390	US	Dodge	Magnum	2010/01-2010/12	433MHz	●	●	4	A	433Mhz	Schrader	56029398AB/ 56029398AA		56029398AB/ 56029398AA
1391	US	Dodge	Magnum	2010/01-2010/12	433MHz	●	●	5	A	433Mhz	Schrader	56029398AB/ 56029398AA		56029398AB/ 56029398AA

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
1388	US	Dodge	Magnum	2009/01-2009/12	433MHz	●	●	4	A	433Mhz	Schrader	56029400AE/ 56029400AD/ 56029400AC/ 56029400AB		56029400AE/ 56029400AD/ 56029400AC/ 56029400AB
1389	US	Dodge	Magnum	2009/01-2009/12	433MHz	●	●	5	A	433Mhz	Schrader	56029400AE/ 56029400AD/ 56029400AC/ 56029400AB		56029400AE/ 56029400AD/ 56029400AC/ 56029400AB
1386	US	Dodge	Magnum	2008/01-2008/12	433MHz	●	●	4	A	433Mhz	Continental	68078768AA		
1387	US	Dodge	Magnum	2008/01-2008/12	433MHz	●	●	5	A	433Mhz	Continental	68078768AA		
1384	US	Dodge	Magnum	2007/01-2007/12	315MHz	●	●	4	A	315Mhz	Continental	68001696AB		
1385	US	Dodge	Magnum	2007/01-2007/12	315MHz	●	●	5	A	315Mhz	Continental	68001696AB		
1382	US	Dodge	Magnum	2005/01-2006/12	315MHz	●	●	4	A	315Mhz	Continental	56053030ABAC		
1383	US	Dodge	Magnum	2005/01-2006/12	315MHz	●	●	5	A	315Mhz	Continental	56053030ABAC		
1398	US	Dodge	Nitro	2012/01-2012/12	315MHz	●	●	4	A	315Mhz	Schrader	56029465AB		56029465AB
1399	US	Dodge	Nitro	2012/01-2012/12	315MHz	●	●	5	A	315Mhz	Schrader	56029465AB		56029465AB
1396	US	Dodge	Nitro	2009/01-2011/12	315MHz	●	●	4	A	315Mhz	Schrader	56029465AB		56029465AB
1397	US	Dodge	Nitro	2009/01-2011/12	315MHz	●	●	5	A	315Mhz	Schrader	56029465AB		56029465AB
1394	US	Dodge	Nitro	2007/01-2008/12	315MHz	●	●	4	A	315Mhz	Continental	56053030ABAC		
1395	US	Dodge	Nitro	2007/01-2008/12	315MHz	●	●	5	A	315Mhz	Continental	56053030ABAC		
1400	US	Dodge	Raider	2006/01-2009/12	315MHz	●	●	4	A	315Mhz	Schrader	56029319AC		56029319AC
1401	US	Dodge	Raider	2006/01-2009/12	315MHz	●	●	5	A	315Mhz	Schrader	56029319AC		56029319AC
1412	US	Dodge	Ram	2014/01-2015/12	433MHz	●	●	4	A	433Mhz	TRW	68239720AB/ 68239720AA/ 68157568AB	231008-109/ 231008-109/ 231008-101	231008-109/ 231008-109/ 231008-101
1413	US	Dodge	Ram	2014/01-2015/12	433MHz	●	●	5	A	433Mhz	TRW	68239720AB/ 68239720AA/ 68157568AB	231008-109/ 231008-109/ 231008-101	231008-109/ 231008-109/ 231008-101
1410	US	Dodge	Ram	2011/01-2013/12	433MHz	●	●	4	A	433Mhz	Schrader	56029398AB/ 56029398AA		56029398AB/ 56029398AA
1411	US	Dodge	Ram	2011/01-2013/12	433MHz	●	●	5	A	433Mhz	Schrader	56029398AB/ 56029398AA		56029398AB/ 56029398AA
1408	US	Dodge	Ram	2010/01-2010/12	433MHz	●	●	4	A	433Mhz	Schrader	56029398AB/ 56029398AA		56029398AB/ 56029398AA
1409	US	Dodge	Ram	2010/01-2010/12	433MHz	●	●	5	A	433Mhz	Schrader	56029398AB/ 56029398AA		56029398AB/ 56029398AA
1404	US	Dodge	Ram	2009/01-2009/12	315MHz	●	●	4	A	315Mhz	Schrader	56029319AC/ 56029319AB/ 56029319AA		56029319AC/ 56029319AB/ 56029319AA
1405	US	Dodge	Ram	2009/01-2009/12	315MHz	●	●	5	A	315Mhz	Schrader	56029319AC/ 56029319AB/ 56029319AA		56029319AC/ 56029319AB/ 56029319AA
1406	US	Dodge	Ram	2009/01-2009/12	433MHz	●	●	4	A	433Mhz	Schrader	56029359AC/ 56029359AB/ 56029359AA		56029359AC/ 56029359AB/ 56029359AA
1407	US	Dodge	Ram	2009/01-2009/12	433MHz	●	●	5	A	433Mhz	Schrader	56029359AC/ 56029359AB/ 56029359AA		56029359AC/ 56029359AB/ 56029359AA
1402	US	Dodge	Ram	2008/01-2008/12	315MHz	●	●	4	A	315Mhz	Schrader	56029319AC/ 56029319AB/ 56029319AA		56029319AC/ 56029319AB/ 56029319AA

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
1403	US	Dodge	Ram	2008/01-2008/12	315MHz	●	●	5	A	315Mhz	Schrader	56029319AC/ 56029319AB/ 56029319AA		56029319AC/ 56029319AB/ 56029319AA
1414	US	Dodge	Ram 2500	2009/01-2009/12	315MHz	●	●	4	A	315Mhz	Schrader	56029319AC/ 56029319AB/ 56029319AA		56029319AC/ 56029319AB/ 56029319AA
1415	US	Dodge	Ram 2500	2009/01-2009/12	315MHz	●	●	5	A	315Mhz	Schrader	56029319AC/ 56029319AB/ 56029319AA		56029319AC/ 56029319AB/ 56029319AA
1417	US	Dodge	Sprinter	2007/01-2013/12	315MHz	●	●	4	A	315Mhz	Continental	68006771AA/ 68038945AA		
1418	US	Dodge	Sprinter	2007/01-2013/12	315MHz	●	●	5	A	315Mhz	Continental	68006771AA/ 68038945AA		
1419	US	Dodge	Stratus	2007/01-2007/12	315MHz	●	●	4	A	315Mhz	Continental	56053030ABAC		
1420	US	Dodge	Stratus	2007/01-2007/12	315MHz	●	●	5	A	315Mhz	Continental	56053030ABAC		
1423	US	Dodge	viper	2013/01-2015/12	433MHz	●	●	4	A	433Mhz	Schrader	56029400AE/ 56029400AD/ 56029400AC/ 56029400AB		56029400AE/ 56029400AD/ 56029400AC/ 56029400AB
1424	US	Dodge	viper	2013/01-2015/12	433MHz	●	●	5	A	433Mhz	Schrader	56029400AE/ 56029400AD/ 56029400AC/ 56029400AB		56029400AE/ 56029400AD/ 56029400AC/ 56029400AB
1421	US	Dodge	Viper	2003/01-2011/12	433MHz	●	●	4	O	433Mhz	Schrader	52088990AC/ 52088990AD		52088990AD/ 52088990AC
1422	US	Dodge	Viper	2003/01-2011/12	433MHz	●	●	5	O	433Mhz	Schrader	52088990AC/ 52088990AD		52088990AD/ 52088990AC
1426	US	Ferrari	550 Maranello	2010/01-2012/12	433MHz	○	●	4		433Mhz	Huf/Beru	224549	0532207001	RDE001
1425	US	Ferrari	599	2004/01-2011/12	433MHz	○	●	4	S	433Mhz	Huf/Beru	224549	0532207001	RDE001
1427	US	Ferrari	612 Scaglietti	2004/01-2011/12	433MHz	○	●	4	A	433Mhz	Huf/Beru	224549	0532207001	RDE001
1428	US	Ferrari	California	2000/01-2012/12	433MHz	○	●	4	A	433Mhz	Huf/Beru	228887	0532207011	RDE011
1429	US	Ferrari	Enzo	2003/01-2003/12	433MHz	○	●	4	A	433Mhz	Huf/Beru	224551	0532207005	RDE005
1430	US	Ferrari	Spider	2002/01-2009/12	433MHz	○	●	4	A	433Mhz	Huf/Beru	224549	0532207001	RDE001
1431	US	Fiat	500	2011/01-2015/12	433MHz	○	●	4	A	433Mhz	Schrader	56029398AB/ 56029398AA		56029398AB/ 56029398AA
1433	US	Ford	C-Max	2012/01-2015/12	315MHz	○	●	4	S	315Mhz	Schrader	CM5T1A180AA		CM5T-1A180-AA
1439	US	Ford	Crown Victoria	2011/01-2011/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
1438	US	Ford	Crown Victoria	2010/01-2010/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
1437	US	Ford	Crown Victoria	2009/01-2009/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
1436	US	Ford	Crown Victoria	2008/01-2008/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
1435	US	Ford	Crown Victoria	2007/01-2007/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
1434	US	Ford	Crown Victoria	2006/01-2006/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
1443	US	Ford	E-150	2010/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	9L3Z1A189A		9L3Z-1A189-A
1442	US	Ford	E-150	2009/01-2009/12	315MHz	●	●	4	S	315Mhz	Lear	8C2Z1A189A		
1441	US	Ford	E-150	2008/01-2008/12	315MHz	●	●	4	S	315Mhz	Lear	8C2Z1A189A		
1440	US	Ford	E-150	2007/01-2007/12	315MHz	●	●	4	S	315Mhz	Lear	8C2Z1A189A		
1447	US	Ford	E-250	2010/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	9L3Z1A189A		9L3Z-1A189-A
1446	US	Ford	E-250	2009/01-2009/12	315MHz	●	●	4	S	315Mhz	Lear	8C2Z1A189A		
1445	US	Ford	E-250	2008/01-2008/12	315MHz	●	●	4	S	315Mhz	Lear	8C2Z1A189A		
1444	US	Ford	E-250	2007/01-2007/12	315MHz	●	●	4	S	315Mhz	Lear	8C2Z1A189A		

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, 0=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
1451	US	Ford	E-350 SD	2010/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	9L3Z1A189A		9L3Z-1A189-A
1450	US	Ford	E-350 SD	2009/01-2009/12	315MHz	●	●	4	S	315Mhz	Lear	8C2Z1A189A		
1449	US	Ford	E-350 SD	2008/01-2008/12	315MHz	●	●	4	S	315Mhz	Lear	8C2Z1A189A		
1448	US	Ford	E-350 SD	2007/01-2007/12	315MHz	●	●	4	S	315Mhz	Lear	8C2Z1A189A		
1457	US	Ford	Edge	2015/01-2015/12	315MHz	○	●	4	A	315Mhz	Schrader	F2GT1A180AB		F2GT1A180AB
1456	US	Ford	Edge	2013/01-2014/12	315MHz	●	●	4	S	315Mhz	Schrader	CM5T1A180AA		CM5T-1A180-AA
1455	US	Ford	Edge	2012/01-2012/12	315MHz	●	●	4	S	315Mhz	Schrader	CM5T1A180AA		CM5T-1A180-AA
1454	US	Ford	Edge	2011/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	9L3Z1A189A		9L3Z-1A189-A
1452	US	Ford	Edge	2007/01-2010/12	with Chrome rims	●	●	4	S	315Mhz	Continental	7L1Z1A189A		
1453	US	Ford	Edge	2007/01-2010/12	no Chrome rims	●	●	4	S	315Mhz	Continental	7L1Z1A189A		
1466	US	Ford	Escape	2013/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	CM5T1A180AA		CM5T-1A180-AA
1465	US	Ford	Escape	2012/01-2012/12	315MHz	●	●	4	S	315Mhz	Schrader	CM5T1A180AA		CM5T-1A180-AA
1464	US	Ford	Escape	2011/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	9L3Z1A189A		9L3Z-1A189-A
1463	US	Ford	Escape	2010/01-2010/12	315MHz	●	●	4	S	315Mhz	Schrader	9L3Z1A189A		9L3Z-1A189-A
1462	US	Ford	Escape	2009/01-2009/12	315MHz	●	●	4	S	315Mhz	Schrader	9L3Z1A189A		9L3Z-1A189-A
1461	US	Ford	Escape	2008/01-2008/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
1460	US	Ford	Escape	2007/01-2007/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
1459	US	Ford	Escape	2006/01-2006/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
1458	US	Ford	Escape	2005/01-2005/12	315MHz	○	●	4	S	315Mhz	Lear	6F2Z1A189A		
1479	US	Ford	Expedition	2012/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	CM5T1A180AA		CM5T-1A180-AA
1478	US	Ford	Expedition	2011/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	9L3Z1A189A		9L3Z-1A189-A
1476	US	Ford	Expedition	2010/01-2010/12	with Chrome rims	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
1477	US	Ford	Expedition	2010/01-2010/12	no Chrome rims	●	●	4	S	315Mhz	Continental	7L1Z1A189A		
1474	US	Ford	Expedition	2009/01-2009/12	with Chrome rims	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
1475	US	Ford	Expedition	2009/01-2009/12	no Chrome rims	●	●	4	S	315Mhz	Continental	7L1Z1A189A		
1472	US	Ford	Expedition	2008/01-2008/12	with Chrome rims	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
1473	US	Ford	Expedition	2008/01-2008/12	no Chrome rims	●	●	4	S	315Mhz	Continental	7L1Z1A189A		
1470	US	Ford	Expedition	2007/01-2007/12	with Chrome rims	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
1471	US	Ford	Expedition	2007/01-2007/12	no Chrome rims	●	●	4	S	315Mhz	Continental	7L1Z1A189A		
1469	US	Ford	Expedition	2005/01-2006/12	315MHz	●	●	4	S	315Mhz	Schrader	5L7Z1A150AA		5L7Z-1A150-AA
1468	US	Ford	Expedition	2004/01-2004/12	433MHz	●	●	4	S	433Mhz	Schrader	4L2T1A150BA/ 4L2Z1A150BA		4L2T1A150BA/ 4L2Z1A150BA
1467	US	Ford	Expedition	2003/01-2003/12	433MHz	●	●	4	S	433Mhz	Schrader	4L2T1A150BA/ 4L2Z1A150BA		4L2T1A150BA/ 4L2Z1A150BA
1492	US	Ford	Explorer	2016/01-2016/12	315MHz	○	●	4	A	315Mhz	Schrader	F2GT1A180AB		F2GT1A180AB
1491	US	Ford	Explorer	2013/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	CM5T1A180AA		CM5T-1A180-AA
1490	US	Ford	Explorer	2012/01-2012/12	315MHz	●	●	4	S	315Mhz	Schrader	CM5T1A180AA		CM5T-1A180-AA
1489	US	Ford	Explorer	2011/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	9L3Z1A189A		9L3Z-1A189-A
1488	US	Ford	Explorer	2010/01-2010/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow: Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
1487	US	Ford	Explorer	2009/01-2009/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
1486	US	Ford	Explorer	2008/01-2008/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
1485	US	Ford	Explorer	2007/01-2007/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
1484	US	Ford	Explorer	2006/01-2006/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
1483	US	Ford	Explorer	2005/01-2005/12	433MHz	●	●	4	S	433Mhz	Schrader	4L2Z1A150BB/ 4L2Z1A150BA/ 4L2T1A150BA		4L2Z-1A150-BB/ 4L2Z-1A150-BA/ 4L2T-1A150-BA
1482	US	Ford	Explorer	2004/01-2004/12	433MHz	●	●	4	S	433Mhz	Schrader	4L2Z1A150BB/ 4L2Z1A150BA/ 4L2T1A150BA		4L2Z-1A150-BB/ 4L2Z-1A150-BA/ 4L2T-1A150-BA
1481	US	Ford	Explorer	2003/01-2003/12	433MHz	●	●	4	S	433Mhz	Schrader	4L2Z1A150BB/ 4L2Z1A150BA/ 4L2T1A150BA		4L2Z-1A150-BB/ 4L2Z-1A150-BA/ 4L2T-1A150-BA
1480	US	Ford	Explorer	2002/01-2002/12	433MHz	●	●	4	S	433Mhz	Schrader	4L2Z1A150BB/ 4L2Z1A150BA/ 4L2T1A150BA		4L2Z-1A150-BB/ 4L2Z-1A150-BA/ 4L2T-1A150-BA
1497	US	Ford	Explorer Sport Trac	2010/01-2010/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
1496	US	Ford	Explorer Sport Trac	2009/01-2009/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
1495	US	Ford	Explorer Sport Trac	2008/01-2008/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
1494	US	Ford	Explorer Sport Trac	2007/01-2007/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
1493	US	Ford	Explorer Sport Trac	2006/01-2006/12	315MHz	○	●	4	S	315Mhz	Lear	6F2Z1A189A		
1502	US	Ford	F-150	2015/01-2015/12	315MHz	○	●	4	S	315Mhz	Schrader	F2GT1A180AB		F2GT1A180AB
1501	US	Ford	F-150	2012/01-2014/12	315MHz	●	●	4	S	315Mhz	Schrader	CM5T1A180AA		CM5T-1A180-AA
1500	US	Ford	F-150	2011/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	9L3Z1A189A		9L3Z-1A189-A
1499	US	Ford	F-150	2009/01-2010/12	315MHz	●	●	4	S	315Mhz	Schrader	9L3Z1A189A		9L3Z-1A189-A
1498	US	Ford	F-150	2007/01-2008/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
1505	US	Ford	F-150 HD	2015/01-2015/12	315MHz	○	●	4	S	315Mhz	Schrader	F2GT1A180AB		F2GT1A180AB
1511	US	Ford	F-250 SD	2012/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	CM5T1A180AA		CM5T-1A180-AA
1510	US	Ford	F-250 SD	2010/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	9L3Z1A189A		9L3Z-1A189-A
1509	US	Ford	F-250 SD	2009/01-2009/12	315MHz	●	●	4	S	315Mhz	Lear	8C2Z1A189A		
1508	US	Ford	F-250 SD	2008/01-2008/12	315MHz	●	●	4	S	315Mhz	Lear	8C2Z1A189A		
1517	US	Ford	F-350 SD	2012/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	CM5T1A180AA		CM5T-1A180-AA
1516	US	Ford	F-350 SD	2010/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	9L3Z1A189A		9L3Z-1A189-A
1515	US	Ford	F-350 SD	2009/01-2009/12	315MHz	●	●	4	S	315Mhz	Lear	8C2Z1A189A		
1514	US	Ford	F-350 SD	2008/01-2008/12	315MHz	●	●	4	S	315Mhz	Lear	8C2Z1A189A		
1520	US	Ford	F-450/550	2012/01-2014/12	315MHz	○	●	4	S	315Mhz	Schrader	CM5T1A180AA		CM5T-1A180-AA
1519	US	Ford	F-450/550	2010/01-2011/12	315MHz	○	●	4	S	315Mhz	Schrader	9L3Z1A189A		9L3Z-1A189-A
1518	US	Ford	F-450/550	2008/01-2009/12	315MHz	○	●	4	S	315Mhz	Lear	8C2Z1A189A		
1521	US	Ford	Fiesta	2011/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	CM5T1A180AA		CM5T-1A180-AA
1523	US	Ford	Five Hundred	2008/01-2009/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
1522	US	Ford	Five Hundred	2006/01-2007/12	315MHz	○	●	4	S	315Mhz	Lear	6F2Z1A189A		
1527	US	Ford	Flex	2013/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	CM5T1A180AA		CM5T-1A180-AA
1526	US	Ford	Flex	2012/01-2012/12	315MHz	●	●	4	S	315Mhz	Schrader	CM5T1A180AA		CM5T-1A180-AA
1525	US	Ford	Flex	2011/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	9L3Z1A189A		9L3Z-1A189-A
1524	US	Ford	Flex	2009/01-2010/12	315MHz	●	●	4	S	315Mhz	Continental	7L1Z1A189A		
1531	US	Ford	Focus	2012/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	CM5T1A180AA		CM5T-1A180-AA
1530	US	Ford	Focus	2010/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	9L3Z1A189A		9L3Z-1A189-A

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow: Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, 0=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
1529	US	Ford	Focus	2008/01-2009/12	315MHz	●	●	4	S	315Mhz	Continental	7L1Z1A189A		
1528	US	Ford	Focus	2007/01-2007/12	315MHz	○	●	4	S	315Mhz	Lear	6F2Z1A189A		
1534	US	Ford	Freestar	2006/01-2007/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
1533	US	Ford	Freestar	2005/01-2005/12	315MHz	●	●	4	S	315Mhz	Schrader	5L7Z1A150AA		5L7Z-1A150-AA
1532	US	Ford	Freestar	2004/01-2004/12	315MHz	○	●	4	S	315Mhz	Schrader	5L7Z1A150AA		5L7Z-1A150-AA
1539	US	Ford	Fusion	2012/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	CM5T1A180AA		CM5T-1A180-AA
1538	US	Ford	Fusion	2010/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	9L3Z1A189A		9L3Z-1A189-A
1537	US	Ford	Fusion	2009/01-2009/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
1536	US	Ford	Fusion	2008/01-2008/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
1535	US	Ford	Fusion	2007/01-2007/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
1548	US	Ford	Mustang	2015/01-2015/12	315MHz	○	●	4	A	315Mhz	Schrader			F2GT1A180AB
1547	US	Ford	Mustang	2012/01-2014/12	315MHz	●	●	4	S	315Mhz	Schrader	CM5T1A180AA		CM5T-1A180-AA
1546	US	Ford	Mustang	2010/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	9L3Z1A189A		9L3Z-1A189-A
1545	US	Ford	Mustang	2009/01-2009/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
1544	US	Ford	Mustang	2008/01-2008/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
1543	US	Ford	Mustang	2007/01-2007/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
1550	US	Ford	Ranger	2008/01-2011/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
1549	US	Ford	Ranger	2007/01-2007/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
1552	US	Ford	Shelby GT	2013/01-2015/12	433MHz	○	●	4	A	433Mhz	Schrader	DR3V1A180BA		
1551	US	Ford	Shelby GT	2012/01-2012/12	315MHz	○	●	4	S	315Mhz	Schrader	CM5T1A180AA		CM5T-1A180-AA
1556	US	Ford	Taurus	2013/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	CM5T1A180AA		CM5T-1A180-AA
1555	US	Ford	Taurus	2012/01-2012/12	315MHz	●	●	4	S	315Mhz	Schrader	CM5T1A180AA		CM5T-1A180-AA
1554	US	Ford	Taurus	2011/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	9L3Z1A189A		9L3Z-1A189-A
1553	US	Ford	Taurus	2008/01-2010/12	315MHz	●	●	4	S	315Mhz	Continental	7L1Z1A189A		
1557	US	Ford	Taurus X	2008/01-2009/12	315MHz	●	●	4	S	315Mhz	Continental	7L1Z1A189A		
1559	US	Ford	Transit connect	2012/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	CM5T1A180AA		CM5T-1A180-AA
1558	US	Ford	Transit connect	2010/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	9L3Z1A189A		9L3Z-1A189-A
1561	US	GMC	Acadia	2009/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/ 20923680
1560	US	GMC	Acadia	2007/01-2008/12	315MHz	●	●	4	S	315Mhz	Continental	15921013	S120123009A	
1563	US	GMC	Canyon	2011/01-2012/12	315MHz	●	●	4	S	315Mhz	Schrader	15122618		15122618
1562	US	GMC	Canyon	2007/01-2010/12	315MHz	●	●	4	S	315Mhz	Schrader	15122618		15122618
1565	US	GMC	Envoy	2006/01-2006/12	315MHz	○	●	4	S	315Mhz	Schrader	25774006		25774006
1564	US	GMC	Envoy	2005/01-2005/12	315MHz	○	●	4	S	315Mhz	Schrader	25774006		25774006
1568	US	GMC	Envoy (NO. 15825475)	2007/01-2007/12		●	●	4	S	315Mhz	TRW	15825475		15825475
1569	US	GMC	Envoy (NO. 25774006)	2008/01-2009/12		●	●	4	S	315Mhz	Schrader	25774006		25774006
1566	US	GMC	Envoy (NO. 25774006)	2007/01-2007/12		●	●	4	S	315Mhz	Schrader	25774006		25774006
1570	US	GMC	Envoy (NO. 25920615)	2008/01-2009/12		●	●	4	S	315Mhz	Schrader	25920615		25920615
1567	US	GMC	Envoy (NO. 25920615)	2007/01-2007/12		●	●	4	S	315Mhz	Schrader	25920615		25920615
1572	US	GMC	Savana	2010/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/20923680
1571	US	GMC	Savana	2008/01-2009/12	315MHz	○	●	4	S	315Mhz	Continental	15921013	S120123009A	
1580	US	GMC	Sierra	2014/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	13581558		13581558
1579	US	GMC	Sierra	2009/01-2013/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615/ 20923680/ 13586335		25920615/ 20923680/ 13586335

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
1578	US	GMC	Sierra	2008/01-2008/12	TRW clamp in	●	●	4	S	315Mhz	Schrader	25920615/ 20923680/ 13586335		25920615/ 20923680/ 13586335
1575	US	GMC	Sierra	2007/01-2007/12		●	●	4	S	315Mhz	Schrader/TRW	15114379/ 20923680/ 25920615/ 15825475		15114379
1574	US	GMC	Sierra	2005/01-2006/12	315MHz	○	●	4	S	315Mhz	Schrader	15114379		15114379
1573	US	GMC	Sierra	2004/01-2004/12	315MHz	○	●	4	S	315Mhz	Schrader	15136883		15136883
1582	US	GMC	Terrain	2012/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	12768826/ 20922900/ 22854866		12768826/ 20922900/ 22854866
1581	US	GMC	Terrain	2010/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	12768826/ 20922900/ 22854866		12768826/ 20922900/ 22854866
1589	US	GMC	Yukon All	2014/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615/ 20923680/ 13586335		25920615/ 20923680/ 13586335
1588	US	GMC	Yukon All	2009/01-2013/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615/ 20923680/ 13586335		25920615/ 20923680/ 13586335
1587	US	GMC	Yukon All	2008/01-2008/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615/ 20923680/ 13586335		25920615/ 20923680/ 13586335
1585	US	GMC	Yukon All	2007/01-2007/12	Clamp in	●	●	4	S	315Mhz	TRW	15825475		
1586	US	GMC	Yukon All	2007/01-2007/12	Snap in	●	●	4	S	315Mhz	Schrader	20923680/ 25920615/ 13586335		20923680/ 25920615/ 13586335
1584	US	GMC	Yukon All	2005/01-2006/12	315MHz	○	●	4	S	315Mhz	Schrader	15114379		15114379
1583	US	GMC	Yukon All	2004/01-2004/12	315MHz	○	●	4	S	315Mhz	Schrader	15136883		15136883
1590	US	Honda	Accord	2008/01-2012/12	315MHz	●	●	4	0	315Mhz	Pacific	42753SWA316	PMV-107M	42753-SWA-316
1594	US	Honda	Civic	2014/01-2015/12	315MHz	●	●	4	S	315Mhz	TRW	42753TR3A81/ 42753SNAA83	225260-103/ 217652-109	225260-103/ 217652-109
1593	US	Honda	Civic	2012/01-2013/12	315MHz	●	●	4	0	315Mhz	TRW	42753TR3A81/ 42753TROA81/ 42753SNAA83	225260-103/ 217652-114/ 217652-109	225260-103/ 217652-114/ 217652-109
1592	US	Honda	Civic	2008/01-2011/12	315MHz	●	●	4	0	315Mhz	TRW	42753TR3A81/ 42753TROA81/ 42753SNAA83	225260-103/ 217652-114/ 217652-109	225260-103/ 217652-114/ 217652-109
1595	US	Honda	Crosstour	2010/01-2015/12	315MHz	●	●	4	0	315Mhz	Continental	42753TP6A82	S180052025E	S180052025
1599	US	Honda	CR-V	2015/01-2015/12	315MHz	●	●	4	S	315Mhz				
1598	US	Honda	CR-V	2012/01-2014/12	315MHz	●	●	4	0	315Mhz	Continental	42753TP6A82	S180052025E	S180052025
1596	US	Honda	CR-V	2007/01-2011/12	Alloy	●	●	4	0	315Mhz	Pacific	42753SWA316	PMV-107M	42753-SWA-316
1597	US	Honda	CR-V	2007/01-2011/12	Steel	●	●	4	0	315Mhz	Pacific	42753SWA315	PMV-107M	42753-SWA-315
1600	US	Honda	CR-Z	2011/01-2014/12	315MHz	●	●	4	0	315Mhz	TRW	42753SNAA83	217652-114	217652-114
1603	US	Honda	Element	2009/01-2011/12	315MHz	●	●	4	0	315Mhz	TRW	42753SNAA83	217652-114	217652-114
1602	US	Honda	Element	2008/01-2008/12	315MHz	●	●	4	0	315Mhz	TRW	42753SHJA82	217652-115	217652-115
1601	US	Honda	Element	2006/01-2007/12	315MHz	●	●	4	0	315Mhz	TRW	06421SCVA00		
1605	US	Honda	Fit	2009/01-2014/12	315MHz	●	●	4	0	315Mhz	TRW	42753SNAA83	217652-114	217652-114
1604	US	Honda	Fit	2008/01-2008/12	315MHz	●	●	4	0	315Mhz	Pacific	42753SWA316	PMV-107M	42753-SWA-316
1607	US	Honda	Insight	2010/01-2014/12	315MHz	●	●	4	0	315Mhz	TRW	42753SNAA83	217652-114	217652-114

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
1610	US	Honda	Odyssey	2011/01-2015/12	315MHz	●	●	4	0	315Mhz	TRW	42753SNAA83	217652-114	217652-114
1609	US	Honda	Odyssey	2008/01-2010/12	315MHz	●	●	4	0	315Mhz	TRW	42753SHJA82	217652-115	217652-115
1608	US	Honda	Odyssey	2006/01-2007/12	315MHz	●	●	4	0	315Mhz	TRW	06421SCVA00		
1613	US	Honda	Odyssey Touring	2011/01-2015/12	315MHz	●	●	4	A	315Mhz	TRW	42753SNAA83	217652-114	217652-114
1612	US	Honda	Odyssey Touring	2008/01-2010/12	315MHz	●	●	4	A	315Mhz	TRW	42753SHJA53	217652-116	217652-116
1611	US	Honda	Odyssey Touring	2005/01-2007/12	315MHz	●	●	4	A	315Mhz	TRW	06421S3VA04	218898-101	218898-101
1617	US	Honda	Pilot	2009/01-2015/12	Alloy	●	●	4	A	315Mhz	Pacific	42753STKA04	PMV-107G	42753-STK-A04
1618	US	Honda	Pilot	2009/01-2015/12	Steel	●	●	4	A	315Mhz	Pacific	42753STKA04	PMV-107G	42753-STK-A04
1616	US	Honda	Pilot	2006/01-2008/12	Alloy	●	●	4	A	315Mhz	TRW	06421S3VA04	218898-101	218898-101
1615	US	Honda	Pilot	2005/01-2008/12	Steel	●	●	4	A	315Mhz	TRW	06421S9VA03/ 06421S3VA04	218898-103/ 218898-101	218898-103/ 218898-101
1614	US	Honda	Pilot	2005/01-2005/12	Alloy	●	●	4	A	315Mhz	TRW	06421S3VA04	218898-101	218898-101
1619	US	Honda	Pilot Touring	2009/01-2015/12	315MHz	●	●	4	A	315Mhz	Pacific	42753STKA04	PMV-107G	42753-STK-A04
1622	US	Honda	Ridgeline	2009/01-2014/12	Alloy	●	●	4	A	315Mhz	TRW	42753SHJA53	217652-116	217652-116
1623	US	Honda	Ridgeline	2009/01-2014/12	Steel	●	●	4	A	315Mhz	TRW	06421S3VA04	218898-101	218898-101
1620	US	Honda	Ridgeline	2006/01-2008/12	Alloy	●	●	4	A	315Mhz	TRW	06421S3VA04	218898-101	218898-101
1621	US	Honda	Ridgeline	2006/01-2008/12	Steel	●	●	4	A	315Mhz	TRW	06421S9VA03/ 06421S3VA04	218898-103/ 218898-101	218898-103/ 218898-101
1624	US	Honda	Ridgeline RTL	2009/01-2013/12	315MHz	●	●	4	A	315Mhz	TRW	42753SHJA53	217652-116	217652-116
1625	US	Honda	S2000	2008/01-2009/12	315MHz	●	●	4	0	315Mhz	Pacific	42753S2A325/ 42753S2A315/ 42753S2A305	PMV-107M	42753-S2A-325/ 42753-S2A-315/ 42753-S2A-305
1628	US	Hummer	H2	2009/01-2010/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/ 20923680
1629	US	Hummer	H2	2009/01-2010/12	315MHz	●	●	5	S	315Mhz	Schrader	25920615/ 20923680		25920615/ 20923680
1626	US	Hummer	H2	2008/01-2008/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/ 20923680
1627	US	Hummer	H2	2008/01-2008/12	315MHz	●	●	5	S	315Mhz	Schrader	25920615/ 20923680		25920615/ 20923680
1632	US	Hummer	H3	2007/01-2010/12	315MHz	●	●	4	S	315Mhz	Schrader	20927604/ 15122618		15122618/ 20927604
1633	US	Hummer	H3	2007/01-2010/12	315MHz	●	●	5	S	315Mhz	Schrader	20927604/ 15122618		15122618/ 20927604
1630	US	Hummer	H3	2006/01-2006/12	315MHz	●	●	4	S	315Mhz	Schrader	20927604/ 15122618		15122618/ 20927604
1631	US	Hummer	H3	2006/01-2006/12	315MHz	●	●	5	S	315Mhz	Schrader	20927604/ 15122618		15122618/ 20927604
1634	US	Hummer	H3T	2006/01-2010/12	315MHz	○	●	4	S	315Mhz	Schrader	20927604/ 15122618		15122618/ 20927604
1635	US	Hummer	H3T	2006/01-2010/12	315MHz	○	●	5	S	315Mhz	Schrader	20927604/ 15122618		15122618/ 20927604
1637	US	Hyundai	Accent	2012/01-2015/12	315MHz	●	●	4	0	315Mhz	Continental	529332M000	S180052017G	S180052017
1636	US	Hyundai	Accent	2007/01-2011/12	315MHz	●	●	4	0	315Mhz	TRW	529332F000	216707-101	216707-101
1640	US	Hyundai	Azera	2014/01-2015/12	433MHz	●	●	4	0	433Mhz	TRW	529333V600	225816-104	225816-104
1638	US	Hyundai	Azera	2007/01-2011/12	315MHz	●	●	4	0	315Mhz	Lear	529332G200		52933-2G200
1642	US	Hyundai	Elantra	2011/01-2015/12	315MHz	●	●	4	0	315Mhz	TRW	529333X200	225816-101	225816-101
1641	US	Hyundai	Elantra	2007/01-2010/12	315MHz	●	●	4	0	315Mhz	Lear	529332G200		52933-2G200
1644	US	Hyundai	Elantra GT	2013/01-2015/12	315MHz	●	●	4	0	315Mhz	Continental	52933A5000	S180052041F	S180052041
1645	US	Hyundai	Elantra Touring	2009/01-2012/12	315MHz	●	●	4	0	315Mhz	Continental	529332M000	S180052017G	S180052017

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, 0=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
1647	US	Hyundai	Entourage	2009/01-2010/12	315MHz	●	●	4	0	315Mhz	Lear	529334D800/ 529334D200/ 529334D000		52933-4D800/ 52933-4D200/ 52933-4D000
1646	US	Hyundai	Entourage	2007/01-2008/12	315MHz	●	●	4	0	315Mhz	Lear	529334D800/ 529334D200/ 529334D000		52933-4D800/ 52933-4D200/ 52933-4D000
1648	US	Hyundai	Equus	2011/01-2014/12	315MHz	●	●	4	0	315Mhz	TRW	529332F000	216707-101	216707-101
1651	US	Hyundai	Genesis Coupe	2013/01-2015/12	315MHz	●	●	4	0	315Mhz	Continental	52933A5000	S180052041F	S180052041
1650	US	Hyundai	Genesis Coupe	2010/01-2012/12	315MHz	●	●	4	0	315Mhz	Continental	529332M000	S180052017G	S180052017
1653	US	Hyundai	Genesis Sedan	2015/01-2015/12	433MHz	●	●	4	0	433Mhz	Continental	529333N100	S180052092Z	S180052092
1652	US	Hyundai	Genesis Sedan	2009/01-2014/12	315MHz	●	●	4	0	315Mhz	TRW	529332F000	216707-101	216707-101
1659	US	Hyundai	Santa Fe	2013/01-2014/12	315MHz	●	●	4	0	315Mhz	Continental	52933A5000	S180052041F	S180052041
1658	US	Hyundai	Santa Fe	2010/01-2012/12	315MHz	●	●	4	0	315Mhz	Lear	529330W100		52933-0W100
1657	US	Hyundai	Santa Fe	2009/01-2009/12	315MHz	●	●	4	0	315Mhz	Lear	529332G200		52933-2G200
1655	US	Hyundai	Santa Fe	2008/01-2008/12	Hi line	●	●	4	0	315Mhz	Lear	529334D800/ 529334D200/ 529334D000		52933-4D800/ 52933-4D200/ 52933-4D000
1656	US	Hyundai	Santa Fe	2008/01-2008/12	Lo Line	●	●	4	0	315Mhz	Lear	529332G200		52933-2G200
1654	US	Hyundai	Santa Fe	2007/01-2007/12	315MHz	●	●	4	0	315Mhz	Lear	529334D800/ 529334D200/ 529334D000		52933-4D800/ 52933-4D200/ 52933-4D000
1661	US	Hyundai	Santa Fe Sport	2013/01-2015/12	315MHz	●	●	4	0	315Mhz	Continental	529333N000/ 529332M550	S180052091C	S180052091
1663	US	Hyundai	Sonata	2008/01-2008/12	AM Lo Line	●	●	4	0	315Mhz	TRW	529333E000		
1664	US	Hyundai	Sonata	2008/01-2008/12	FM Lo Line	●	●	4	0	315Mhz	TRW	529332F000	216707-101	216707-101
1662	US	Hyundai	Sonata	2006/01-2007/12	Lo Line	●	●	4	0	315Mhz	TRW	529333E000		
1671	US	Hyundai	Tiburon	2008/01-2008/12	Lo Line	●	●	4	0	315Mhz	TRW	529333E000		
1670	US	Hyundai	Tiburon	2007/01-2007/12	Lo Line	●	●	4	0	315Mhz	TRW	529333E000		
1674	US	Hyundai	Tucson	2010/01-2015/12	Lo Line	●	●	4	0	315Mhz	TRW	529332F000	216707-101	216707-101
1673	US	Hyundai	Tucson	2008/01-2009/12	Lo Line	●	●	4	0	315Mhz	TRW	529333E000		
1672	US	Hyundai	Tucson	2006/01-2007/12	Lo Line	●	●	4	0	315Mhz	TRW	529333E000/ 529331F000		
1676	US	Hyundai	Veloster	2013/01-2015/12	315MHz	●	●	4	0	315Mhz	Schrader	529332V000		52933-2V000
1675	US	Hyundai	Veloster	2012/01-2012/12	315MHz	●	●	4	0	315Mhz	Schrader	529332V000		52933-2V000
1682	US	Hyundai	Veracruz	2013/01-2013/12	Lo Line	●	●	4	0	315Mhz	TRW	529332F000	216707-101	216707-101
1681	US	Hyundai	Veracruz	2009/01-2012/12	315MHz	●	●	4	0	315Mhz	Lear	529332G200		52933-2G200
1679	US	Hyundai	Veracruz	2008/01-2008/12	Hi line	●	●	4	0	315Mhz	Lear	529334D800/ 529334D200/ 529334D000		52933-4D800/ 52933-4D200/ 52933-4D000
1680	US	Hyundai	Veracruz	2008/01-2008/12	Lo Line	●	●	4	0	315Mhz	Lear	529332G200		52933-2G200
1678	US	Hyundai	Veracruz	2007/01-2007/12	315MHz	●	●	4	0	315Mhz	Lear	529334D800/ 529334D200/ 529334D000		52933-4D800/ 52933-4D200/ 52933-4D000
1677	US	Hyundai	Veracruz	2006/01-2006/12	315MHz	●	●	4	0	315Mhz	Lear	529334D800/ 529334D200/ 529334D000		52933-4D800/ 52933-4D200/ 52933-4D000
1685	US	Infiniti	EX35	2010/05-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	407001LA0E/ 407001LA0C	PMV-C811/ PMV-107S	40700-1LA0E/ 40700-1LA0C
1684	US	Infiniti	EX35	2009/01-2010/04	315MHz	●	●	4	0	315Mhz	Pacific	40700JK00C	PMV-107L	40700-JK00C
1683	US	Infiniti	EX35	2008/01-2008/12	315MHz	●	●	4	0	315Mhz	Schrader	40700CD001		40700-CD001

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
1686	US	Infiniti	EX37	2013/01-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	407001LA0E/ 407001LA0C	PMV-C811/ PMV-107S	40700-1LA0E/ 40700-1LA0C
1689	US	Infiniti	FX35	2010/05-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	407001LA0E/ 407001LA0C	PMV-C811/ PMV-107S	40700-1LA0E/ 40700-1LA0C
1688	US	Infiniti	FX35	2009/01-2010/04	315MHz	●	●	4	0	315Mhz	Pacific	40700JK01B/ 40700JK00B/ 40700JK00C	PMV-C813/ PMV-107L/ PMV-107L	40700-JK01B/ 40700-JK00B/ 40700-JK00C
1687	US	Infiniti	FX35	2003/01-2008/12	315MHz	●	●	4	0	315Mhz	Schrader	40700CD001		40700-CD001
1690	US	Infiniti	FX37	2013/01-2013/12	315MHz	●	●	4	0	315Mhz	Pacific	407001LA0E/ 407001LA0C	PMV-C811/ PMV-107S	40700-1LA0E/ 40700-1LA0C
1691	US	Infiniti	FX45	2003/01-2008/12	315MHz	●	●	4	0	315Mhz	Schrader	40700CD001		40700-CD001
1693	US	Infiniti	FX50	2010/05-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	407001LA0E/ 407001LA0C	PMV-C811/ PMV-107S	40700-1LA0E/ 40700-1LA0C
1692	US	Infiniti	FX50	2009/01-2010/04	315MHz	●	●	4	0	315Mhz	Pacific	40700JK01B/ 40700JK00B/ 40700JK00C	PMV-C813/ PMV-107L/ PMV-107L	40700-JK01B/ 40700-JK00B/ 40700-JK00C
1694	US	Infiniti	G25	2011/01-2013/12	315MHz	●	●	4	0	315Mhz	Pacific	407001LA0E/ 407001LA0C	PMV-C811/ PMV-107S	40700-1LA0E/ 40700-1LA0C
1697	US	Infiniti	G35	2008/01-2008/12	315MHz	●	●	4	0	315Mhz	Pacific	40700JK00C	PMV-107L	40700-JK00C
1696	US	Infiniti	G35	2007/01-2007/12	315MHz	●	○	4	0	315Mhz	Schrader	40700JA01B		40700-JA01B
1695	US	Infiniti	G35	2003/01-2006/12	315MHz	●	●	4	0	315Mhz	Schrader	40700CD001		40700-CD001
1699	US	Infiniti	G37	2010/05-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	407001LA0E/ 407001LA0C	PMV-C811/ PMV-107S	40700-1LA0E/ 40700-1LA0C
1698	US	Infiniti	G37	2008/01-2010/04	315MHz	●	●	4	0	315Mhz	Pacific	40700JK01B/ 40700JK00B/ 40700JK00C	PMV-C813/ PMV-107L/ PMV-107L	40700-JK01B/ 40700-JK00B/ 40700-JK00C
1700	US	Infiniti	JX35	2013/01-2015/12	433MHz	●	●	4	0	433Mhz	Continental	407003JA0A	S180052036Z	S180052036
1702	US	Infiniti	M35	2009/01-2012/12	315MHz	●	●	4	0	315Mhz	Schrader	40700JA01C		40700-JA01C
1701	US	Infiniti	M35	2006/01-2008/12	315MHz	●	●	4	0	315Mhz	Schrader	40700CD001		40700-CD001
1703	US	Infiniti	M35h	2012/01-2012/12	315MHz	●	●	4	0	315Mhz	Pacific	407001LA0E/ 407001LA0A/ 407001LA0C	PMV-C811/ PMV-107S/ PMV-107S	40700-1LA0E/ 40700-1LA0A/ 40700-1LA0C
1704	US	Infiniti	M37	2011/01-2013/12	315MHz	●	●	4	0	315Mhz	Pacific	407001LA0E/ 407001LA0C	PMV-C811/ PMV-107S	40700-1LA0E/ 40700-1LA0C
1706	US	Infiniti	M45	2009/01-2010/12	315MHz	●	●	4	0	315Mhz	Schrader	40700JA01C		40700-JA01C
1705	US	Infiniti	M45	2003/01-2008/12	315MHz	●	●	4	0	315Mhz	Schrader	40700CD001		40700-CD001
1707	US	Infiniti	M56	2011/01-2013/12	315MHz	●	●	4	0	315Mhz	Pacific	407001LA0E/ 407001LA0C	PMV-C811/ PMV-107S	40700-1LA0E/ 40700-1LA0C
1708	US	Infiniti	Q25	2011/01-2012/12	315MHz	○	●	4	0	315Mhz	Pacific	407001LA0E	PMV-C811	407001LA0E
1709	US	Infiniti	Q40	2014/01-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	407001LA0E/ 407001LA0A/ 407001LA0C	PMV-C811/ PMV-107S/ PMV-107S	40700-1LA0E/ 40700-1LA0A/ 40700-1LA0C
1711	US	Infiniti	Q45	2006/08-2013/12	315MHz	●	○	4	0	315Mhz	Schrader	40700JA01B		40700-JA01B
1710	US	Infiniti	Q45	2003/01-2006/07	315MHz	●	●	4	0	315Mhz	Schrader	40700CD001		40700-CD001
1712	US	Infiniti	Q50	2014/01-2015/12	315MHz	●	○	4	0	315Mhz	Continental	407004GA0A	S180052037C	S180052037
1713	US	Infiniti	Q60	2014/01-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	407001LA0E/ 407001LA0C	PMV-C811/ PMV-107S	40700-1LA0E/ 40700-1LA0C
1714	US	Infiniti	Q70	2014/01-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	407001LA0E/ 407001LA0C	PMV-C811/ PMV-107S	40700-1LA0E/ 40700-1LA0C
1715	US	Infiniti	QX4	2003/01-2004/12	315MHz	●	●	4	0	315Mhz	Schrader	40700CD001		40700-CD001

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
1716	US	Infiniti	QX50	2014/01-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	407001LA0E/ 407001LA0C	PMV-C811/ PMV-107S	40700-1LA0E/ 40700-1LA0C
1722	US	Infiniti	QX56	2011/01-2015/12	315MHz	●	●	4	S	315Mhz	Pacific	407001LA0E/ 407001LA0A/ 407001LA0C	PMV-C811/ PMV-107S/ PMV-107S	40700-1LA0E/ 40700-1LA0A/ 40700-1LA0C
1721	US	Infiniti	QX56	2008/01-2010/12	315MHz	●	●	4	0	315Mhz	Schrader	40700JA01B		40700-JA01B
1720	US	Infiniti	QX56	2007/01-2007/12	315MHz	●	●	4	0	315Mhz	Schrader	40700CK002		40700-CK002
1718	US	Infiniti	QX56	2005/01-2006/12	Alloy	●	●	4	0	315Mhz	Schrader	40700CK001		40700-CK001
1719	US	Infiniti	QX56	2005/01-2006/12	Steel	●	●	4	0	315Mhz	Schrader	40700CK002		40700-CK002
1717	US	Infiniti	QX56	2004/01-2004/12	315MHz	●	●	4	0	315Mhz	Schrader	40700CK002		40700-CK002
1723	US	Infiniti	QX60	2014/01-2015/12	433MHz	●	●	4	0	433Mhz	Continental	407003JA0A	S180052036Z	S180052036
1724	US	Infiniti	QX70	2014/01-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	407001LA0E/ 407001LA0C	PMV-C811/ PMV-107S	40700-1LA0E/ 40700-1LA0C
1725	US	Infiniti	QX80	2011/01-2015/12	315MHz	●	●	4	S	315Mhz	Pacific	407001LA0E/ 407001LA0C	PMV-C811/ PMV-107S	40700-1LA0E/ 40700-1LA0C
1726	US	Isuzu	Ascender	2006/01-2008/12	315MHz	○	●	4	S	315Mhz	Schrader	25774006		25774006
1727	US	Isuzu	i-290	2007/01-2011/12	315MHz	○	●	4	S	315Mhz	Schrader	15122618		15122618
1728	US	Isuzu	i-370	2007/01-2011/12	315MHz	○	●	4	S	315Mhz	Schrader	15122618		15122618
1729	US	Isuzu	Rodeo	2004/01-2004/12	433MHz	○	●	4	S	433Mhz	Schrader	52088990AC/ 52088990AD		52088990AC/ 52088990AD
1732	US	Jaguar	S Type	2008/01-2010/12	315MHz	○	●	4	A	315Mhz	Continental	XR855950		
1730	US	Jaguar	S Type	2005/01-2007/12	315MHz	○	●	4	A	315Mhz	Continental	C2Z15017		
1731	US	Jaguar	S Type	2005/01-2007/12	433MHz	○	●	4	A	433Mhz	Continental	C2Z15016	S180084770Z	S180052022
1733	US	Jaguar	X Type	2007/01-2011/12	315MHz	○	●	4	A	315Mhz	Continental	XR855950		
1736	US	Jaguar	XF	2010/01-2015/12	433MHz	●	●	4	A	433Mhz	Continental	C2Z15016	S180084770Z	S180052022
1737	US	Jaguar	XF	2010/01-2015/12	315MHz	●	●	4	A	315Mhz	Continental	C2Z15017		
1734	US	Jaguar	XF	2009/01-2009/12	315MHz	●	●	4	A	315Mhz	Continental	C2Z15017		
1735	US	Jaguar	XF	2009/01-2009/12	433MHz	●	●	4	A	433Mhz	Continental	C2Z15016	S180084770Z	S180052022
1738	US	Jaguar	XJ	2004/01-2011/12	315MHz	○	●	4	A	315Mhz	Continental	C2Z15017/ XR855950		
1739	US	Jaguar	XJ	2004/01-2011/12	433MHz	○	●	4	A	433Mhz	Continental	C2Z15016/ XR855949	S180084770Z	S180052022
1740	US	Jaguar	XJR	2006/01-2015/12	315MHz	○	●	4	A	315Mhz	Continental	XR855950		
1743	US	Jaguar	XK	2010/01-2015/12	315MHz	●	●	4	A	315Mhz	Continental	XR855950		
1744	US	Jaguar	XK	2010/01-2015/12	433MHz	●	●	4	A	433Mhz	Continental	XR855949		
1741	US	Jaguar	XK	2006/01-2009/12	315MHz	●	●	4	A	315Mhz	Continental	XR855950		
1742	US	Jaguar	XK	2006/01-2009/12	433MHz	●	●	4	A	433Mhz	Continental	XR855949		
1746	US	Jaguar	XKR	2010/01-2014/12	315MHz	●	●	4	A	315Mhz	Continental	XR855950		
1745	US	Jaguar	XKR	2007/01-2009/12	315MHz	●	●	4	A	315Mhz	Continental	XR855950		
1747	US	Jeep	Cherokee	2014/01-2015/12	433MHz	●	●	4	A	433Mhz	TRW	68239720AA/ 68157568AB	231008-109/ 231008-101	231008-109/ 231008-101
1748	US	Jeep	Cherokee	2014/01-2015/12	433MHz	●	●	5	A	433Mhz	TRW	68239720AA/ 68157568AB	231008-109/ 231008-101	231008-109/ 231008-101
1753	US	Jeep	Commander	2008/01-2011/12	433MHz	●	●	4	A	433Mhz	Schrader	56029359AC/ 56029359AB/ 56029359AA		56029359AC/ 56029359AB/ 56029359AA
1754	US	Jeep	Commander	2008/01-2011/12	433MHz	●	●	5	A	433Mhz	Schrader	56029359AC/ 56029359AB/ 56029359AA		56029359AC/ 56029359AB/ 56029359AA

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
1751	US	Jeep	Commander	2007/01-2007/12	315MHz	●	●	4	A	315Mhz	Schrader	56053036AA		56053036AA
1752	US	Jeep	Commander	2007/01-2007/12	315MHz	●	●	5	A	315Mhz	Schrader	56053036AA		56053036AA
1749	US	Jeep	Commander	2006/01-2006/12	315MHz	●	●	4	A	315Mhz	Continental	56053030AC		
1750	US	Jeep	Commander	2006/01-2006/12	315MHz	●	●	5	A	315Mhz	Continental	56053030AC		
1761	US	Jeep	Compass	2011/01-2015/12	315MHz	●	●	4	A	315Mhz	Continental	68001696AAAB		
1762	US	Jeep	Compass	2011/01-2015/12	315MHz	●	●	5	A	315Mhz	Continental	68001696AAAB		
1759	US	Jeep	Compass	2010/01-2010/12	315MHz	●	●	4	A	315Mhz	Continental	68001696AAAB		
1760	US	Jeep	Compass	2010/01-2010/12	315MHz	●	●	5	A	315Mhz	Continental	68001696AAAB		
1757	US	Jeep	Compass	2008/01-2009/12	315MHz	●	●	4	A	315Mhz	Continental	68001696AAAB		
1758	US	Jeep	Compass	2008/01-2009/12	315MHz	●	●	5	A	315Mhz	Continental	68001696AAAB		
1755	US	Jeep	Compass	2007/01-2007/12	315MHz	●	●	4	A	315Mhz	Continental	68001696AAAB		
1756	US	Jeep	Compass	2007/01-2007/12	315MHz	●	●	5	A	315Mhz	Continental	68001696AAAB		
1771	US	Jeep	Grand Cherokee	2011/01-2015/12	433MHz	●	●	4	A	433Mhz	Schrader	56029398AB		56029398AB
1772	US	Jeep	Grand Cherokee	2011/01-2015/12	433MHz	●	●	5	A	433Mhz	Schrader	56029398AB		56029398AB
1769	US	Jeep	Grand Cherokee	2008/01-2010/12	433MHz	●	●	4	A	433Mhz	Schrader	56029359AC/ 56029359AB/ 56029359AA		56029359AC/ 56029359AB/ 56029359AA/
1770	US	Jeep	Grand Cherokee	2008/01-2010/12	433MHz	●	●	5	A	433Mhz	Schrader	56029359AC/ 56029359AB/ 56029359AA		56029359AC/ 56029359AB/ 56029359AA/
1767	US	Jeep	Grand Cherokee	2007/01-2007/12	315MHz	●	●	4	A	315Mhz	Schrader	56053036AA		56053036AA
1768	US	Jeep	Grand Cherokee	2007/01-2007/12	315MHz	●	●	5	A	315Mhz	Schrader	56053036AA		56053036AA
1765	US	Jeep	Grand Cherokee	2005/01-2006/12	315MHz	●	●	4	A	315Mhz	Continental	56053030ABAC		
1766	US	Jeep	Grand Cherokee	2005/01-2006/12	315MHz	●	●	5	A	315Mhz	Continental	56053030ABAC		
1763	US	Jeep	Grand Cherokee	2002/01-2004/12	433MHz	●	●	4	S	433Mhz	Schrader	52088990AD		52088990AD
1764	US	Jeep	Grand Cherokee	2002/01-2004/12	433MHz	●	●	5	S	433Mhz	Schrader	52088990AD		52088990AD
1783	US	Jeep	Liberty	2010/01-2012/12	315MHz	●	●	4	A	315Mhz	Continental	68078861AA/ 68001696AA		
1784	US	Jeep	Liberty	2010/01-2012/12	315MHz	●	●	5	A	315Mhz	Continental	68078861AA/ 68001696AA		
1779	US	Jeep	Liberty	2009/01-2009/12	315MHz	●	●	4	A	315Mhz	Schrader	56029465AB		56029465AB
1780	US	Jeep	Liberty	2009/01-2009/12	315MHz	●	●	5	A	315Mhz	Schrader	56029465AB		56029465AB
1781	US	Jeep	Liberty	2009/01-2009/12	433MHz	●	●	4	A	433Mhz	Schrader	56029359AC/ 56029359AB/ 56029359AA		56029359AC/ 56029359AB/ 56029359AA/
1782	US	Jeep	Liberty	2009/01-2009/12	433MHz	●	●	5	A	433Mhz	Schrader	56029359AC/ 56029359AB/ 56029359AA		56029359AC/ 56029359AB/ 56029359AA/
1777	US	Jeep	Liberty	2007/01-2008/12	315MHz	●	●	4	A	315Mhz	Schrader	56029465AB		56029465AB
1778	US	Jeep	Liberty	2007/01-2008/12	315MHz	●	●	5	A	315Mhz	Schrader	56029465AB		56029465AB
1775	US	Jeep	Liberty	2005/01-2006/12	315MHz	●	●	4	A	315Mhz	Continental	56053030ABAC		
1776	US	Jeep	Liberty	2005/01-2006/12	315MHz	●	●	5	A	315Mhz	Continental	56053030ABAC		
1773	US	Jeep	Liberty	2002/01-2004/12	433MHz	●	●	4	A	433Mhz	Schrader	52088990AD		52088990AD
1774	US	Jeep	Liberty	2002/01-2004/12	433MHz	●	●	5	A	433Mhz	Schrader	52088990AD		52088990AD
1785	US	Jeep	Patriot	2007/01-2015/12	315MHz	●	●	5	A	315Mhz	Continental	68001696AAAB		
1786	US	Jeep	Patriot	2007/01-2015/12	315MHz	●	●	4	A	315Mhz	Continental	68001696AAAB		
1797	US	Jeep	Wrangler	2013/01-2015/12	433MHz	●	●	4	A	433Mhz	Schrader	56029398AB		56029398AB
1798	US	Jeep	Wrangler	2013/01-2015/12	433MHz	●	●	5	A	433Mhz	Schrader	56029398AB		56029398AB

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
1793	US	Jeep	Wrangler	2010/01-2012/12	Clamp in	●	●	4	A	433Mhz	Schrader	56029359AC/ 56029359AB/ 56029359AA		56029359AC/ 56029359AB/ 56029359AA/
1794	US	Jeep	Wrangler	2010/01-2012/12	Clamp in	●	●	5	A	433Mhz	Schrader	56029359AC/ 56029359AB/ 56029359AA		56029359AC/ 56029359AB/ 56029359AA/
1795	US	Jeep	Wrangler	2010/01-2012/12	Snap in	●	●	4	A	315Mhz	Schrader	56029479AA		56029479AA
1796	US	Jeep	Wrangler	2010/01-2012/12	Snap in	●	●	5	A	315Mhz	Schrader	56029479AA		56029479AA
1789	US	Jeep	Wrangler	2009/01-2009/12	Clamp in	●	●	4	A	433Mhz	Schrader	56029359AC/ 56029359AB/ 56029359AA		56029359AC/ 56029359AB/ 56029359AA/
1790	US	Jeep	Wrangler	2009/01-2009/12	Clamp in	●	●	5	A	433Mhz	Schrader	56029359AC/ 56029359AB/ 56029359AA		56029359AC/ 56029359AB/ 56029359AA/
1791	US	Jeep	Wrangler	2009/01-2009/12	Snap in	●	●	4	A	315Mhz	Schrader	56029479AA/ 56029465AB		56029479AA/ 56029465AB
1792	US	Jeep	Wrangler	2009/01-2009/12	Snap in	●	●	5	A	315Mhz	Schrader	56029479AA/ 56029465AB		56029479AA/ 56029465AB
1787	US	Jeep	Wrangler	2007/01-2008/12	315MHz	●	●	4	A	315Mhz	Continental	56053030ABAC		
1788	US	Jeep	Wrangler	2007/01-2008/12	315MHz	●	●	5	A	315Mhz	Continental	56053030ABAC		
1802	US	KIA	Amanti	2010/01-2012/12	315MHz	○	●	4	O	315Mhz	TRW	529333E000		
1801	US	KIA	Amanti	2009/01-2009/12	315MHz	●	●	4	O	315Mhz	TRW	529333E000		
1800	US	KIA	Amanti	2008/01-2008/12	315MHz	●	●	4	O	315Mhz	TRW	529333E000		
1799	US	KIA	Amanti	2007/01-2007/12	315MHz	●	●	4	O	315Mhz	TRW	529333E000		
1803	US	KIA	Borrego	2009/01-2011/12	315MHz	●	●	4	O	315Mhz	TRW	529332F000	216707-101	216707-101
1804	US	KIA	Cadenza	2014/01-2015/12	315MHz	●	●	4	O	315Mhz	Continental	52933A5000	S180052041F	S180052041
1806	US	KIA	Forte	2014/01-2015/12	315MHz	●	●	4	O	315Mhz	TRW	52933A7000	225816-116	225816-116
1805	US	KIA	Forte	2010/01-2013/12	315MHz	●	●	4	O	315Mhz	Continental	529332M000	S180052017G	S180052017
1807	US	KIA	Magentis	2008/01-2010/12	315MHz	●	●	4	O	315Mhz	Lear	529332G200		52933-2G200
1808	US	KIA	Mohave	2009/01-2011/12	Hi line	●	●	4	O	315Mhz	TRW	529332F000	216707-101	216707-101
1810	US	KIA	Optima	2011/01-2013/12	315MHz	●	●	4	O	315Mhz	Continental	529332M000	S180052017G	S180052017
1809	US	KIA	Optima	2006/01-2010/12	315MHz	●	●	4	O	315Mhz	Lear	529332G200		52933-2G200
1812	US	KIA	Rio	2012/01-2014/12	315MHz	●	●	4	O	315Mhz	TRW	529333X200U/ 529333X200	225816-101	225816-101
1811	US	KIA	Rio	2007/01-2011/12	Lo Line	●	●	4	O	315Mhz	TRW	529332F000	216707-101	216707-101
1815	US	KIA	Rondo	2011/01-2012/12	315MHz	○	●	4	O	315Mhz	Lear	529332G200		52933-2G200
1814	US	KIA	Rondo	2007/01-2010/12	315MHz	●	●	4	O	315Mhz	Lear	529332G200		52933-2G200
1813	US	KIA	Rondo	2006/01-2006/12	315MHz	●	●	4	O	315Mhz	Lear	529332G200		52933-2G200
1819	US	KIA	Sedona	2014/01-2015/12	315MHz	●	○	4	O	315Mhz	Lear	529334D700		52933-4D700
1818	US	KIA	Sedona	2010/01-2013/12	315MHz	●	●	4	O	315Mhz	Lear	529332G200		52933-2G200
1817	US	KIA	Sedona	2009/01-2009/12	315MHz	●	●	4	O	315Mhz	Lear	529332G200		52933-2G200
1816	US	KIA	Sedona	2006/01-2008/12	315MHz	●	●	4	O	315Mhz	Lear	529334D800/ 529334D200/ 529334D000		52933-4D800/ 52933-4D200/ 52933-4D000
1824	US	KIA	Sorento	2011/01-2015/12	315MHz	●	●	4	O	315Mhz	Continental	529332M000	S180052017G	S180052017
1823	US	KIA	Sorento	2010/01-2010/12	Hi line	●	●	4	O	315Mhz	TRW	529333E000		
1822	US	KIA	Sorento	2009/01-2009/12	Hi line	●	●	4	O	315Mhz	TRW	529333E000		
1821	US	KIA	Sorento	2008/01-2008/12	Hi line	●	●	4	O	315Mhz	TRW	529333E000		
1820	US	KIA	Sorento	2007/01-2007/12	Hi line	●	●	4	O	315Mhz	TRW	529333E000		

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
1828	US	KIA	Soul	2014/01-2015/12	433MHz	●	●	4	0	433Mhz	Schrader	52933B2100		52933-B2100
1827	US	KIA	Soul	2010/01-2013/12	315MHz	●	●	4	0	315Mhz	Continental	529332M000	S180052017G	S180052017
1830	US	KIA	Spectra	2010/01-2011/12	Lo Line	○	●	4	0	315Mhz	TRW	529332F000	216707-101	216707-101
1829	US	KIA	Spectra	2007/01-2009/12	Lo Line	●	●	4	0	315Mhz	TRW	529332F000	216707-101	216707-101
1834	US	KIA	Sportage	2011/01-2013/12	Lo Line	●	●	4	0	315Mhz	TRW	529332F000	216707-101	216707-101
1833	US	KIA	Sportage	2009/01-2013/12	Lo Line	●	●	4	0	315Mhz	TRW	529332F000	216707-101	216707-101
1832	US	KIA	Sportage	2008/01-2008/12	Lo Line	●	●	4	0	315Mhz	TRW	529333E000		
1831	US	KIA	Sportage	2005/01-2007/12	Lo Line	●	●	4	0	315Mhz	TRW	529333E000		
1836	US	KIA	Tuscany	2007/01-2008/12	Lo Line	○	●	4	0	315Mhz	TRW	529333E000		
1837	US	Lamborghini	Gallardo	2008/01-2013/12	433MHz	○	●	4		433Mhz	Huf/Beru	4F0907275B	0532207011	RDE011
1839	US	Lamborghini	Murcielago	2008/01-2010/12	433MHz	○	●	4		433Mhz	Huf/Beru	4F0907275B	0532207011	RDE011
1841	US	Lamborghini	Reventon	2008/01-2008/12	433MHz	○	●	4		433Mhz	Huf/Beru	4F0907275B	0532207011	RDE011
1846	US	LandRover	LR2	2010/01-2013/12	315MHz	●	●	4	A	315Mhz	Continental	LR021936/ LR018859		
1847	US	LandRover	LR2	2010/01-2013/12	315MHz	●	●	5	A	315Mhz	Continental	LR021936/ LR018859		
1842	US	LandRover	LR2	2008/01-2009/12	315MHz	●	●	4	A	315Mhz	Continental	LR021936/ LR018859		
1843	US	LandRover	LR2	2008/01-2009/12	315MHz	●	●	5	A	315Mhz	Continental	LR021936/ LR018859		
1844	US	LandRover	LR2	2008/01-2009/12	433MHz	●	●	4	A	433Mhz	Continental	LR018861	T120123002H	T120123002
1845	US	LandRover	LR2	2008/01-2009/12	433MHz	●	●	5	A	433Mhz	Continental	LR018861	T120123002H	T120123002
1850	US	LandRover	LR3	2006/01-2009/12	315MHz	●	●	4	A	315Mhz	Continental	LR018860		
1851	US	LandRover	LR3	2006/01-2009/12	315MHz	●	●	5	A	315Mhz	Continental	LR018860		
1852	US	LandRover	LR3	2006/01-2009/12	433MHz	●	●	4	A	433Mhz	Continental	LR018861	T120123002H	T120123002
1853	US	LandRover	LR3	2006/01-2009/12	433MHz	●	●	5	A	433Mhz	Continental	LR018861	T120123002H	T120123002
1848	US	LandRover	LR3	2002/01-2005/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	YDB000060	0532207003	RDE003
1849	US	LandRover	LR3	2002/01-2005/12	433MHz	●	●	5	A	433Mhz	Huf/Beru	YDB000060	0532207003	RDE003
1854	US	LandRover	LR4	2010/01-2015/12	315MHz	●	●	4	A	315Mhz	Continental	LR021936/ LR018859		
1855	US	LandRover	LR4	2010/01-2015/12	315MHz	●	●	5	A	315Mhz	Continental	LR021936/ LR018859		
1856	US	LandRover	LR4	2010/01-2015/12	433MHz	●	●	4	A	433Mhz	Continental	LR018861	T120123002H	T120123002
1857	US	LandRover	LR4	2010/01-2015/12	433MHz	●	●	5	A	433Mhz	Continental	LR018861	T120123002H	T120123002
1867	US	LandRover	Range Rover	2010/01-2015/12	315MHz	●	●	5	A	315Mhz	Continental	LR021936		
1866	US	LandRover	Range Rover	2010/01-2013/12	315MHz	●	●	4	A	315Mhz	Continental	LR021936		
1862	US	LandRover	Range Rover	2007/01-2009/12	315MHz	●	●	4	A	315Mhz	Continental	LR018860		
1863	US	LandRover	Range Rover	2007/01-2009/12	315MHz	●	●	5	A	315Mhz	Continental	LR018860		
1864	US	LandRover	Range Rover	2007/01-2009/12	433MHz	●	●	4	A	433Mhz	Continental	LR018861	T120123002H	T120123002
1865	US	LandRover	Range Rover	2007/01-2009/12	433MHz	●	●	5	A	433Mhz	Continental	LR018861	T120123002H	T120123002
1858	US	LandRover	Range Rover	2006/01-2006/12	315MHz	●	●	4	A	315Mhz	Continental	LR018860		
1859	US	LandRover	Range Rover	2006/01-2006/12	315MHz	●	●	5	A	315Mhz	Continental	LR018860		
1860	US	LandRover	Range Rover	2006/01-2006/12	433MHz	●	●	4	A	433Mhz	Continental	LR018861	T120123002H	T120123002
1861	US	LandRover	Range Rover	2006/01-2006/12	433MHz	●	●	5	A	433Mhz	Continental	LR018861	T120123002H	T120123002
1868	US	LandRover	Range Rover Evoque	2012/01-2013/12	315MHz	●	●	4	A	315Mhz	Continental	LR010533		
1869	US	LandRover	Range Rover Evoque	2012/01-2013/12	315MHz	●	●	5	A	315Mhz	Continental	LR010533		
1876	US	LandRover	Range Rover Sport	2010/01-2013/12	315MHz	●	●	4	A	315Mhz	Continental	LR010533		

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow: Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, 0=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
1877	US	LandRover	Range Rover Sport	2010/01-2013/12	315MHz	●	●	5	A	315Mhz	Continental	LR010533		
1874	US	LandRover	Range Rover Sport	2010/01-2011/12	433MHz	●	●	4	A	433Mhz	Continental	LR018861	T120123002H	T120123002
1875	US	LandRover	Range Rover Sport	2010/01-2011/12	433MHz	●	●	5	A	433Mhz	Continental	LR018861	T120123002H	T120123002
1870	US	LandRover	Range Rover Sport	2006/01-2009/12	315MHz	●	●	4	A	315Mhz	Continental	LR018860		
1871	US	LandRover	Range Rover Sport	2006/01-2009/12	315MHz	●	●	5	A	315Mhz	Continental	LR018860		
1872	US	LandRover	Range Rover Sport	2006/01-2009/12	433MHz	●	●	4	A	433Mhz	Continental	LR018861	T120123002H	T120123002
1873	US	LandRover	Range Rover Sport	2006/01-2009/12	433MHz	●	●	5	A	433Mhz	Continental	LR018861	T120123002H	T120123002
1880	US	Lexus	CT 200H	2011/01-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1881	US	Lexus	CT 200H	2011/01-2015/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1884	US	Lexus	ES 250	2012/08-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	4260730060	3729A-PMVC010	42607-30060
1885	US	Lexus	ES 250	2012/08-2015/12	315MHz	●	●	5	0	315Mhz	Pacific	4260730060	3729A-PMVC010	42607-30060
1882	US	Lexus	ES 250	2007/01-2012/07	315MHz	●	●	4	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1883	US	Lexus	ES 250	2007/01-2012/07	315MHz	●	●	5	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1886	US	Lexus	ES 300h	2013/01-2013/12	315MHz	●	●	4	0	315Mhz	Pacific	4260730060	3729A-PMVC010	42607-30060
1887	US	Lexus	ES 300h	2013/01-2013/12	315MHz	●	●	5	0	315Mhz	Pacific	4260730060	3729A-PMVC010	42607-30060
1890	US	Lexus	ES 350	2013/01-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	4260730060	3729A-PMVC010	42607-30060
1891	US	Lexus	ES 350	2013/01-2015/12	315MHz	●	●	5	0	315Mhz	Pacific	4260730060	3729A-PMVC010	42607-30060
1888	US	Lexus	ES 350	2007/01-2012/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1889	US	Lexus	ES 350	2007/01-2012/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1892	US	Lexus	GS 300	2005/01-2012/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1893	US	Lexus	GS 300	2005/01-2012/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1896	US	Lexus	GS 350	2013/01-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	4260730060	3729A-PMVC010	42607-30060
1897	US	Lexus	GS 350	2013/01-2015/12	315MHz	●	●	5	0	315Mhz	Pacific	4260730060	3729A-PMVC010	42607-30060
1898	US	Lexus	GS 350	2013/01-2015/12	433MHz	●	●	4	0	433Mhz	Pacific	4260730070	PMV-107J	42607-30070
1899	US	Lexus	GS 350	2013/01-2015/12	433MHz	●	●	5	0	433Mhz	Pacific	4260730070	PMV-107J	42607-30070
1894	US	Lexus	GS 350	2007/01-2012/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1895	US	Lexus	GS 350	2007/01-2012/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1902	US	Lexus	GS 430	2006/07-2007/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1903	US	Lexus	GS 430	2006/07-2007/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1900	US	Lexus	GS 430	2005/01-2006/06	315MHz	●	●	4	0	315Mhz	Pacific	4260730030	PMV-1017	42607-30030
1901	US	Lexus	GS 430	2005/01-2006/06	315MHz	●	●	5	0	315Mhz	Pacific	4260730030	PMV-1017	42607-30030
1906	US	Lexus	GS 450h	2013/01-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	4260730060	3729A-PMVC010	42607-30060
1907	US	Lexus	GS 450h	2013/01-2015/12	315MHz	●	●	5	0	315Mhz	Pacific	4260730060	3729A-PMVC010	42607-30060
1904	US	Lexus	GS 450h	2007/01-2012/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1905	US	Lexus	GS 450h	2007/01-2012/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1910	US	Lexus	GS 460	2013/01-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	4260730060	3729A-PMVC010	42607-30060
1911	US	Lexus	GS 460	2013/01-2015/12	315MHz	●	●	5	0	315Mhz	Pacific	4260730060	3729A-PMVC010	42607-30060
1908	US	Lexus	GS 460	2008/01-2012/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1909	US	Lexus	GS 460	2008/01-2012/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1912	US	Lexus	GX 460	2010/01-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1913	US	Lexus	GX 460	2010/01-2015/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1918	US	Lexus	GX 470	2006/07-2014/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1919	US	Lexus	GX 470	2006/07-2014/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1916	US	Lexus	GX 470	2006/01-2006/06	315MHz	●	●	4	0	315Mhz	Pacific	4260730030	PMV-1017	42607-30030
1917	US	Lexus	GX 470	2006/01-2006/06	315MHz	●	●	5	0	315Mhz	Pacific	4260730030	PMV-1017	42607-30030

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, 0=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
1914	US	Lexus	GX 470	2004/01-2005/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733021/ 4260733011/ 4260735010	PMV-107J	42607-33021
1915	US	Lexus	GX 470	2004/01-2005/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733021/ 4260733011/ 4260735010	PMV-107J	42607-33021
1920	US	Lexus	HS 250h	2010/01-2012/12	315MHz	●	●	4	0	315Mhz	Pacific	4260775010	PMV-107J	42607-75010
1921	US	Lexus	HS 250h	2010/01-2012/12	315MHz	●	●	5	0	315Mhz	Pacific	4260775010	PMV-107J	42607-75010
1922	US	Lexus	IS 250	2006/01-2013/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1923	US	Lexus	IS 250	2006/01-2013/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1924	US	Lexus	IS 300h	2006/01-2013/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1925	US	Lexus	IS 300h	2006/01-2013/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1926	US	Lexus	IS 350	2006/01-2013/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1927	US	Lexus	IS 350	2006/01-2013/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1928	US	Lexus	IS C	2006/01-2012/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1929	US	Lexus	IS C	2006/01-2012/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1932	US	Lexus	IS F	2014/01-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	4260730060	3729A-PMVC010	42607-30060
1933	US	Lexus	IS F	2014/01-2015/12	315MHz	●	●	5	0	315Mhz	Pacific	4260730060	3729A-PMVC010	42607-30060
1930	US	Lexus	IS F	2006/01-2013/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1931	US	Lexus	IS F	2006/01-2013/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1936	US	Lexus	IS Series	2014/01-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	4260730060	3729A-PMVC010	42607-30060
1937	US	Lexus	IS Series	2014/01-2015/12	315MHz	●	●	5	0	315Mhz	Pacific	4260730060	3729A-PMVC010	42607-30060
1934	US	Lexus	IS Series	2006/01-2013/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1935	US	Lexus	IS Series	2006/01-2013/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1938	US	Lexus	LFA	2012/01-2013/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1939	US	Lexus	LFA	2012/01-2013/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1942	US	Lexus	LS 460	2013/01-2013/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1943	US	Lexus	LS 460	2013/01-2013/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1940	US	Lexus	LS 460	2007/01-2012/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1941	US	Lexus	LS 460	2007/01-2012/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1948	US	Lexus	LS 600h	2013/07-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	4260730060	3729A-PMVC010	42607-30060
1949	US	Lexus	LS 600h	2013/07-2015/12	315MHz	●	●	5	0	315Mhz	Pacific	4260730060	3729A-PMVC010	42607-30060
1946	US	Lexus	LS 600h	2013/01-2013/06	315MHz	●	●	4	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1947	US	Lexus	LS 600h	2013/01-2013/06	315MHz	●	●	5	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1944	US	Lexus	LS 600h	2007/01-2012/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1945	US	Lexus	LS 600h	2007/01-2012/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1950	US	Lexus	LX 470	2005/01-2007/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1951	US	Lexus	LX 470	2005/01-2007/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1954	US	Lexus	LX 570	2013/01-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1955	US	Lexus	LX 570	2013/01-2015/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1952	US	Lexus	LX 570	2008/01-2012/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1953	US	Lexus	LX 570	2008/01-2012/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1956	US	Lexus	NX	2014/01-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	4260730060	3729A-PMVC010	42607-30060
1957	US	Lexus	NX	2014/01-2015/12	315MHz	●	●	5	0	315Mhz	Pacific	4260730060	3729A-PMVC010	42607-30060
1958	US	Lexus	RC	2014/01-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	4260730060	3729A-PMVC010	42607-30060
1959	US	Lexus	RC	2014/01-2015/12	315MHz	●	●	5	0	315Mhz	Pacific	4260730060	3729A-PMVC010	42607-30060

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
1961	US	Lexus	RX 330	2006/01-2006/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1962	US	Lexus	RX 330	2006/01-2006/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1967	US	Lexus	RX 350	2014/09-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	4260730060	3729A-PMVC010	42607-30060
1968	US	Lexus	RX 350	2014/09-2015/12	315MHz	●	●	5	0	315Mhz	Pacific	4260730060	3729A-PMVC010	42607-30060
1966	US	Lexus	RX 350	2013/01-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	426070E011	3729A-PMV107J	42607-0E011
1965	US	Lexus	RX 350	2013/01-2014/08	315MHz	●	●	5	0	315Mhz	Pacific	426070E011	3729A-PMV107J	42607-0E011
1963	US	Lexus	RX 350	2007/01-2012/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1964	US	Lexus	RX 350	2007/01-2012/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1969	US	Lexus	RX 400h	2007/01-2012/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1970	US	Lexus	RX 400h	2007/01-2012/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1971	US	Lexus	RX 450h	2007/01-2013/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1972	US	Lexus	RX 450h	2007/01-2013/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1975	US	Lexus	SC 430	2007/01-2011/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1976	US	Lexus	SC 430	2007/01-2011/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733021	PMV-107J	42607-33021
1978	US	Lincoln	Aviator	2004/01-2005/12	433MHz	●	●	4	S	433Mhz	Schrader	4L2Z1A150BB/ 4L2Z1A150BA/ 4L2T1A150BA		4L2Z-1A150-BB/ 4L2Z-1A150-BA/ 4L2T-1A150-BA
1977	US	Lincoln	Aviator	2003/01-2003/12	433MHz	●	●	4	S	433Mhz	Schrader	4L2Z1A150BB/ 4L2Z1A150BA/ 4L2T1A150BA		4L2Z-1A150-BB/ 4L2Z-1A150-BA/ 4L2T-1A150-BA
1980	US	Lincoln	Mark LT	2009/01-2009/12	315MHz	○	●	4	S	315Mhz	Schrader	CM5T1A180AA		CM5T-1A180-AA
1979	US	Lincoln	Mark LT	2007/01-2008/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
1981	US	Lincoln	MKC	2015/01-2015/12	315MHz	○	●	4	A	315Mhz	Schrader	CM5T1A150AA		CM5T-1A150-AA
1985	US	Lincoln	MKS	2013/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	CM5T1A180AA		CM5T-1A180-AA
1984	US	Lincoln	MKS	2012/01-2012/12	315MHz	●	●	4	S	315Mhz	Schrader	CM5T1A180AA		CM5T-1A180-AA
1983	US	Lincoln	MKS	2011/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	9L3Z1A189A		9L3Z-1A189-A
1982	US	Lincoln	MKS	2009/01-2010/12	315MHz	●	●	4	S	315Mhz	Continental	7L1Z1A189A		
1989	US	Lincoln	MKT	2013/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	CM5T1A180AA		CM5T-1A180-AA
1988	US	Lincoln	MKT	2012/01-2012/12	315MHz	●	●	4	S	315Mhz	Schrader	CM5T1A180AA		CM5T-1A180-AA
1987	US	Lincoln	MKT	2011/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	9L3Z1A189A		9L3Z-1A189-A
1986	US	Lincoln	MKT	2010/01-2010/12	315MHz	●	●	4	S	315Mhz	Continental	7L1Z1A189A		
1996	US	Lincoln	MKX	2013/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	CM5T1A180AA		CM5T-1A180-AA
1995	US	Lincoln	MKX	2012/01-2012/12	315MHz	●	●	4	S	315Mhz	Schrader	CM5T1A180AA		CM5T-1A180-AA
1994	US	Lincoln	MKX	2011/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	9L3Z1A189A		9L3Z-1A189-A
1992	US	Lincoln	MKX	2008/01-2010/12	with Chrome rims	●	●	4	S	315Mhz	Continental	7L1Z1A189A		
1993	US	Lincoln	MKX	2008/01-2010/12	no Chrome rims	●	●	4	S	315Mhz	Continental	7L1Z1A189A		
1990	US	Lincoln	MKX	2007/01-2007/12	with Chrome rims	●	●	4	S	315Mhz	Continental	7L1Z1A189A		
1991	US	Lincoln	MKX	2007/01-2007/12	no Chrome rims	●	●	4	S	315Mhz	Continental	7L1Z1A189A		
2000	US	Lincoln	MKZ	2012/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	CM5T1A180AA		CM5T-1A180-AA
1999	US	Lincoln	MKZ	2010/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	9L3Z1A189A		9L3Z-1A189-A
1998	US	Lincoln	MKZ	2008/01-2009/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
1997	US	Lincoln	MKZ	2007/01-2007/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
2007	US	Lincoln	Navigator	2012/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	CM5T1A180AA		CM5T-1A180-AA
2006	US	Lincoln	Navigator	2011/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	9L3Z1A189A		9L3Z-1A189-A

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
2005	US	Lincoln	Navigator	2008/01-2010/12	315MHz	●	●	4	S	315Mhz	Continental	7L1Z1A189A		
2004	US	Lincoln	Navigator	2007/01-2007/12	315MHz	●	●	4	S	315Mhz	Continental	7L1Z1A189A		
2003	US	Lincoln	Navigator	2005/01-2006/12	315MHz	●	●	4	S	315Mhz	Schrader	5L1Z1A150AA		5L1Z-1A150-AA
2002	US	Lincoln	Navigator	2004/01-2004/12	433MHz	●	●	4	S	433Mhz	Schrader	4L2Z1A150BA		4L2Z-1A150-BA
2001	US	Lincoln	Navigator	2003/01-2003/12	433MHz	●	●	4	S	433Mhz	Schrader	4L2Z1A150BA		4L2Z-1A150-BA
2012	US	Lincoln	Town Car	2012/01-2012/12	315MHz	○	●	4	S	315Mhz	Schrader	CM5T1A150AA		CM5T-1A150-AA
2011	US	Lincoln	Town Car	2010/01-2011/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
2010	US	Lincoln	Town Car	2009/01-2009/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
2009	US	Lincoln	Town Car	2008/01-2008/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
2008	US	Lincoln	Town Car	2006/01-2007/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
2013	US	Lotus	Elise	2008/01-2011/12	433MHz	○	●	4		433Mhz	Schrader	13227143		13227143
2014	US	Lotus	Evora	2010/01-2011/12	433MHz	○	●	4		433Mhz	Schrader	13227143		13227143
2015	US	Lotus	Exige	2008/01-2011/12	433MHz	○	●	4		433Mhz	Schrader	13227143		13227143
2017	US	Maserati	Coupe	2009/01-2011/12	433MHz	○	●	4	A	433Mhz	Huf/Beru	248887	0532207011	RDE011
2016	US	Maserati	Coupe	2007/01-2008/12	433MHz	○	●	4	A	433Mhz	Huf/Beru	224549	0532207001	RDE001
2019	US	Maserati	Quattroporte	2010/01-2011/12	433MHz	○	●	4	A	433Mhz	Huf/Beru	248887	0532207011	RDE011
2018	US	Maserati	Quattroporte	2004/01-2009/12	433MHz	○	●	4	A	433Mhz	Huf/Beru	224549/185189	0532207001	RDE001
2020	US	Maybach	Landaulet	2009/01-2012/12	315MHz	○	●	4	S	315Mhz	Huf/Beru	A0055422418	0532107001	RDE004
2021	US	Maybach	Maybach 57	2003/01-2011/12	315MHz	○	●	4	S	315Mhz	Huf/Beru	A0055422418	0532107001	RDE004
2022	US	Maybach	Maybach 57 S	2006/01-2012/12	315MHz	○	●	4	S	315Mhz	Huf/Beru	A0055422418	0532107001	RDE004
2023	US	Maybach	Maybach 62	2003/01-2011/12	315MHz	○	●	4	S	315Mhz	Huf/Beru	A0055422418	0532107001	RDE004
2024	US	Maybach	Maybach 62 S	2003/01-2012/12	315MHz	○	●	4	S	315Mhz	Huf/Beru	A0055422418	0532107001	RDE004
2026	US	Mazda	B Pickup	2009/01-2013/12	315MHz	○	●	4	S	315Mhz	Schrader	ZZDA37140		ZZDA-37-140
2025	US	Mazda	B Pickup	2007/01-2008/12	315MHz	○	●	4	S	315Mhz	Lear	6F2Z1A189A		
2029	US	Mazda	CX-7	2011/01-2012/12	315MHz	○	●	4	A	315Mhz	Continental	BBM237140B	S180052019H	S180052019
2028	US	Mazda	CX-7	2010/01-2010/12	315MHz	●	●	4	A	315Mhz	Continental	BBM237140B	S180052019H	S180052019
2027	US	Mazda	CX-7	2007/01-2009/12	315MHz	●	●	4	A	315Mhz	Continental	BBM237140B	S180052019H	S180052019
2030	US	Mazda	CX-9	2007/01-2015/12	315MHz	●	●	4	A	315Mhz	Continental	BBM237140B	S180052019H	S180052019
2031	US	Mazda	Mazda 2	2011/01-2014/12	315MHz	●	●	4	A	315Mhz	Continental	BBM237140B	S180052019H	S180052019
2035	US	Mazda	Mazda 3	2010/01-2014/12	315MHz	●	●	4	A	315Mhz	Continental	BBM237140B	S180052019H	S180052019
2034	US	Mazda	Mazda 3	2007/01-2009/12	315MHz	●	●	4	A	315Mhz	Continental	BBM237140B	S180052019H	S180052019
2033	US	Mazda	Mazda 3	2005/01-2006/12	315MHz	●	●	4	A	315Mhz	Continental	BBM237140B	S180052019H	S180052019
2032	US	Mazda	Mazda 3	2004/01-2004/12	315MHz	●	●	4	A	315Mhz	Continental	BBM237140B/ FE0137140A	S180052019H	S180052019
2038	US	Mazda	Mazda 5	2011/01-2015/12	315MHz	●	●	4	A	315Mhz	Continental	BBM237140B	S180052019H	S180052019
2037	US	Mazda	Mazda 5	2008/01-2010/12	315MHz	●	●	4	A	315Mhz	Continental	BBM237140B	S180052019H	S180052019
2036	US	Mazda	Mazda 5	2006/01-2007/12	315MHz	●	●	4	A	315Mhz	Continental	BBM237140B	S180052019H	S180052019
2042	US	Mazda	Mazda 6	2011/01-2014/12	315MHz	●	●	4	A	315Mhz	Continental	BBM237140B	S180052019H	S180052019
2041	US	Mazda	Mazda 6	2009/01-2010/12	315MHz	●	●	4	A	315Mhz	Continental	BBM237140B	S180052019H	S180052019
2040	US	Mazda	Mazda 6	2008/01-2008/12	315MHz	●	●	4	A	315Mhz	Continental	BBM237140B	S180052019H	S180052019
2039	US	Mazda	Mazda 6	2005/01-2007/12	315MHz	●	●	4	A	315Mhz	Continental	BBM237140B	S180052019H	S180052019
2043	US	Mazda	MX-5 Miata	2006/01-2015/12	315MHz	●	●	4	A	315Mhz	Continental	BBM237140B	S180052019H	S180052019
2047	US	Mazda	RX-8	2011/01-2015/12	315MHz	○	●	4	A	315Mhz	Continental	BBM237140B	S180052019H	S180052019
2046	US	Mazda	RX-8	2009/01-2010/12	315MHz	●	●	4	A	315Mhz	Continental	BBM237140B/ GN3A37140B	S180052019H	S180052019

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
2045	US	Mazda	RX-8	2005/01-2008/12	315MHz	●	●	4	A	315Mhz	Continental	BBM237140B/ GN3A37140B	S180052019H	S180052019
2044	US	Mazda	RX-8	2004/01-2004/12	315MHz	●	●	4	A	315Mhz	Continental	FE0137140A	S180052019H	S180052019
2048	US	Mazda	Speed 3	2010/01-2012/12	315MHz	○	●	4	A	315Mhz	Continental	BBM237140B/ GN3A37140B	S180052019H	S180052019
2049	US	Mazda	Speed 6	2007/01-2008/12	315MHz	○	●	4	A	315Mhz	Continental	GN3A37140B	S180052019H	S180052019
2054	US	Mazda	Tribute	2011/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	9L3Z1A189A/ ZZDA37140		9L3Z-1A189-A/ ZZDA-37-140
2053	US	Mazda	Tribute	2010/01-2010/12	315MHz	●	●	4	S	315Mhz	Schrader	9L3Z1A189A/ ZZDA37140		9L3Z-1A189-A/ ZZDA-37-140
2052	US	Mazda	Tribute	2009/01-2009/12	315MHz	●	●	4	S	315Mhz	Schrader	9L3Z1A189A/ ZZDA37140		9L3Z-1A189-A/ ZZDA-37-140
2051	US	Mazda	Tribute	2008/01-2008/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
2050	US	Mazda	Tribute	2006/01-2007/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
2056	US	Mercedes	C Class	2007/01-2015/12	433MHz	●	●	4	A	433Mhz	Schrader	0045400217/ A0035400217		A 003 540 02 17
2061	US	Mercedes	CL Class	2010/01-2015/12	433MHz	●	●	4	S	433Mhz	Schrader	0045400217/ A0035400217		A 003 540 02 17
2059	US	Mercedes	CL Class	2007/01-2009/12	315MHz	●	●	4	A	315Mhz	Continental	A0025407917		
2060	US	Mercedes	CL Class	2007/01-2009/12	433MHz	●	●	4	A	433Mhz	Continental	A0025408017	S180014730Z	S122228002
2057	US	Mercedes	CL Class	2000/01-2006/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	0008223406/ A0055422418	0532107001	RDE004
2058	US	Mercedes	CL Class	2000/01-2006/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	0008223306/ A0055422318	0532207001	RDE001
2062	US	Mercedes	CLA Class	2014/01-2015/12	433MHz	●	●	4	A	433Mhz	Schrader	0045400217/ A0035400217		A 003 540 02 17
2064	US	Mercedes	CLK Class	2008/01-2009/12	433MHz	●	●	4	A	433Mhz	Schrader	0045400217/ A0035400217		A 003 540 02 17
2063	US	Mercedes	CLK Class	2006/01-2007/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	0008223406/ A0055422418	0532107001	RDE004
2067	US	Mercedes	CLS Class	2012/01-2015/12	433MHz	●	●	4	A	433Mhz	Schrader	A0035400217		A 003 540 02 17
2065	US	Mercedes	CLS Class	2006/01-2011/12	315MHz	●	●	4	A	315Mhz	Continental	A0025407917		
2066	US	Mercedes	CLS Class	2006/01-2011/12	433MHz	●	●	4	A	433Mhz	Continental	A0025408017	S180014730Z	S122228002
2072	US	Mercedes	E Class	2010/06-2015/12	433MHz	●	●	4	A	433Mhz	Schrader	A0035400217		A 003 540 02 17
2070	US	Mercedes	E Class	2006/01-2010/05	315MHz	●	●	4	A	315Mhz	Continental	A0025407917		
2071	US	Mercedes	E Class	2006/01-2010/05	433MHz	●	●	4	A	433Mhz	Continental	A0025408017	S180014730Z	S122228002
2068	US	Mercedes	E Class	2000/01-2005/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	8223406	0532107001	RDE004
2069	US	Mercedes	E Class	2000/01-2005/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	8223306	0532207001	RDE001
2073	US	Mercedes	G Class	2007/01-2015/12	433MHz	●	●	4	A	433Mhz	Schrader	A0035400217		A 003 540 02 17
2076	US	Mercedes	GL Class	2010/01-2015/12	433MHz	●	●	4	S	433Mhz	Schrader	0045400217/ 0035400217		004 540 02 17/ 003 540 02 17
2074	US	Mercedes	GL Class	2007/01-2009/12	315MHz	●	●	4	A	315Mhz	Continental	A0025407917		
2075	US	Mercedes	GL Class	2007/01-2009/12	433MHz	●	●	4	A	433Mhz	Continental	A0025408017	S180014730Z	S122228002
2077	US	Mercedes	GLA	2014/01-2015/12	433MHz	●	●	4	A	433Mhz	Schrader	A0045400217		
2078	US	Mercedes	GLK	2010/01-2015/12	433MHz	●	●	4	A	433Mhz	Schrader	0045400217/ 0035400217		004 540 02 17/ 003 540 02 17
2081	US	Mercedes	ML Class	2010/06-2015/12	433MHz	●	●	4	A	433Mhz	Schrader	0045400217/ A0035400217		A 003 540 02 17
2079	US	Mercedes	ML Class	2006/01-2010/05	315MHz	●	●	4	A	315Mhz	Continental	A0025407917		
2080	US	Mercedes	ML Class	2006/01-2010/05	433MHz	●	●	4	A	433Mhz	Continental	A0025408017	S180014730Z	S122228002

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
2084	US	Mercedes	R Class	2010/01-2015/12	433MHz	●	●	4	A	433Mhz	Schrader	A0035400217		A 003 540 02 17
2082	US	Mercedes	R Class	2006/01-2009/12	315MHz	●	●	4	A	315Mhz	Continental	A0025407917		
2083	US	Mercedes	R Class	2006/01-2009/12	433MHz	●	●	4	A	433Mhz	Continental	A0025408017	S180014730Z	S122228002
2091	US	Mercedes	S Class	2010/01-2015/12	433MHz	●	●	4	A	433Mhz	Schrader	A0035400217		A 003 540 02 17
2089	US	Mercedes	S Class	2007/01-2009/12	315MHz	●	●	4	A	315Mhz	Continental	A0025407917		
2090	US	Mercedes	S Class	2007/01-2009/12	433MHz	●	●	4	A	433Mhz	Continental	A0025408017	S180014730Z	S122228002
2085	US	Mercedes	S Class	2000/01-2006/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	0008223406/ A0055422418	0532107001	RDE004
2086	US	Mercedes	S Class	2000/01-2006/12	315MHz	●	●	5	A	315Mhz	Huf/Beru	0008223406/ A0055422418	0532107001	RDE004
2087	US	Mercedes	S Class	2000/01-2006/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	0008223306/ A0055422318	0532207001	RDE001
2088	US	Mercedes	S Class	2000/01-2006/12	433MHz	●	●	5	A	433Mhz	Huf/Beru	0008223306/ A0055422318	0532207001	RDE001
2094	US	Mercedes	SL Class	2006/01-2012/12	315MHz	●	●	4	A	315Mhz	Continental	A0025407917		
2095	US	Mercedes	SL Class	2006/01-2012/06	433MHz	●	●	4	A	433Mhz	Continental	A0025408017	S180014730Z	S122228002
2092	US	Mercedes	SL Class	2000/01-2005/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	0008223406/ A0055422418	0532107001	RDE004
2093	US	Mercedes	SL Class	2000/01-2005/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	0008223306/ A0055422318	0532207001	RDE001
2097	US	Mercedes	SLK Class	2008/01-2015/12	433MHz	●	●	4	A	433Mhz	Schrader	0045400217/ A0035400217		A 003 540 02 17
2100	US	Mercedes	SLR Class	2008/01-2009/12	315MHz	●	●	4	A	315Mhz	Continental	A0025407917		
2101	US	Mercedes	SLR Class	2008/01-2009/12	433MHz	●	●	4	A	433Mhz	Continental	A0025408017	S180014730Z	S122228002
2098	US	Mercedes	SLR Class	2001/01-2007/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	8223406	0532107001	RDE004
2099	US	Mercedes	SLR Class	2001/01-2007/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	8223306	0532207001	RDE001
2102	US	Mercedes	SLR McLaren	2005/01-2006/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	A0055422418	0532107001	RDE004
2103	US	Mercedes	SLS	2011/01-2012/12	433MHz	●	●	4	A	433Mhz	Schrader	A0035400217		A 003 540 02 17
2108	US	Mercury	Grand Marquis	2009/01-2011/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
2107	US	Mercury	Grand Marquis	2008/01-2008/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
2106	US	Mercury	Grand Marquis	2006/01-2007/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
2113	US	Mercury	Mariner	2011/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	9L3Z1A189A		9L3Z-1A189-A
2112	US	Mercury	Mariner	2010/01-2010/12	315MHz	●	●	4	S	315Mhz	Schrader	9L3Z1A189A		9L3Z-1A189-A
2111	US	Mercury	Mariner	2009/01-2009/12	315MHz	●	●	4	S	315Mhz	Schrader	9L3Z1A189A		9L3Z-1A189-A
2110	US	Mercury	Mariner	2008/01-2008/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
2109	US	Mercury	Mariner	2006/01-2007/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
2115	US	Mercury	Milan	2010/01-2011/12	315MHz	●	●	4	S	315Mhz	Schrader	9L3Z1A189A		9L3Z-1A189-A
2114	US	Mercury	Milan	2008/01-2009/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
2116	US	Mercury	Montego	2006/01-2007/12	315MHz	○	●	4	S	315Mhz	Lear	6F2Z1A189A		
2119	US	Mercury	Monterey	2006/01-2007/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
2118	US	Mercury	Monterey	2005/01-2005/12	315MHz	●	●	4	S	315Mhz	Schrader	5L7Z1A150AA		5L7Z-1A150-AA
2117	US	Mercury	Monterey	2004/01-2004/12	315MHz	○	●	4	S	315Mhz	Schrader	5L7Z1A150AA		5L7Z-1A150-AA
2123	US	Mercury	Mountaineer	2008/01-2010/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
2122	US	Mercury	Mountaineer	2006/01-2007/12	315MHz	●	●	4	S	315Mhz	Lear	6F2Z1A189A		
2121	US	Mercury	Mountaineer	2004/01-2005/12	433MHz	●	●	4	S	433Mhz	Schrader	4L2Z1A150BA		4L2Z-1A150-BA
2120	US	Mercury	Mountaineer	2002/01-2003/12	433MHz	●	●	4	S	433Mhz	Schrader	4L2Z1A150BA		4L2Z-1A150-BA
2124	US	Mercury	Sable	2008/01-2009/12	315MHz	●	●	4	S	315Mhz	Continental	7L1Z1A189A		
2127	US	Mini	All	2014/03-2015/12	433MHz	●	●	4	A	433Mhz	Continental	36106856227	S180052056Z	S180052056

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufactuer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
2126	US	Mini	All	2010/01-2014/02	433MHz	●	●	4	A	433Mhz	Huf/Beru	36106790054/ 36106856227	0532207012	RDE012
2125	US	Mini	All	2007/01-2009/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	36236781847	0532207008	RDE008
2134	US	Mitsubishi	Eclipse	2011/01-2012/12	Alloy	●	●	4	0	315Mhz	Schrader	4250B877		4250B877
2135	US	Mitsubishi	Eclipse	2011/01-2012/12	Alloy	●	●	5	0	315Mhz	Schrader	4250B877		4250B877
2136	US	Mitsubishi	Eclipse	2011/01-2012/12	Steel	●	●	4	0	315Mhz	Schrader	4250B875		4250B875
2137	US	Mitsubishi	Eclipse	2011/01-2012/12	Steel	●	●	5	0	315Mhz	Schrader	4250B875		4250B875
2132	US	Mitsubishi	Eclipse	2008/01-2010/12	315MHz	●	●	4	0	315Mhz	Schrader	MN103081		MN103081
2133	US	Mitsubishi	Eclipse	2008/01-2010/12	315MHz	●	●	5	0	315Mhz	Schrader	MN103081		MN103081
2128	US	Mitsubishi	Eclipse	2006/01-2007/12	Alloy	●	●	4	0	315Mhz	Schrader	MN103081		MN103081
2129	US	Mitsubishi	Eclipse	2006/01-2007/12	Alloy	●	●	5	0	315Mhz	Schrader	MN103081		MN103081
2130	US	Mitsubishi	Eclipse	2006/01-2007/12	Steel	●	●	4	0	315Mhz	Schrader	MN103081		MN103081
2131	US	Mitsubishi	Eclipse	2006/01-2007/12	Steel	●	●	5	0	315Mhz	Schrader	MN103081		MN103081
2148	US	Mitsubishi	Endeavor	2011/01-2012/12	Alloy	●	●	4	0	315Mhz	Schrader	4250B877		4250B877
2149	US	Mitsubishi	Endeavor	2011/01-2012/12	Alloy	●	●	5	0	315Mhz	Schrader	4250B877		4250B877
2150	US	Mitsubishi	Endeavor	2011/01-2012/12	Steel	●	●	4	0	315Mhz	Schrader	4250B875		4250B875
2151	US	Mitsubishi	Endeavor	2011/01-2012/12	Steel	●	●	5	0	315Mhz	Schrader	4250B875		4250B875
2146	US	Mitsubishi	Endeavor	2008/01-2010/12	315MHz	●	●	4	0	315Mhz	Schrader	MN103081		MN103081
2147	US	Mitsubishi	Endeavor	2008/01-2010/12	315MHz	●	●	5	0	315Mhz	Schrader	MN103081		MN103081
2142	US	Mitsubishi	Endeavor	2007/01-2007/12	315MHz	●	●	4	0	315Mhz	Schrader	MN103081		MN103081
2143	US	Mitsubishi	Endeavor	2007/01-2007/12	315MHz	●	●	5	0	315Mhz	Schrader	MN103081		MN103081
2144	US	Mitsubishi	Endeavor	2007/01-2007/12	433MHz	●	●	4	0	433Mhz	Schrader	MN103033		MN103033
2145	US	Mitsubishi	Endeavor	2007/01-2007/12	433MHz	●	●	5	0	433Mhz	Schrader	MN103033		MN103033
2140	US	Mitsubishi	Endeavor	2003/01-2006/12	433MHz	●	●	4	0	433Mhz	Schrader	MN103033/ 52088990AC		MN103033/ 52088990AC
2141	US	Mitsubishi	Endeavor	2003/01-2006/12	433MHz	●	●	5	0	433Mhz	Schrader	MN103033/ 52088990AC		MN103033/ 52088990AC
2160	US	Mitsubishi	Galant	2011/01-2013/12	Alloy	●	●	4	0	315Mhz	Schrader	4250B877		4250B877
2161	US	Mitsubishi	Galant	2011/01-2013/12	Alloy	●	●	5	0	315Mhz	Schrader	4250B877		4250B877
2162	US	Mitsubishi	Galant	2011/01-2013/12	Steel	●	●	4	0	315Mhz	Schrader	4250B875		4250B875
2163	US	Mitsubishi	Galant	2011/01-2013/12	Steel	●	●	5	0	315Mhz	Schrader	4250B875		4250B875
2158	US	Mitsubishi	Galant	2010/01-2010/12	315MHz	●	●	4	0	315Mhz	Schrader	MN103081		MN103081
2159	US	Mitsubishi	Galant	2010/01-2010/12	315MHz	●	●	5	0	315Mhz	Schrader	MN103081		MN103081
2154	US	Mitsubishi	Galant	2007/01-2009/12	Alloy	●	●	4	0	315Mhz	Schrader	MN103081		MN103081
2155	US	Mitsubishi	Galant	2007/01-2009/12	Alloy	●	●	5	0	315Mhz	Schrader	MN103081		MN103081
2156	US	Mitsubishi	Galant	2007/01-2009/12	Steel	●	●	4	0	315Mhz	Schrader	MN103081		MN103081
2157	US	Mitsubishi	Galant	2007/01-2009/12	Steel	●	●	5	0	315Mhz	Schrader	MN103081		MN103081
2152	US	Mitsubishi	Galant	2004/01-2006/12	433MHz	●	●	4	0	433Mhz	Schrader	MN103033		MN103033
2153	US	Mitsubishi	Galant	2004/01-2006/12	433MHz	●	●	5	0	433Mhz	Schrader	MN103033		MN103033
2164	US	Mitsubishi	i-MiEV	2010/01-2014/12	315MHz	●	●	4	0	315Mhz	Continental	4250B975	S180052027C	S180052027
2165	US	Mitsubishi	i-MiEV	2010/01-2014/12	315MHz	●	●	5	0	315Mhz	Continental	4250B975	S180052027C	S180052027
2168	US	Mitsubishi	Lancer	2011/01-2015/12	315MHz	●	●	4	0	315Mhz	Continental	4250B668/ 4250B975	S180052027B/ S180052027C	S180052027
2169	US	Mitsubishi	Lancer	2011/01-2015/12	315MHz	●	●	5	0	315Mhz	Continental	4250B668/ 4250B975	S180052027B/ S180052027C	S180052027
2166	US	Mitsubishi	Lancer	2008/01-2010/12	315MHz	●	●	4	0	315Mhz	Continental	4250A225/ 4250B975		

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
2167	US	Mitsubishi	Lancer	2008/01-2010/12	315MHz	●	●	5	0	315Mhz	Continental	4250A225/ 4250B975		
2170	US	Mitsubishi	Mirage	2014/01-2015/12	315MHz	○	●	4	A	315Mhz	Continental	4250B668	S180052027B	S180052027
2171	US	Mitsubishi	Mirage	2014/01-2015/12	315MHz	○	●	5	A	315Mhz	Continental	4250B668	S180052027B	S180052027
2172	US	Mitsubishi	Montero	2003/01-2006/12	315MHz	●	●	4	0	315Mhz	Schrader	MN103081		MN103081
2173	US	Mitsubishi	Montero	2003/01-2006/12	315MHz	●	●	5	0	315Mhz	Schrader	MN103081		MN103081
2176	US	Mitsubishi	Outlander	2011/01-2014/12	315MHz	●	●	4	0	315Mhz	Continental	4250B668	S180052027B	S180052027
2177	US	Mitsubishi	Outlander	2011/01-2014/12	315MHz	●	●	5	0	315Mhz	Continental	4250B668	S180052027B	S180052027
2174	US	Mitsubishi	Outlander	2007/01-2010/12	315MHz	●	●	4	0	315Mhz	Continental	4250A225		
2175	US	Mitsubishi	Outlander	2007/01-2010/12	315MHz	●	●	5	0	315Mhz	Continental	4250A225		
2178	US	Mitsubishi	Raider	2008/01-2009/12	315MHz	●	●	4	0	315Mhz	Schrader	56029319AC/ 56029319AB/ 56029319AA		56029319AC/ 56029319AB/ 56029319AA
2179	US	Mitsubishi	Raider	2008/01-2009/12	315MHz	●	●	5	0	315Mhz	Schrader	56029319AC/ 56029319AB/ 56029319AA		56029319AC/ 56029319AB/ 56029319AA
2180	US	Mitsubishi	RVR	2011/01-2014/12	315MHz	●	●	4	0	315Mhz	Continental	4250B668	S180052027B	S180052027
2181	US	Mitsubishi	RVR	2011/01-2014/12	315MHz	●	●	5	0	315Mhz	Continental	4250B668	S180052027B	S180052027
2183	US	Nissan	350Z	2007/01-2009/12	315MHz	●	●	4	0	315Mhz	Schrader	407001AA0B/ 407001AA0C/ 40700JA01C		40700-1AA0B/ 40700-1AA0C/ 40700-JA01C
2182	US	Nissan	350Z	2003/01-2006/12	315MHz	●	●	4	0	315Mhz	Schrader	40700CD001		40700-CD001
2185	US	Nissan	370Z	2010/05-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	407001LA0E/ 407001LA0D/ 407001LA0C/ 407001LA0B/ 407001LA0A	PMV-C811/ PMV-107S	40700-1LA0E/ 40700-1LA0D/ 40700-1LA0C/ 40700-1LA0B/ 40700-1LA0A
2184	US	Nissan	370Z	2009/01-2010/04	315MHz	●	●	4	0	315Mhz	Pacific	40700JK00C	PMV-107L	40700-JK00C
2188	US	Nissan	Altima	2013/01-2015/12	433MHz	●	●	4	S	433Mhz	Continental	407003JA0B/ 407003JA0A	S180052036G/ S180052036Z	S180052036
2186	US	Nissan	Altima	2006/01-2012/12	315MHz	●	●	4	0	315Mhz	Schrader	407001AA0B/ 40700JA01B/ 40700JA02B		40700-1AA0B/ 40700-JA01B/ 40700-JA02B
2192	US	Nissan	Armada	2009/01-2015/12	315MHz	●	●	4	0	315Mhz	Schrader	407001AA0B/ 40700JA02B		40700-1AA0B/ 40700-JA02B
2191	US	Nissan	Armada	2007/01-2008/12	315MHz	●	●	4	0	315Mhz	Schrader	40700CK001		40700-CK001
2189	US	Nissan	Armada	2005/01-2006/12	Alloy	●	●	4	0	315Mhz	Schrader	40700CK001		40700-CK001
2190	US	Nissan	Armada	2005/01-2006/12	Steel	●	○	4	0	315Mhz	Schrader	40700CK002		40700-CK002
2195	US	Nissan	Cube	2011/01-2015/12	with iKey	●	○	4	0	315Mhz	Pacific	407001LA0E/ 407001LA0D/ 407001LA0C/ 407001LA0B/ 407001LA0A	PMV-C811/ PMV-107S	40700-1LA0E/ 40700-1LA0D/ 40700-1LA0C/ 40700-1LA0B/ 40700-1LA0A
2196	US	Nissan	Cube	2009/01-2015/12	no iKey	●	○	4	0	315Mhz	Schrader	407001AA0C		40700-1AA0B/ 40700-1AA0C/ 40700-JA01C
2200	US	Nissan	Frontier	2008/01-2008/12	Alloy	●	●	4	0	315Mhz	Schrader	40700CK001		40700-CK001
2201	US	Nissan	Frontier	2008/01-2008/12	Steel	●	●	4	0	315Mhz	Schrader	40700JA01B		40700-JA01B
2198	US	Nissan	Frontier	2005/01-2007/12	Alloy	●	●	4	0	315Mhz	Schrader	40700CK001		40700-CK001
2199	US	Nissan	Frontier	2005/01-2007/12	Steel	●	●	4	0	315Mhz	Schrader	40700CK002/ 40700CK001		40700-CK002

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, 0=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
2197	US	Nissan	Frontier	2003/01-2004/12	315MHz	●	●	4	0	315Mhz	Schrader	40700CD001		40700-CD001
2203	US	Nissan	GT-R	2009/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	407001AA0B/ 40700JA00C/ 40700JA01B		40700-1AA0B/ 40700-JA00C/ 40700-JA01B
2205	US	Nissan	Juke	2011/01-2015/12	with iKey	●	●	4	0	315Mhz	Pacific	407001LA0E/ 407001LA0D/ 407001LA0C/ 407001LA0B/ 407001LA0A	PMV-C811/ PMV-107S	40700-1LA0E/ 40700-1LA0D/ 40700-1LA0C/ 40700-1LA0B/ 40700-1LA0A
2204	US	Nissan	Juke	2011/01-2013/12	no iKey	●	●	4	0	315Mhz	Schrader	407001AA0B/ 407001AA0C/ 40700JA01B		40700-1AA0B/ 40700-1AA0C/ 40700-JA01B
2207	US	Nissan	Leaf	2013/01-2013/12	315MHz	●	●	4	0	315Mhz	Pacific	407001LA0E/ 407001LA0D/ 407001LA0C/ 407001LA0B/ 407001LA0A	PMV-C811/ PMV-107S	40700-1LA0E/ 40700-1LA0D/ 40700-1LA0C/ 40700-1LA0B/ 40700-1LA0A
2206	US	Nissan	Leaf	2011/01-2012/12	315MHz	●	●	4	0	315Mhz	Pacific	407001LA0E/ 407001LA0D/ 407001LA0C/ 407001LA0B/ 407001LA0A	PMV-C811/ PMV-107S	40700-1LA0E/ 40700-1LA0D/ 40700-1LA0C/ 40700-1LA0B/ 40700-1LA0A
2212	US	Nissan	Maxima	2008/01-2013/12	315MHz	●	●	4	0	315Mhz	Schrader	407001AA0B/ 40700JA01B/ 40700JA02B		40700-1AA0B/ 40700-JA01B/ 40700-JA02B
2210	US	Nissan	Maxima	2007/01-2007/12	Alloy	●	●	4	0	315Mhz	Schrader	40700CK001		40700-CK001
2211	US	Nissan	Maxima	2007/01-2007/12	Steel	●	●	4	0	315Mhz	Schrader	407001AA0B/ 40700JA01B/ 40700JA02B		40700-1AA0B/ 40700-JA01B/ 40700-JA02B
2209	US	Nissan	Maxima	2006/01-2006/12	315MHz	●	●	4	0	315Mhz	Schrader	40700CK001		40700-CK001
2214	US	Nissan	Maxima GCC	2013/01-2013/12	433MHz	●	●	4	S	433Mhz	Schrader	40700JY00B	90518295	40700-JY00B
2218	US	Nissan	Murano	2015/01-2015/12	315MHz	●	●	4	0	315Mhz	Schrader	40700JA01B		40700-JA01B
2217	US	Nissan	Murano	2010/01-2014/12	315MHz	●	●	4	0	315Mhz	Schrader	407001AA0B/ 407001AA0C/ 40700JA01B		40700-1AA0B/ 40700-1AA0C/ 40700-JA01B
2216	US	Nissan	Murano	2007/01-2009/12	315MHz	●	●	4	0	315Mhz	Schrader	407001AA0B/ 40700JA01B/ 40700JA02B		40700-1AA0B/ 40700-JA01B/ 40700-JA02B
2215	US	Nissan	Murano	2003/01-2006/12	315MHz	●	●	4	0	315Mhz	Schrader	40700CD001		40700-CD001
2219	US	Nissan	NV 200	2013/01-2015/12	315MHz	●	●	4	0	315Mhz	Schrader	407001AA0D		40700-1AA0D
2220	US	Nissan	NV1500	2012/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	407001PA0A		40700-1PA0A
2221	US	Nissan	NV2500HD	2012/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	407001PA0A		40700-1PA0A
2222	US	Nissan	NV3500HD	2012/01-2015/12	315MHz	●	●	4	S	315Mhz	Schrader	407001PA0A		40700-1PA0A
2228	US	Nissan	Pathfinder	2013/01-2015/12	433MHz	●	●	4	S	433Mhz	Continental	407003JA0B/ 407003JA0A	S180052036G/ S180052036Z	S180052036
2227	US	Nissan	Pathfinder	2007/01-2012/12	315MHz	●	●	4	0	315Mhz	Schrader	407001AA0B/ 40700JA02B		40700-1AA0B/ 40700-JA02B
2226	US	Nissan	Pathfinder	2005/01-2006/12	315MHz	●	●	4	0	315Mhz	Schrader	40700CK001		40700-CK001
2224	US	Nissan	Pathfinder	2004/01-2004/12	Alloy	●	●	4	0	315Mhz	Schrader	40700CK001		40700-CK001
2225	US	Nissan	Pathfinder	2004/01-2004/12	Steel	●	●	4	0	315Mhz	Schrader	40700CK002		40700-CK002
2223	US	Nissan	Pathfinder	2003/01-2003/12	315MHz	●	●	4	0	315Mhz	Schrader	40700CD001		40700-CD001

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
2229	US	Nissan	Patrol	2008/01-2010/12	433MHz	●	●	4	0	433Mhz	Pacific	407001LL0C	PMV-107U	40700-1LL0C
2234	US	Nissan	Quest	2011/01-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	407001LA0E/ 407001LA0D/ 407001LA0C/ 407001LA0B/ 407001LA0A	PMV-C811/ PMV-107S	40700-1LA0E/ 40700-1LA0D/ 40700-1LA0C/ 40700-1LA0B/ 40700-1LA0A
2233	US	Nissan	Quest	2008/01-2010/12	315MHz	●	●	4	0	315Mhz	Schrader	407001AA0B/ 40700JA01B/ 40700JA02B		40700-1AA0B/ 40700-JA01B/ 40700-JA02B
2231	US	Nissan	Quest	2005/01-2007/12	Alloy	●	●	4	0	315Mhz	Schrader	40700CK001		40700-CK001
2232	US	Nissan	Quest	2005/01-2007/12	Steel	●	●	4	0	315Mhz	Schrader	40700CK002		40700-CK002
2230	US	Nissan	Quest	2004/01-2004/12	315MHz	●	●	4	0	315Mhz	Schrader	40700CK002		40700-CK002
2236	US	Nissan	Rogue	2014/01-2015/12	433MHz	●	○	4	S	433Mhz	Continental	407003VU0A	S180052048Z	S180052048
2235	US	Nissan	Rogue	2008/01-2013/12	315MHz	●	●	4	0	315Mhz	Schrader	407001AA0B/ 40700JA01C		40700-1AA0B/ 40700-JA01C
2238	US	Nissan	Rogue Select	2014/01-2014/12	USA	●	○	4	S	433Mhz	Continental	407003VU0A	S180052048Z	S180052048
2242	US	Nissan	Sentra	2013/01-2015/12	with iKey	●	●	4	S	315Mhz	Continental	407003AN1B/ 407003AN1A	S180052035D	S180052035
2241	US	Nissan	Sentra	2009/01-2012/12	315MHz	●	●	4	0	315Mhz	Schrader	407001AA0B/ 40700JA02B		40700-1AA0B/ 40700-JA02B
2239	US	Nissan	Sentra	2007/01-2008/12	Alloy	●	●	4	0	315Mhz	Schrader	40700CK001		40700-CK001
2240	US	Nissan	Sentra	2007/01-2008/12	Steel	●	●	4	0	315Mhz	Schrader	407001AA0B/ 40700JA02B		40700-1AA0B/ 40700-JA02B
2249	US	Nissan	Titan	2009/01-2015/12	315MHz	●	●	4	0	315Mhz	Schrader	407001AA0D/ 40700JA02B		40700-1AA0D/ 40700-JA02B
2247	US	Nissan	Titan	2008/01-2008/12	Alloy	●	●	4	0	315Mhz	Schrader	40700CD001		40700-CD001
2248	US	Nissan	Titan	2008/01-2008/12	Steel	●	●	4	0	315Mhz	Schrader	407001AA0D/ 40700JA02B		40700-1AA0D/ 40700-JA02B
2245	US	Nissan	Titan	2005/01-2007/12	Alloy	●	●	4	0	315Mhz	Schrader	40700CK001		40700-CK001
2246	US	Nissan	Titan	2005/01-2007/12	Steel	●	●	4	0	315Mhz	Schrader	40700CK002		40700-CK002
2244	US	Nissan	Titan	2004/01-2004/12	315MHz	●	●	4	0	315Mhz	Schrader	40700CK002		40700-CK002
2254	US	Nissan	Versa	2013/01-2015/12	with iKey	●	●	4	S	315Mhz	Continental	407003AN1B/ 407003AN1A	S180052035D	S180052035
2253	US	Nissan	Versa	2012/01-2012/12	315MHz	●	●	4	0	315Mhz	Continental/ Schrader	407003AN0A/ 407003AN0B/ 407001AA0B	S180052033G	S180052033
2252	US	Nissan	Versa	2009/01-2011/12	315MHz	●	●	4	0	315Mhz	Schrader	407001AA0B/ 40700JA02B		40700-1AA0B/ 40700-JA02B
2250	US	Nissan	Versa	2007/01-2008/12	Alloy	●	●	4	0	315Mhz	Schrader	40700CK001		40700-CK001
2251	US	Nissan	Versa	2007/01-2008/12	Steel	●	●	4	0	315Mhz	Schrader	407001AA0B/ 40700JA02B		40700-1AA0B/ 40700-JA02B
2256	US	Nissan	Versa Hatchback	2007/01-2013/12	315MHz	●	●	4	0	315Mhz	Continental	407003AN0A	S180052033G	S180052033
2259	US	Nissan	Xterra	2006/01-2011/12	Alloy	●	●	4	0	315Mhz	Schrader	40700CK001		40700-CK001
2260	US	Nissan	Xterra	2006/01-2011/12	Steel	●	○	4	0	315Mhz	Schrader	40700CK002		40700-CK002
2258	US	Nissan	Xterra	2005/01-2005/12	315MHz	●	●	4	0	315Mhz	Schrader	40700CK001		40700-CK001
2257	US	Nissan	Xterra	2003/01-2004/12	315MHz	●	●	4	0	315Mhz	Schrader	40700CD001		40700-CD001
2263	US	Pontiac	G3	2009/01-2010/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/ 20923680
2265	US	Pontiac	G5	2009/01-2010/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/ 20923680
2264	US	Pontiac	G5	2008/01-2008/12	315MHz	●	●	4	S	315Mhz	Continental	15921013	S120123009A	

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
2268	US	Pontiac	G6	2009/01-2010/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/ 20923680
2266	US	Pontiac	G6	2008/01-2008/12	Clamp in	●	●	4	S	315Mhz	Continental	15921013	S120123009A	
2267	US	Pontiac	G6	2008/01-2008/12	Snap in	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/ 20923680
2269	US	Pontiac	G8	2008/01-2009/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/ 20923680
2272	US	Pontiac	Grand Prix	2008/01-2008/12	Clamp in	●	●	4	S	315Mhz	Continental	15921013	S120123009A	
2273	US	Pontiac	Grand Prix	2008/01-2008/12	Snap in	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/ 20923680
2271	US	Pontiac	Grand Prix	2007/01-2007/12	315MHz	●	●	4	S	315Mhz	Continental	15921013	S120123009A	
2274	US	Pontiac	Montana	2008/01-2009/12	315MHz	●	●	4	S	315Mhz	Schrader	15268606		15268606
2277	US	Pontiac	Solstice	2010/01-2010/12	315MHz	●	●	4	S	315Mhz	Continental	15921013	S120123009A	
2276	US	Pontiac	Solstice	2009/01-2009/12	315MHz	●	●	4	S	315Mhz	Continental	15921013	S120123009A	
2275	US	Pontiac	Solstice	2008/01-2008/12	315MHz	●	●	4	S	315Mhz	Continental	15921013	S120123009A	
2279	US	Pontiac	Torrent	2009/01-2009/12	315MHz	●	●	4	S	315Mhz	Continental	10394110	S120123007B	S120123007
2278	US	Pontiac	Torrent	2007/01-2008/12	315MHz	●	●	4	S	315Mhz	Continental	10394110	S120123007B	S120123007
2280	US	Pontiac	Vibe	2008/01-2010/12	315MHz	●	●	4	O	315Mhz	Pacific	88974915	PMV-107J	88974915
2281	US	Pontiac	Wave	2008/01-2009/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/ 20923680
2285	US	Porsche	911	2012/02-2015/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	99760602120	0532207011	RDE011
2282	US	Porsche	911	2005/02-2008/04	315MHz	●	●	4	A	315Mhz	Huf/Beru	95560602301		
2284	US	Porsche	911	2008/05-2012/10	433MHz	●	●	4	A	433Mhz	Huf/Beru	99760602120	0532207011	RDE011
2283	US	Porsche	911	2005/02-2008/04	433MHz	●	●	4	A	433Mhz	Huf/Beru	99760602101	0532207001	RDE001
2615	US	Porsche	911 Anniversary Edition	2014/01-2014/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	7PP907275G		
2616	US	Porsche	911 Carrera	2012/01-2015/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	7PP907275G		
2609	US	Porsche	911 Carrera	2009/01-2012/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	99760602321		
2617	US	Porsche	911 Carrera 4	2013/01-2015/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	7PP907275G		
2618	US	Porsche	911 Carrera 4 GTS	2012/01-2012/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	7PP907275G		
2619	US	Porsche	911 Carrera 4S	2012/01-2015/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	7PP907275G		
2620	US	Porsche	911 Carrera GTS	2012/01-2012/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	7PP907275G		
2621	US	Porsche	911 Carrera S	2012/01-2015/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	7PP907275G		
2622	US	Porsche	911 GT3	2014/01-2015/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	7PP907275G		
2623	US	Porsche	911 Targa 4	2014/01-2015/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	7PP907275G		
2625	US	Porsche	911 Targa 4S	2014/01-2015/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	7PP907275G		
2624	US	Porsche	911 Targa 4S	2012/01-2012/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	7PP907275G		
2626	US	Porsche	911 Turbo	2014/01-2015/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	7PP907275G		
2287	US	Porsche	911 Turbo	2010/01-2015/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	95836166100	0532207011	RDE011
2286	US	Porsche	911 Turbo	2007/01-2009/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	99760602101	0532207001	RDE001
2627	US	Porsche	911 Turbo S	2014/01-2015/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	7PP907275G		
2612	US	Porsche	911 Turbo/GT2 RS	2010/01-2013/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	99760602321		
2288	US	Porsche	918 Spyder	2013/01-2015/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	7PP907275F	0532207011	RDE011
2289	US	Porsche	Boxster	2013/09-2015/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	7PP907275F	0532207011	RDE011
2613	US	Porsche	Boxster	2009/01-2012/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	99760602321		
2292	US	Porsche	Boxster	2008/11-2014/01	433MHz	●	●	4	A	433Mhz	Huf/Beru	99760602120	0532207011	RDE011
2290	US	Porsche	Boxster	2005/02-2008/10	315MHz	●	●	4	A	315Mhz	Huf/Beru	95560602301		
2291	US	Porsche	Boxster	2005/02-2008/10	433MHz	●	●	4	A	433Mhz	Huf/Beru	99760602101	0532207001	RDE001

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
2628	US	Porsche	Boxster Base	2013/01-2014/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	7PP907275G		
2629	US	Porsche	Boxster S	2013/01-2014/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	7PP907275G		
2293	US	Porsche	Carrera GT	2003/09-2011/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	99760602101	0532207001	RDE001
2297	US	Porsche	Cayenne	2014/08-2015/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018
2296	US	Porsche	Cayenne	2013/01-2014/06	433MHz	●	●	4	A	433Mhz	Huf/Beru	95836166100	0532207011	RDE011
2294	US	Porsche	Cayenne	2011/01-2012/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	7P0907275A		
2295	US	Porsche	Cayenne	2011/01-2012/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	95836166100	0532207011	RDE011
2299	US	Porsche	Cayenne	2007/01-2010/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	95560602301		
2300	US	Porsche	Cayenne	2007/01-2010/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	95560602100	0532207011	RDE011
2298	US	Porsche	Cayenne	2002/01-2006/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	99760602101	0532207001	RDE001
2630	US	Porsche	Cayenne Base	2008/01-2009/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	7PP907275G		
2631	US	Porsche	Cayenne M/T GTS	2008/01-2009/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	7PP907275G		
2632	US	Porsche	Cayenne S	2008/01-2009/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	7PP907275G		
2633	US	Porsche	Cayenne Turbo	2008/01-2009/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	7PP907275G		
2634	US	Porsche	Cayenne Turbo S	2009/01-2009/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	7PP907275G		
2301	US	Porsche	Cayman	2013/04-2015/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	7PP907275F	0532207011	RDE011
2303	US	Porsche	Cayman	2009/01-2014/03	433MHz	●	●	4	A	433Mhz	Huf/Beru	99760602120	0532207011	RDE011
2614	US	Porsche	Cayman	2009/01-2012/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	99760602321		
2635	US	Porsche	Cayman Base	2014/01-2015/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	7PP907275G		
2636	US	Porsche	Cayman GTS	2015/01-2015/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	7PP907275G		
2637	US	Porsche	Cayman S	2014/01-2015/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	7PP907275G		
2305	US	Porsche	GT3	2010/01-2014/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	99760602120	0532207011	RDE011
2307	US	Porsche	GT3	2010/01-2014/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	99760602120	0532207011	RDE011
2304	US	Porsche	GT3	2007/03-2009/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	99760602100	0532207001	RDE001
2306	US	Porsche	GT3	2007/03-2009/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	99760602101	0532207001	RDE001
2308	US	Porsche	Macan	2014/01-2015/12	433MHz	○	●	4	A	433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018
2311	US	Porsche	Panamera	2013/01-2015/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	99760602120	0532207011	RDE011
2309	US	Porsche	Panamera	2010/01-2012/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	99760602321		
2310	US	Porsche	Panamera	2010/01-2012/12	433MHz	●	●	4	A	433Mhz	Huf/Beru	99760602120	0532207011	RDE011
2638	US	Porsche	Panamera 4	2011/01-2013/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	7PP907275G		
2639	US	Porsche	Panamera 4S	2010/01-2013/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	7PP907275G		
2640	US	Porsche	Panamera Base	2011/01-2013/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	7PP907275G		
2641	US	Porsche	Panamera GTS	2013/01-2013/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	7PP907275G		
2642	US	Porsche	Panamera S	2010/01-2013/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	7PP907275G		
2643	US	Porsche	Panamera S Hybrid	2012/01-2013/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	7PP907275G		
2644	US	Porsche	Panamera Turbo	2010/01-2013/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	7PP907275G		
2645	US	Porsche	Panamera Turbo S	2012/01-2013/12	315MHz	●	●	4	A	315Mhz	Huf/Beru	7PP907275G		
2312	US	Rolls-Royce	Ghost	2012/01-2012/12	433MHz	○	●	4	A	433Mhz	Huf/Beru	36106790054	0532207012	RDE012
2314	US	Rolls-Royce	Phantom	2012/01-2014/12	433MHz	○	●	4	A	433Mhz	Huf/Beru	36106790054	0532207012	RDE012
2313	US	Rolls-Royce	Phantom	2007/01-2011/12	433MHz	○	●	4	A	433Mhz	Huf/Beru	36236781847	0532207008	RDE008
2316	US	Saab	9-3	2008/01-2012/12	433MHz	○	●	4	A	433Mhz	Schrader	13227143		13227143
2315	US	Saab	9-3	2004/01-2007/12	433MHz	○	●	4	A	433Mhz	Schrader	13172567		13172567
2320	US	Saab	9-4X	2012/01-2012/12	315MHz	○	●	4	S	315Mhz	Schrader	20922900/ 22854866/ 12768826		20922900
2318	US	Saab	9-5	2008/01-2012/12	433MHz	○	●	4	A	433Mhz	Schrader	13227143		13227143

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, 0=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
2317	US	Saab	9-5	2004/01-2007/12	433MHz	○	●	4	A	433Mhz	Schrader	13172567		13172567
2322	US	Saab	9-7X	2008/01-2009/12	315MHz	●	●	4	S	315Mhz	Schrader	25774006		25774006
2321	US	Saab	9-7X	2005/01-2007/12	315MHz	○	●	4	S	315Mhz	Schrader	25774006		25774006
2324	US	Saturn	Astra	2010/01-2010/12	315MHz	○	●	4	S	315Mhz	Schrader	12768826/ 20922900/ 22854866		12768826/ 20922900/ 22854866
2323	US	Saturn	Astra	2008/01-2009/12	433MHz	○	●	4	S	433Mhz	Schrader	13172567		13172567
2328	US	Saturn	Aura	2009/01-2010/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/ 20923680
2326	US	Saturn	Aura	2008/01-2008/12	Clamp in	●	●	4	S	315Mhz	Continental	15921013	S120123009A	
2327	US	Saturn	Aura	2008/01-2008/12	Snap in	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/ 20923680
2325	US	Saturn	Aura	2007/01-2007/12	315MHz	●	●	4	S	315Mhz	Continental	15921013	S120123009A	
2329	US	Saturn	Lambda Crossover	2007/01-2008/12	315MHz	○	●	4	S	315Mhz	Schrader	15268606		15268606
2331	US	Saturn	Outlook	2009/01-2010/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615		25920615
2330	US	Saturn	Outlook	2007/01-2008/12	315MHz	●	●	4	S	315Mhz	Continental	15921013	S120123009A	
2333	US	Saturn	Sky	2009/01-2009/12	315MHz	●	●	4	S	315Mhz	Continental	15921013	S120123009A	
2332	US	Saturn	Sky	2008/01-2008/12	315MHz	●	●	4	S	315Mhz	Continental	15921013	S120123009A	
2336	US	Saturn	Vue	2009/01-2010/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/ 20923680
2335	US	Saturn	Vue	2008/01-2008/12	315MHz	●	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/ 20923680
2334	US	Saturn	Vue	2007/01-2007/12	315MHz	○	●	4	S	315Mhz	Schrader	25920615/ 20923680		25920615/ 20923680
2337	US	Scion	FR-S	2013/01-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	SU00300754	3729A-PMVC010	
2338	US	Scion	iQ	2012/01-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733011	PMV-107J	42607-33011
2339	US	Scion	tC	2006/01-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733011	PMV-107J	42607-33011
2340	US	Scion	xB	2007/01-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733011	PMV-107J	42607-33011
2341	US	Scion	xD	2008/01-2014/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733011	PMV-107J	42607-33011
2344	US	Smart	Fortwo	2009/01-2015/12	433MHz	○	●	4	A	433Mhz	Schrader	A0025400217/ A0035400217		A 003 540 02 17
2342	US	Smart	Fortwo	2008/01-2008/12	Schrader	○	●	4	A	433Mhz	Schrader	A0025400217/ A0035400217		A 003 540 02 17
2343	US	Smart	Fortwo	2008/01-2008/12	Siemens	○	●	4	A	433Mhz	Continental/ Schrader	A0045421518/ A0025409017		
2345	US	Subaru	B9 Tribeca	2006/01-2014/12	315MHz	●	●	4	0	315Mhz	Schrader	28103AG00B/ 28103AG00A		28103AG00B/ 28103AG00A
2346	US	Subaru	BRZ	2013/01-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	28103CA000	PMV-C010	28103CA000
2347	US	Subaru	Forester	2008/01-2015/12	315MHz	●	●	4	0	315Mhz	Schrader	28103AG01C		28103AG01C
2348	US	Subaru	Impreza	2008/01-2015/12	315MHz	●	●	4	0	315Mhz	Schrader	28103AG01C		28103AG01C
2350	US	Subaru	Legacy	2008/01-2015/12	315MHz	●	●	4	0	315Mhz	Schrader	28103AG01C		28103AG01C
2349	US	Subaru	Legacy	2004/01-2007/12	315MHz	●	●	4	0	315Mhz	Schrader	28103AG00B/ 28103AG00A		28103AG00B/ 28103AG00A
2352	US	Subaru	Outback	2008/01-2015/12	315MHz	●	●	4	0	315Mhz	Schrader	28103AG01C		28103AG01C
2351	US	Subaru	Outback	2004/01-2007/12	315MHz	●	●	4	0	315Mhz	Schrader	28103AG00B/ 28103AG00A		28103AG00B/ 28103AG00A
2353	US	Subaru	Tribeca	2008/01-2015/12	315MHz	●	●	4	0	315Mhz	Schrader	28103AG01C		28103AG01C
2354	US	Subaru	XV Crosstrek	2013/01-2015/12	315MHz	●	●	4	0	315Mhz	Schrader	28103AG01C		28103AG01C
2355	US	Suzuki	Equator	2009/01-2013/12	315MHz	○	●	4	0	315Mhz	Schrader	4321182Z00		43211-82Z00

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, 0=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
2356	US	Suzuki	Forenza	2007/01-2008/12	315MHz	○	●	4	0	315Mhz	Schrader	4313085Z03		43130-85Z03
2357	US	Suzuki	Grand Vitara	2007/01-2013/12	315MHz	○	●	4	S	315Mhz	Schrader	4313054J21		43130-54J21
2358	US	Suzuki	Kizashi	2010/01-2013/12	315MHz	○	●	4	0	315Mhz	Continental	4313057L00	S180052015E	S180052015
2359	US	Suzuki	Reno	2007/01-2008/12	315MHz	○	●	4	0	315Mhz	Schrader	4313085Z00		
2360	US	Suzuki	SX4	2007/01-2013/12	315MHz	○	●	4	S	315Mhz	Schrader	4313054J21		43130-54J21
2361	US	Suzuki	Verona	2005/01-2006/12	315MHz	○	●	4	0	315Mhz	Schrader	4313086Z20		43130-86Z20
2363	US	Suzuki	XL-7	2007/01-2011/12	315MHz	○	●	4	S	315Mhz	Continental	4313078J10		
2362	US	Suzuki	XL-7	2005/01-2006/12	315MHz	○	●	4	S	315Mhz	Schrader	4313054J21		43130-54J21
2369	US	Toyota	4 Runner	2013/01-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2370	US	Toyota	4 Runner	2013/01-2015/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2367	US	Toyota	4 Runner	2006/09-2012/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2368	US	Toyota	4 Runner	2006/09-2012/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2365	US	Toyota	4 Runner	2003/01-2006/08	315MHz	●	●	4	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021/ 4260735010	PMV-107J	42607-33011/ 42607-06011/ 42607-33021/ 42607-35010
2366	US	Toyota	4 Runner	2003/01-2006/08	315MHz	●	●	5	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021/ 4260735010	PMV-107J	42607-33011/ 42607-06011/ 42607-33021/ 42607-35010
2375	US	Toyota	Avalon	2013/01-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	4260706020	3729A-PMVC010	42607-06020
2376	US	Toyota	Avalon	2013/01-2015/12	315MHz	●	●	5	0	315Mhz	Pacific	4260706020	3729A-PMVC010	42607-06020
2371	US	Toyota	Avalon	2007/01-2012/12	Japan	●	●	4	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2372	US	Toyota	Avalon	2007/01-2012/12	Japan	●	●	5	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2373	US	Toyota	Avalon	2007/01-2012/12	USA	●	●	4	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2374	US	Toyota	Avalon	2007/01-2012/12	USA	●	●	5	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2381	US	Toyota	Camry	2012/01-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	4260706020	3729A-PMVC010	42607-06020
2382	US	Toyota	Camry	2012/01-2015/12	315MHz	●	●	5	0	315Mhz	Pacific	4260706020	3729A-PMVC010	42607-06020
2377	US	Toyota	Camry	2007/01-2011/12	Japan	●	●	4	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021/ 4260734020	PMV-107J	42607-33011/ 42607-06011/ 42607-33021/ 42607-34020
2378	US	Toyota	Camry	2007/01-2011/12	Japan	●	●	5	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021/ 4260734020	PMV-107J	42607-33011/ 42607-06011/ 42607-33021/ 42607-34020

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, 0=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
2379	US	Toyota	Camry	2007/01-2011/12	USA	●	●	4	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2380	US	Toyota	Camry	2007/01-2011/12	USA	●	●	5	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2385	US	Toyota	Camry Hybrid	2014/01-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	4260706020	3729A-PMVC010	42607-06020
2386	US	Toyota	Camry Hybrid	2014/01-2015/12	315MHz	●	●	5	0	315Mhz	Pacific	4260706020	3729A-PMVC010	42607-06020
2383	US	Toyota	Camry Hybrid	2008/01-2011/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021/ 4260734020	PMV-107J	42607-33011/ 42607-06011/ 42607-33021/ 42607-34020
2384	US	Toyota	Camry Hybrid	2008/01-2011/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021/ 4260734020	PMV-107J	42607-33011/ 42607-06011/ 42607-33021/ 42607-34020
2391	US	Toyota	Corolla	2014/01-2015/12	315MHz	●	●	4	S	315Mhz	Pacific	4260706020	3729A-PMVC010	42607-06020
2392	US	Toyota	Corolla	2014/01-2015/12	315MHz	●	●	5	S	315Mhz	Pacific	4260706020	3729A-PMVC010	42607-06020
2387	US	Toyota	Corolla	2006/01-2013/12	Japan	●	●	4	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021/ 4260734020	PMV-107J	42607-33011/ 42607-06011/ 42607-33021/ 42607-34020
2388	US	Toyota	Corolla	2006/01-2013/12	Japan	●	●	5	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021/ 4260734020	PMV-107J	42607-33011/ 42607-06011/ 42607-33021/ 42607-34020
2389	US	Toyota	Corolla	2006/01-2013/12	USA	●	●	4	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2390	US	Toyota	Corolla	2006/01-2013/12	USA	●	●	5	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2395	US	Toyota	FJ Cruiser	2013/01-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2396	US	Toyota	FJ Cruiser	2013/01-2015/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2393	US	Toyota	FJ Cruiser	2008/01-2012/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2394	US	Toyota	FJ Cruiser	2008/01-2012/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2401	US	Toyota	Highlander	2014/01-2015/12	Smart Key	●	●	4	0	315Mhz	Pacific	4260706020	3729A-PMVC010	42607-06020
2402	US	Toyota	Highlander	2014/01-2015/12	Smart Key	●	●	5	0	315Mhz	Pacific	4260706020	3729A-PMVC010	42607-06020
2399	US	Toyota	Highlander	2013/01-2013/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2400	US	Toyota	Highlander	2013/01-2013/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, 0=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
2397	US	Toyota	Highlander	2007/01-2012/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2398	US	Toyota	Highlander	2007/01-2012/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2405	US	Toyota	Highlander Hybrid	2013/01-2015/12	315MHz	●	●	4	0	315Mhz	TRW	426070R010	228408-101	228408-101
2406	US	Toyota	Highlander Hybrid	2013/01-2015/12	315MHz	●	●	5	0	315Mhz	TRW	426070R010	228408-101	228408-101
2403	US	Toyota	Highlander Hybrid	2008/01-2012/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733011	PMV-107J	42607-33011
2404	US	Toyota	Highlander Hybrid	2008/01-2012/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733011	PMV-107J	42607-33011
2407	US	Toyota	Highlander RKE	2014/01-2015/12	Canada	●	●	4	0	315Mhz	TRW	426070R010	228408-101	228408-101
2408	US	Toyota	Highlander RKE	2014/01-2015/12	Canada	●	●	5	0	315Mhz	TRW	426070R010	228408-101	228408-101
2417	US	Toyota	Land Cruiser	2015/01-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	4260730060	3729A-PMVC010	42607-30060
2418	US	Toyota	Land Cruiser	2015/01-2015/12	315MHz	●	●	5	0	315Mhz	Pacific	4260730060	3729A-PMVC010	42607-30060
2415	US	Toyota	Land Cruiser	2012/01-2014/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2416	US	Toyota	Land Cruiser	2012/01-2014/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2413	US	Toyota	Land Cruiser	2007/06-2011/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2414	US	Toyota	Land Cruiser	2007/06-2011/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2411	US	Toyota	Land Cruiser	2006/01-2007/05	315MHz	●	●	4	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2412	US	Toyota	Land Cruiser	2006/01-2007/05	315MHz	●	●	5	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2409	US	Toyota	Land Cruiser	2005/01-2005/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2410	US	Toyota	Land Cruiser	2005/01-2005/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2419	US	Toyota	Matrix	2007/01-2014/12	Japan made	●	●	4	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2420	US	Toyota	Matrix	2007/01-2014/12	Japan made	●	●	5	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2421	US	Toyota	Matrix	2007/01-2014/12	USA made	●	●	4	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2422	US	Toyota	Matrix	2007/01-2014/12	USA made	●	●	5	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, 0=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
2425	US	Toyota	Prius	2013/01-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2426	US	Toyota	Prius	2013/01-2015/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2423	US	Toyota	Prius	2006/01-2012/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2424	US	Toyota	Prius	2006/01-2012/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2429	US	Toyota	Prius V	2012/01-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2430	US	Toyota	Prius V	2012/01-2015/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2437	US	Toyota	RAV4	2013/07-2015/12	Standard key	●	●	4	0	315Mhz	TRW	426070R010	228408-101	228408-101
2438	US	Toyota	RAV4	2013/07-2015/12	Standard key	●	●	5	0	315Mhz	TRW	426070R010	228408-101	228408-101
2433	US	Toyota	RAV4	2007/01-2013/06	315MHz	●	●	4	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2434	US	Toyota	RAV4	2007/01-2013/06	315MHz	●	●	5	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2431	US	Toyota	RAV4	2006/01-2006/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2432	US	Toyota	RAV4	2006/01-2006/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2439	US	Toyota	RAV4 EV	2012/01-2012/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2440	US	Toyota	RAV4 EV	2012/01-2012/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2449	US	Toyota	Sequoia	2009/01-2015/12	315MHz	●	●	4	0	315Mhz	TRW	426070C070/ 4260708010	226196-101/ 216709-106	226196-101/ 216709-106
2450	US	Toyota	Sequoia	2009/01-2015/12	315MHz	●	●	5	0	315Mhz	TRW	426070C070/ 4260708010	226196-101/ 216709-106	226196-101/ 216709-106
2445	US	Toyota	Sequoia	2008/01-2008/12	Alloy	●	●	4	0	315Mhz	TRW	426070C070/ 4260708010/ 426070C030	226196-101/ 216709-106/ 216709-101	226196-101/ 216709-106/ 216709-101
2446	US	Toyota	Sequoia	2008/01-2008/12	Alloy	●	●	5	0	315Mhz	TRW	426070C070/ 4260708010/ 426070C030	226196-101/ 216709-106/ 216709-101	226196-101/ 216709-106/ 216709-101
2447	US	Toyota	Sequoia	2008/01-2008/12	Steel	●	●	4	0	315Mhz	TRW	426070C040	216710-101	216710-101
2448	US	Toyota	Sequoia	2008/01-2008/12	Steel	●	●	5	0	315Mhz	TRW	426070C040	216710-101	216710-101

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
2441	US	Toyota	Sequoia	2004/01-2007/12	Alloy	●	●	4	0	315Mhz	Pacific	4260733011/ 4260733021/ 4260706011/ 426070C020	PMV-107J	42607-0C020
2442	US	Toyota	Sequoia	2004/01-2007/12	Alloy	●	●	5	0	315Mhz	Pacific	4260733011/ 4260733021/ 4260706011/ 426070C020	PMV-107J	42607-0C020
2443	US	Toyota	Sequoia	2004/01-2007/12	Steel	●	●	4	0	315Mhz	Pacific	4260733011/ 4260733021/ 4260706011/ 426070C020	PMV-107J	42607-0C020
2444	US	Toyota	Sequoia	2004/01-2007/12	Steel	●	●	5	0	315Mhz	Pacific	4260733011/ 4260733021/ 4260706011/ 426070C020	PMV-107J	42607-0C020
2451	US	Toyota	Sienna	2006/01-2015/12	315MHz	●	●	4	0	315Mhz	TRW	426070C070/ 4260708010	226196-101/ 216709-106	226196-101/ 216709-106
2452	US	Toyota	Sienna	2006/01-2015/12	315MHz	●	●	5	0	315Mhz	TRW	426070C070/ 4260708010	226196-101/ 216709-106	226196-101/ 216709-106
2453	US	Toyota	Solara	2006/01-2011/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2454	US	Toyota	Solara	2006/01-2011/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2459	US	Toyota	Tacoma	2006/07-2015/12	Alloy	●	●	4	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2460	US	Toyota	Tacoma	2006/07-2015/12	Alloy	●	●	5	0	315Mhz	Pacific	4260733011/ 4260706011/ 4260733021	PMV-107J	42607-33011/ 42607-06011/ 42607-33021
2461	US	Toyota	Tacoma	2006/07-2015/12	Steel	●	●	4	0	315Mhz	Pacific	4260704010	PMV-108J	
2462	US	Toyota	Tacoma	2006/07-2015/12	Steel	●	●	5	0	315Mhz	Pacific	4260704010	PMV-108J	
2455	US	Toyota	Tacoma	2005/01-2006/06	Alloy	●	●	4	0	315Mhz	Pacific	42607AD020	PMV-1017	42607-AD020
2456	US	Toyota	Tacoma	2005/01-2006/06	Alloy	●	●	5	0	315Mhz	Pacific	42607AD020	PMV-1017	42607-AD020
2457	US	Toyota	Tacoma	2005/01-2006/06	Steel	●	●	4	0	315Mhz	Pacific	4260704010	PMV-108J	
2458	US	Toyota	Tacoma	2005/01-2006/06	Steel	●	●	5	0	315Mhz	Pacific	4260704010	PMV-108J	
2475	US	Toyota	Tundra	2007/01-2015/12	Alloy	●	●	4	0	315Mhz	TRW	426070C070/ 4260708010/ 426070C050	226196-101/ 216709-106/ 216709-105	226196-101/ 216709-106/ 216709-105
2476	US	Toyota	Tundra	2007/01-2015/12	Alloy	●	●	5	0	315Mhz	TRW	426070C070/ 4260708010/ 426070C050	226196-101/ 216709-106/ 216709-105	226196-101/ 216709-106/ 216709-105
2477	US	Toyota	Tundra	2007/01-2015/12	Steel	●	●	4	0	315Mhz	TRW	426070C060	216710-105	216710-106
2478	US	Toyota	Tundra	2007/01-2015/12	Steel	●	●	5	0	315Mhz	TRW	426070C060	216710-105	216710-106
2467	US	Toyota	Tundra	2006/01-2006/12	Alloy Pacifica	●	●	4	0	315Mhz	Pacific	4260733011/ 4260733021/ 4260706011/ 426070C020	PMV-107J	42607-0C020

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, 0=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
2468	US	Toyota	Tundra	2006/01-2006/12	Alloy Pacifica	●	●	5	0	315Mhz	Pacific	4260733011/ 4260733021/ 4260706011/ 426070C020	PMV-107J	42607-0C020
2469	US	Toyota	Tundra	2006/01-2006/12	Alloy TRW	●	●	4	0	315Mhz	TRW	426070C070/ 4260708010/ 426070C050	226196-101/ 216709-106/ 216709-105	226196-101/ 216709-106/ 216709-105
2470	US	Toyota	Tundra	2006/01-2006/12	Alloy TRW	●	●	5	0	315Mhz	TRW	426070C070/ 4260708010/ 426070C050	226196-101/ 216709-106/ 216709-105	226196-101/ 216709-106/ 216709-105
2471	US	Toyota	Tundra	2006/01-2006/12	Steel Pacifica	●	●	4	0	315Mhz	Pacific	4260733011/ 4260733021/ 4260706011	PMV-107J	42607-33011/ 42607-33021/ 42607-06011
2472	US	Toyota	Tundra	2006/01-2006/12	Steel Pacifica	●	●	5	0	315Mhz	Pacific	4260733011/ 4260733021/ 4260706011	PMV-107J	42607-33011/ 42607-33021/ 42607-06011
2473	US	Toyota	Tundra	2006/01-2006/12	Steel TRW	●	●	4	0	315Mhz	TRW	426070C060	216710-105	216710-106
2474	US	Toyota	Tundra	2006/01-2006/12	Steel TRW	●	●	5	0	315Mhz	TRW	426070C060	216710-105	216710-106
2463	US	Toyota	Tundra	2005/01-2005/12	Alloy	●	●	4	0	315Mhz	Pacific	4260733011/ 4260733021/ 4260706011/ 426070C020	PMV-107J	42607-0C020
2464	US	Toyota	Tundra	2005/01-2005/12	Alloy	●	●	5	0	315Mhz	Pacific	4260733011/ 4260733021/ 4260706011/ 426070C020	PMV-107J	42607-0C020
2465	US	Toyota	Tundra	2005/01-2005/12	Steel	●	●	4	0	315Mhz	Pacific	4260733011/ 4260733021/ 4260706011	PMV-107J	42607-33011/ 42607-33021/ 42607-06011
2466	US	Toyota	Tundra	2005/01-2005/12	Steel	●	●	5	0	315Mhz	Pacific	4260733011/ 4260733021/ 4260706011	PMV-107J	42607-33011/ 42607-33021/ 42607-06011
2479	US	Toyota	Venza	2009/01-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733011/ 4260733021/ 4260706011	PMV-107J	42607-33011/ 42607-33021/ 42607-06011
2480	US	Toyota	Venza	2009/01-2015/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733011/ 4260733021/ 4260706011	PMV-107J	42607-33011/ 42607-33021/ 42607-06011
2483	US	Toyota	Yaris	2012/01-2015/12	315MHz	●	●	4	0	315Mhz	Pacific	4260706020	3729A-PMVC010	42607-06020
2484	US	Toyota	Yaris	2012/01-2015/12	315MHz	●	●	5	0	315Mhz	Pacific	4260706020	3729A-PMVC010	42607-06020
2481	US	Toyota	Yaris	2007/01-2011/12	315MHz	●	●	4	0	315Mhz	Pacific	4260733011/ 4260733021/ 4260706011	PMV-107J	42607-33011/ 42607-33021/ 42607-06011
2482	US	Toyota	Yaris	2007/01-2011/12	315MHz	●	●	5	0	315Mhz	Pacific	4260733011/ 4260733021/ 4260706011	PMV-107J	42607-33011/ 42607-33021/ 42607-06011
2485	US	Volkswagen	Beetle	2007/01-2011/12	315MHz	●	●	5	A	315Mhz	Continental	1K0907253D	S122215001C	
2487	US	Volkswagen	CC	2012/01-2015/12	433MHz	●	●	5	A	433Mhz	Huf/Beru	3AA907275	0532207013	RDE013
2486	US	Volkswagen	CC	2009/01-2011/12	315MHz	●	●	5	A	315Mhz	Continental	1K0907253D	S122215001C	
2488	US	Volkswagen	EOS	2007/01-2015/12	315MHz	●	●	5	A	315Mhz	Continental	1K0907253D	S122215001C	
2489	US	Volkswagen	GLI	2008/01-2011/12	315MHz	●	●	5	A	315Mhz	Continental	1K0907253D	S122215001C	
2490	US	Volkswagen	Golf	2010/01-2012/12	315MHz	●	●	5	A	315Mhz	Continental	1K0907253D	S122215001C	

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
2492	US	Volkswagen	GTI	2006/01-2012/12	315MHz	●	●	5	A	315Mhz	Continental	1K0907253D	S122215001C	
2493	US	Volkswagen	GTI(O-ring Hex)	2006/01-2007/12	315MHz	●	●	5	A	315Mhz	Continental	1K0907253E		
2495	US	Volkswagen	Jetta	2013/01-2015/12	433MHz	●	●	5	A	433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018
2494	US	Volkswagen	Jetta	2006/01-2012/12	315MHz	●	●	5	A	315Mhz	Continental	1K0907253D	S122215001C	
2497	US	Volkswagen	Passat	2012/01-2015/12	433MHz	●	●	5	S	433Mhz	Huf/Beru	5Q0907275	0532207018	RDE018
2496	US	Volkswagen	Passat	2006/01-2011/12	315MHz	●	●	5	A	315Mhz	Continental	1K0907253D	S122215001C	
2498	US	Volkswagen	Passat(O-ring Hex)	2006/01-2008/12	315MHz	●	●	5	A	315Mhz	Continental	1K0907253E		
2502	US	Volkswagen	Phaeton	2011/01-2011/12	433MHz	●	●	5	S	433Mhz	Huf/Beru	4F0907275D	0532207011	RDE011
2501	US	Volkswagen	Phaeton	2007/06-2010/12	433MHz	●	●	5	A	433Mhz	Huf/Beru	4F0907275B	0532207011	RDE011
2499	US	Volkswagen	Phaeton	2003/01-2007/05	315MHz	●	●	5	A	315Mhz	Huf/Beru	4D0907275A	0532107001	RDE004
2500	US	Volkswagen	Phaeton	2003/01-2007/05	433MHz	●	●	5	A	433Mhz	Huf/Beru	4D0907275C	0532207001	RDE001
2503	US	Volkswagen	R32	2008/01-2011/12	315MHz	●	●	5	A	315Mhz	Continental	1K0907253D	S122215001C	
2504	US	Volkswagen	Rabbit	2006/01-2009/12	315MHz	●	●	5	A	315Mhz	Continental	1K0907253D	S122215001C	
2505	US	Volkswagen	Rabbit(O-ring Hex)	2006/01-2007/12	315MHz	●	●	5	A	315Mhz	Continental	1K0907253E		
2507	US	Volkswagen	Routan	2011/01-2015/12	433MHz	●	●	5	A	433Mhz	Schrader	7B0907253C/ 7B0907253B		7B0 907 253C/ 7B0 907 253B
2506	US	Volkswagen	Routan	2009/01-2010/12	433MHz	●	●	5	A	433Mhz	Continental	7B0907253A		
2509	US	Volkswagen	Tiguan	2012/01-2015/12	433MHz	●	●	5	A	433Mhz	Huf/Beru	3AA907275	0532207013	RDE013
2508	US	Volkswagen	Tiguan	2009/01-2011/12	315MHz	●	●	5	A	315Mhz	Continental	1K0907253D	S122215001C	
2510	US	Volkswagen	Touareg	2002/01-2006/12	433MHz	●	●	5	A	433Mhz	Huf/Beru	7L0907275	0532207005	RDE005
2512	US	Volkswagen	Touareg 2	2012/01-2015/12	433MHz	●	●	5	A	433Mhz	Huf/Beru	4F0907275D	0532207011	RDE011
2511	US	Volkswagen	Touareg 2	2007/01-2011/12	433MHz	●	●	5	A	433Mhz	Huf/Beru	4F0907275B	0532207011	RDE011
2518	US	Volvo	C30	2012/01-2013/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2517	US	Volvo	C30	2011/01-2011/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2516	US	Volvo	C30	2010/01-2010/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2515	US	Volvo	C30	2009/01-2009/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2514	US	Volvo	C30	2008/01-2008/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2513	US	Volvo	C30	2006/01-2007/12	433MHz	○	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2524	US	Volvo	C70	2012/01-2013/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2523	US	Volvo	C70	2011/01-2011/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2522	US	Volvo	C70	2010/01-2010/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2521	US	Volvo	C70	2009/01-2009/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2520	US	Volvo	C70	2008/01-2008/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2519	US	Volvo	C70	2007/01-2007/12	433MHz	○	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2530	US	Volvo	S40	2012/01-2012/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2529	US	Volvo	S40	2011/01-2011/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2528	US	Volvo	S40	2010/01-2010/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2527	US	Volvo	S40	2009/01-2009/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2526	US	Volvo	S40	2008/01-2008/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2525	US	Volvo	S40	2007/01-2007/12	433MHz	○	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2539	US	Volvo	S60	2012/01-2015/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2538	US	Volvo	S60	2011/01-2011/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2537	US	Volvo	S60	2010/01-2010/12	315MHz	○	●	4	A	315Mhz	Schrader	31200923		31200923
2536	US	Volvo	S60	2009/01-2009/12	315MHz	●	●	4	A	315Mhz	Schrader	31200923		31200923
2535	US	Volvo	S60	2008/01-2008/12	315MHz	●	●	4	A	315Mhz	Schrader	31200923		31200923

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, O=OBD)	Frequency	Sensor Manufacturer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
2534	US	Volvo	S60	2007/01-2007/12	315MHz	●	●	4	A	315Mhz	Schrader	31200923/ 30748991		31200923/ 30748991
2533	US	Volvo	S60	2006/01-2006/12	315MHz	●	●	4	A	315Mhz	Schrader	31200923/ 30748991		31200923/ 30748991
2532	US	Volvo	S60	2005/01-2005/12	315MHz	●	●	4	A	315Mhz	Schrader	31200923/ 30748991		31200923/ 30748991
2531	US	Volvo	S60	2004/01-2004/12	315MHz	○	●	4	A	315Mhz	Schrader	31200923/ 30748991		31200923/ 30748991
2548	US	Volvo	S80	2012/01-2015/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2547	US	Volvo	S80	2011/01-2011/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2546	US	Volvo	S80	2010/01-2010/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2545	US	Volvo	S80	2009/01-2009/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2544	US	Volvo	S80	2008/01-2008/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2543	US	Volvo	S80	2007/01-2007/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2542	US	Volvo	S80	2006/01-2007/12	315MHz	●	●	4	A	315Mhz	Schrader	31200923/ 30748991		31200923/ 30748991
2541	US	Volvo	S80	2005/01-2005/12	315MHz	●	●	4	A	315Mhz	Schrader	31200923/ 30748991		31200923/ 30748991
2540	US	Volvo	S80	2004/01-2004/12	315MHz	○	●	4	A	315Mhz	Schrader	31200923/ 30748991		31200923/ 30748991
2554	US	Volvo	V50	2012/01-2012/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2553	US	Volvo	V50	2011/01-2011/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2552	US	Volvo	V50	2010/01-2010/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2551	US	Volvo	V50	2009/01-2009/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2550	US	Volvo	V50	2008/01-2008/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2549	US	Volvo	V50	2007/01-2007/12	433MHz	○	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2561	US	Volvo	V70	2010/01-2014/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2560	US	Volvo	V70	2009/01-2009/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2559	US	Volvo	V70	2008/01-2008/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2558	US	Volvo	V70	2007/01-2007/12	315MHz	●	●	4	A	315Mhz	Schrader	31200923/ 30748991		31200923/ 30748991
2557	US	Volvo	V70	2006/01-2006/12	315MHz	●	●	4	A	315Mhz	Schrader	31200923/ 30748991		31200923/ 30748991
2556	US	Volvo	V70	2005/01-2005/12	315MHz	●	●	4	A	315Mhz	Schrader	31200923/ 30748991		31200923/ 30748991
2555	US	Volvo	V70	2004/01-2004/12	315MHz	○	●	4	A	315Mhz	Schrader	31200923/ 30748991		31200923/ 30748991
2565	US	Volvo	XC60	2012/01-2015/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2564	US	Volvo	XC60	2011/01-2011/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2563	US	Volvo	XC60	2010/01-2010/12	315MHz	●	●	4	A	315Mhz	Schrader	31200923		31200923
2562	US	Volvo	XC60	2009/01-2009/12	315MHz	●	●	4	A	315Mhz	Schrader	31200923		31200923
2574	US	Volvo	XC70	2012/01-2015/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2573	US	Volvo	XC70	2011/01-2011/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2572	US	Volvo	XC70	2010/01-2010/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2571	US	Volvo	XC70	2009/01-2009/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2570	US	Volvo	XC70	2008/01-2008/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2569	US	Volvo	XC70	2007/01-2007/12	315MHz	●	●	4	A	315Mhz	Schrader	31200923/ 30748991		31200923/ 30748991
2568	US	Volvo	XC70	2006/01-2006/12	315MHz	●	●	4	A	315Mhz	Schrader	31200923/ 30748991		31200923/ 30748991

SN.	Market	Make	Model	Year Range	Feature	OBD-II Function	Programming Status (Red:New, Yellow:Modify)	Tires	Relearn Type (A=Automatic, S=Stationary, 0=OBD)	Frequency	Sensor Manufactuer	OE Part NO.	Manufacturer Sensor #	Number on Sensor#
2567	US	Volvo	XC70	2005/01-2005/12	315MHz	●	●	4	A	315Mhz	Schrader	31200923/ 30748991		31200923/ 30748991
2566	US	Volvo	XC70	2004/01-2004/12	315MHz	○	●	4	A	315Mhz	Schrader	31200923/ 30748991		31200923/ 30748991
2580	US	Volvo	XC90	2010/01-2015/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2579	US	Volvo	XC90	2010/01-2014/12	315MHz	●	●	4	A	315Mhz	Schrader	31200923		31200923
2578	US	Volvo	XC90	2008/01-2009/12	433MHz	●	○	4	A	433Mhz	Continental	31302096	S180052020	S180052020
2577	US	Volvo	XC90	2007/01-2009/12	315MHz	●	●	4	A	315Mhz	Schrader	31200923		31200923
2576	US	Volvo	XC90	2006/01-2006/12	315MHz	●	●	4	A	315Mhz	Schrader	31200923		31200923
2575	US	Volvo	XC90	2004/01-2005/12	315MHz	●	●	4	A	315Mhz	Schrader	31200923		31200923