

## **MaxiSys Pro Benz V8.11 2016-09-12**

1.Fixed an issue that caused failure in multiple functions under Active test in engine system for Chassis 211.042