

MaxiSys Benz V8.11 2016-09-13

1.Fixed an issue that caused failure in multiple functions under Active test in engine system for Chassis 211.042.