

MaxiSys Roewe V2.20 2016-09-23

1. Fixed an issue that could cause failure in Read codes in Body and some other systems for Roewe 500 and other models before 2016.
2. Fixed an issue that could cause failure in automatic identification in engine system for Roewe 500 before 2016.
3. Fixed an issue that could cause communication failure in 2012 and 2013 Roewe 950.
4. Fixed an issue that caused failure in VIN analysis for Roewe 360 before 2016.