

## **MaxiSys Saab V2.50 2016-09-23**

1. Fixed an issue where users failed to exit model selection menu for 9-5 models before 2009.
2. Fixed an issue that caused failure in function Reset Adaptive Values for 2008 9-3 models.