

MaxiSys Sprinter V5.10 2016-10-14

1. Fixed bugs that caused failure in CR3_NAFT injector programming in Chassis 90X.6.
2. Fixed bugs that caused CR2 algorithm error in Chassis 90X.6.
3. Added VIN auto reading function.
4. Improved the display of graphic symbol in menu interface.