

MaxiSys MS905 OS Program V03.13.00 2016-10-17

1. Fixed an issue where there is no response when click the "vehicle" icon in navigation bar.
2. Fixed related problems in build-in browser.
3. Improved battery over-temperature protection mechanism. To prevent the diagnosis device from damage and danger, system will warn users to power off when temperature is above 55°C, and automatically shut down when the temperature reaches 60°C.
4. Added Log Tool .
5. Updated the default version of management system to V2.19.