

MaxiSys Holden V3.60 2016-10-18

1. Fixed an issue where security code is wrong when entering Inject Programming in 2009 / Colorado / Engine control module/ 3.0L 4JJ1-TC (Delphi).
2. Fixed an issue where fault codes status can not be displayed and the descriptions is wrong in coding function in 2008 Viva / body.
3. Fixed an issue where descriptions of fault codes cannot be identified in coding function in V6 engine in 2011 / VE and WM Series / ECM.