

MaxiSys TJFAW V3.10 2016-10-28

1. Resolved an issue that caused failure in key programming in immobilizer for Junpai D60.