

Maxisys CV Lib-HD V2.02.23 2016-11-14

1. Fixed an issue that caused communication disconnection after MaxiSys management procedure is hidden.
2. Fixed an issue that caused Volvo, Cummins, Maxxforce, OBD J1708 and J1939 communication unstable.
3. Improved stability of software for commercial vehicles