

MaxiSys GM V9.80 2016-11-15

1. Fixed an issue that could prevent Clutch Pedal Position Learn from executing successfully in Engine system for 2012 Chevrolet Truck Orlando.
2. Fixed an issue that could cause crash when executing New BCM Setup in Body module for 2004 (2) Pontiac (Product lines N).
3. Added VIN Analysis for some models.