

MaxiDas Saicmg V4.40 2016-12-05

1. Fixed bugs that caused failure when entering Engine system, Transmission system and ABS, and resolved an issue that users failed to test SRS normally.
2. Resolved an issue that undefined fault codes are existed when performing Read Codes in Body system, and fixed bugs that caused failure in Clear Codes function.
3. Fixed bugs that caused failure in Window Lifting of Active Test in Body Control System for MG GT 1.5L before 2016.