

MaxiSys MS906TS MSTs V2.02 2016-12-05

1. Added progress bar for MX-sensor burned.
2. Fixed activation problems for some models.
3. Improved display of TPMS OBD function.
4. Improved the Proceed tips of traditional Chinese, fixed some French and Italian display of messages.