

## **MaixSys Benz V8.13 2016-12-08**

1. Fixed an issue that the system automatically returned to the vehicle menu screen when Auto VIN Scan was performed;
2. Fixed issues that resulted in failure to perform Pressure reservoir: check pretension pressure for the SBC system on some W211 models;
3. Fixed issues that resulted in failure to clear fault codes for the airbag system on some W168 models;
4. Fixed issues that resulted in failure to read correct VINs automatically;
5. Fixed issues that resulted in failure to perform "Calibration of control unit ABR" for the SBC system on some W221 models;
6. Fixed issues that caused errors in fault codes that were read by automatically scanning the TCM on some W251 models.