

MaxiSys Skoda V8.52 2016-12-12

1. Fixed issues that caused throttle matching failure for some models.
2. Improved performance when entering the system applications by test.