

## **MaxiSys MS906TS Hyundai V5.10 2016-12-14**

1. Updated TPMS Status function.
2. Fixed bugs that caused communication failure for some models.