

MaxiSys Holden V3.70 2016-12-20

1. Fixed bugs in Reprogram All Transponder Keys in Special functions for 2010 VE and WM Series Immobiliser.
2. Optimized the way to enter BCM for 2005 Vectra-C/Signum .
3. Fixed bugs in Live Data under Engine 3.0L 4JJ1-TC (TransTron) for 2008 RA Rodeo/Colorado.
4. Fixed bugs in VIN Programming, Inject Programming and Program ECU in Engine 3.0L 4JJ1-TC (TransTron) for 2008 RA Rodeo/Colorado.