

J2534 V3.90 2017-01-12

1.Fixed an issue that some models of VW abnormality cause by ISO9141 and KWP1281.