

Release Notes (May)

This release includes improved performance and bug fixes for <u>MaxiSys series</u> products, <u>MaxiSys 906/908/908 pro</u>, <u>MaxiSys CV</u>, <u>MD808/MaxiService/MaxiDiagElite</u> <u>Oil Reset</u>.

MaxiSys Series

♦ Asia

• Honda (V4.21)

> Added Maintenance Mode for Brake Disc in ABS.

> Added Regulator Bleeding function in ABS.

Improved the operation speed for softwares.

> Added menu access for common systems and all systems in

Auto Scan.

Added quick access for Hot Functions.

> Fixed bugs that caused display error on Gauges after

performing Lock Release function.

♦ America

• Ford (V7.11)

Added quick access for Hot Functions.

> Fixed bugs that caused failure in performing some functions.

• Chrysler (V7.53)

Added quick access for Hot Functions.

• Fiat (V1.00)

➢ Supports all basic functions and special functions for Fiat in Britan, including TPMS, Oil Reset, Immobilizer, Proxi Configuration, Calibration function and DPF.

♦ Europe

LandRover (V5.02)

> Added quick access for Hot Functions.

Fixed bugs in Program Keys function for 2006 Range Rover

Sport.

• Fiat (V6.01)

Added quick access for Hot Functions.

MaxiSys pro & 908 & 906

♦ European:

• Opel/Vauxhall (V5.70)

Added special function Program Transponder & Remote Key

for 2014 Corsa-D Body Control Module.

Fixed bugs that caused error in reading fault codes for 2007

Astra-H SDM (Airbag).

➢ Fixed bugs that caused error in accessing engine X 12 SZ system for 1997 Corsa-B.

➢ Fixed bugs that caused error in accessing live data (engine data) for 2010 Insignia engine 2.0L (LDK).

Merged menus of engine functions for 2009 Vivaro.

> Fixed bugs that caused errors in special function Program

Transponder & Remote Key for 2002 Astra-G Immobiliser.

➢ Added DPF Service Regeneration function for 2015 Vivaro-B Engine 1.6L (LWU).

➢ Fixed bugs that caused error in Read Security Code for Astra-H ECM.

➢ Fixed bugs that caused problems in Reset Learned Value function for 2002 Zafira engine Z 18 XE.

➢ Fixed bugs that caused failure in accessing system from History Records.

➢ Fixed bugs in Active Test, Read Codes and special functions for 2011 Opel/Antara.

➢ Fixed bugs in special function Electronic Throttle Control for 2007 Opel/Astra engine Z18XER.

Holden (V4.10)

➤ Added quick access for Hot Functions.

➢ Fixed bugs that caused errors in the process of Reset Service Interval in IPC (Instrument Panel Cluster) for 2010 VE and WM Series.

➢ Added Fuel Trim Reset in Active test in Fuel System of Engine Control Module\LY7(V6) for 2010 VE and WM Series.

➢ Fixed bugs that caused failure in communication of Live Data function in Engine Control Module\LY7(V6) for 2007~2009 VE and WM Series.

➢ Fixed bugs that caused failure in accessing Engine Control Module Engine(V6) for 2001 VX Commodore.

Benz (V11.00)

Added Active Test and Special functions for 102 systems under Chassis 213.

Supports Coding and Learning for almost all systems, such as Engine, Transmission, Instrument, Headlamp, Door, Sgnal Sampling and Multimedia.

♦ VW (V9.51)

Improved the speed of entering systems.

Added Service functions, including Oil Reset, EPB, DPF, Battery Adaptation, ABS Brake Bleed, Key Adaptation, Injector Adaptation, Steering Angle Learning, Suspension System, Thottle Adaptation, Headlamp Adaptation and TEC Learning.

♦ Asia

Hyundai/KIA (V6.72) (Maxisys908 only)

> Optimized structure codes, and fixed bugs that caused failure in Live Data.

Optimized the way of display for Auto Scan.

♦ American

♦ GMUSA(V10.40)

➢ Resolved problems in the process of Fuel Composition Reset function in Engine for 2012 Chevrolet Sonic.

Fixed bugs that caused errors in performing Steering Angle

Sensor Reset in Steering wheel angle sensor module for 2016

Chevrolet Silverado.

Fixed bugs that caused exception in Read Codes function in

Engine for 2001 Chevrolet MPV.

> Added VIN Analysis for some models.

MaxiSys CV

♦ European:

Hino_HD (V3.00)

Added the support of diagnosing Engine, Transmission, Hybrid, Inverter Battery, DCU, VCS, Suspension, SRS, Range Inhibit, Lane Departure Warning System, Immobilizer, ES Start, Door Control, Clutch and other systems for 2012-2017 North American vehicle models.

➢ It supports Auto/Manual VIN, Cylinder Balancing, Cylinder Shut-off, Compression Test, Fuel Leak Test, DPF, Injector Calibration, etc.

MD808/MaxiService/MaxiDiagElite OilReset

♦ European:

LandRover (V1.10)

Added Oil Reset and other related functions, and improved One-button Oil Reset and Manual Oil Reset.

Added support for Oil Reset to all models up to 2017.