

Region	Software	Make	Description	MaxiSys ADAS	MaxiSys ADAS PRO
Europe	ADAS	Benz	<p><b>Version: V16.00 (Nov 25, 2019)</b></p> <p><b>Highlights:</b></p> <p>1. Added fault code guidance function for ACC and LDW.</p> <p>Supported chassis, including: 117, 156, 164, 166, 172, 176, 204, 205, 207, 209, 211, 212, 216, 217, 218, 219, 221, 222, 230, 231, 242, 246, 251, 253, 292, 177, 190, 203, 213, 215, 220, 238, 240, 257, and 463.</p>	√	√
America	ADAS	Chrysler	<p><b>Version: V8.80 (Jan 9, 2020)</b></p> <p><b>Highlights:</b></p> <p>1. Added ACC and LDW functions.</p> <p>Supported models, including: 2019 Renegade, Cherokee, Challenger, Charger, COMPASS (CHINA), 300/Charger/Magnum/Grand voyager, Compass, CHRYSLER PACIFICA, Durango, Grand Cherokee, and so on.</p>	√	√
Domestic / Overseas versions (Europe, America, Japan, Korea, Australia)	ADAS	Honda	<p><b>Version: V6.90(Dec 2, 2019)</b></p> <p><b>Highlights:</b></p> <p>1. Added calibration function for Lanewatch system.</p> <p>Supported model: for all models with the Lanewatch function.</p>	√	√

<p><b>Domestic / Overseas versions (Europe, America, Japan, Korea, Australia)</b></p>	<p><b>ADAS</b></p>	<p><b>Hyundai/ Kia</b></p>	<p><b>Version: V8.21(Nov 27, 2019)</b>  <b>Highlights:</b>  1. Added ACC, LDW, and BSD functions.  Support models: for all 2019 models and four 2020 models of Hyundai in the US including ELANTRA (ADA), Elantra (AD), PALISADE (LX2) and VELOSTER (JS); for 14 models of Kia including 2020 European K900 (RJ), OPTIMA HEV (JF HEV), OPTIMA (JFA) - For Central and South America, Optima (JF), RIO (YB), SOUL EV (SK3 EV), SOUL EV (SK3 EV)-For Mexico, SOUL (SK3), SOUL (SK3)-For Mexico, SOUL (SK3A), STONIC (YB CUV), Sorento (UM), Telluride (ON) and Telluride(ON)-For Mexico.</p>	<p>√</p>	<p>√</p>
<p><b>Domestic / Overseas versions (Europe, America, Japan, Korea, Australia)</b></p>	<p><b>ADAS</b></p>	<p><b>Renault</b></p>	<p><b>Version: V5.40 (Nov 12, 2019)</b>  <b>Highlights:</b>  1. Added rear camera calibration function.  Support 50 models, including TALISMAN/SM6, SCENIC IV, MEGANE IV KADJAR CN, KOLEOS II/QM6, KOLEOS II CN/QM6 CN, MEGANE IV SEDAN, KWID BR, KADJAR, TRIBER, DUSTER ph3, MASTER III, CLIO IV and more.</p>	<p>√</p>	<p>√</p>
<p><b>Domestic / Overseas versions (Europe, America, Japan, Korea, Australia)</b></p>	<p><b>ADAS</b></p>	<p><b>Toyota</b></p>	<p><b>Version: V6.10(Dec 14, 2019)</b>  <b>Highlights:</b>  1. Added new LDW calibration method.  Supported 105 models: Avalon (2016-2020); Camry (2018-2020); Corolla (2017-2020); ES300H (2016-2020); ES350 (2016-2020); GS F (2016-2020); GS300 (2018-2020); HighLander (2017-2019); LS500H (2018-2020); NX300 (2018-2020); NX300H (2018-2020); RAV4(2016-2020); Sequoia (2018-2020); and UX250H (2019-2020).</p>	<p>√</p>	<p>√</p>

<p><b>Domestic / Overseas versions (Europe, America, Japan, Korea, Australia)</b></p>	<p><b>ADAS</b></p>	<p><b>Volkswagen</b></p>	<p><b>Version: V13.10 (Jan 15, 2020)</b>  <b>Highlights:</b>  1. Added NVS calibration function.  Supported models: Bentley Continental Series 2018&gt; (2018-2019)  2. Added LDW calibration function  Supported models: Volkswagen commercial vehicle 2C - Caddy 2011 &gt;(2011-2015), SA - Caddy 2016 &gt;(2016-2019)</p>	<p>√</p>	<p>√</p>
<p><b>Domestic / Overseas versions (Europe, America, Japan, Korea, Australia)</b></p>	<p><b>ADAS</b></p>	<p><b>Volvo</b></p>	<p><b>Version: V10.00 (Jan 15, 2020)</b>  <b>Highlights:</b>  1. Added ACC/LDW calibration function.  Supported model: XC40 (2018-2020)</p>	<p>√</p>	<p>√</p>
<p><b>Domestic / Overseas versions (Europe, America, Japan, Korea, Australia)</b></p>	<p><b>ADAS</b></p>	<p><b>BMW</b></p>	<p><b>Version: V12.90 (Nov 9, 2020)</b>  <b>Highlights:</b>  1. Added fault code guidance function for ACC and LDW systems.  2. Added LDM (longitudinal dynamics management) function.  Supported model: E chassis  3. Fixed the problem of missing HUD calibration function when HUD is mounted to the bus line of the instrument system through APIX.</p>	<p>√</p>	<p>√</p>

<p><b>Domestic / Overseas versions (Europe, America, Japan, Korea, Australia)</b></p>	<p><b>ADAS</b></p>	<p><b>PSA</b></p>	<p><b>Version: V7.20 (Dec 15, 2019)</b>  <b>Highlights:</b></p> <ol style="list-style-type: none"> <li>1. Added ACC calibration function. Supported 16 models: 208, 3008, 5008, 3008 (P84), 4008 (P84), 508(R8), 3008 (P84), DS 7 CROSSBACK, C6 (X81), DS 3 (A55P), EXPERT (K0), JUMPY (K0), SPACETOURER, TRAVELLER PARTNER (B9), DS 3, and C4 SPACETOURER (B78).</li> <li>2. Added LDW calibration function. Supported 20 models: C6 (X81), 5008 (P87), 4008 (P84), 508(R8), 3008 (P84), DS 7 CROSSBACK, C6 (X6), C4 SPACETOURER (B78), C4 PICASSO, C4 SEDAN, C4 (B7), C4 Aircross (A88), BERLINGO (K9), 308, 408 (T73), RIFTER (K9), EXPERT (K0), JUMPY (K0), SPACETOURER, and JUMPER 3 Euro 5 / Euro 6.</li> <li>3. Added NVS calibration function. Supported model: 508(R8)</li> <li>4. Added AVM calibration function. Supported models: C6 (X81), 5008 (P87), 4008 (P84), and 3008 (P84).</li> </ol>	<p>√</p>	<p>√</p>
<p>Email: sales.eu@autel.com (EU)  ussupport@autel.com (US)  support@autel.com (China)  Phone: 0086-755-8614 7779 (China)  1-855-288-3587 (US)</p>					