

MaxiSys Chrysler V7.01 2016-09-10

1. Fixed an issue that caused failure in Read codes for some models before 2003.
2. Fixed an issue where failed to execute Active test for some models before 2003.
3. Fixed an issue that caused failure in Steering angle initialization for some 2007-2011 models.
4. Improved Odometer reset function for models before 2003.