

MaxiDas 708 Benz V10.21 2016-09-26

1. Fixed bugs that could cause functional abnormality in suspension system for Chassis 220.