

MaxiSys Porsche V5.70 2016-11-15

1. Added support for EPB Brake Pad Replacement. instructions for Manca, 991 and 981 models.
2. Added the Brake Pad Replacement function of Manca, 991, 981, Panamera and new-generation Cayenne models into Hot Function.
3. Added the Auto Reset function into Hot Function.
4. Improved some functional performance, such as VIN coding for Panamera, 981 and 991 models, level control calibration algorithm for old-generation Cayenne models, and engine clutch adaption for new-generation Cayenne models.