

## **MaxiDas BAICMotor V4.10 2016-12-09**

1. Optimized Auto Scan function by shortening scanning time.
2. Fixed bugs that caused errors when entering anti-theft system for Huansu S2/S3.
3. Fixed bugs in Active Test in Body system for E-series model.
4. Optimized Service function for E-series model.