

## **MaixSys Audi V8.52 2016-12-12**

1. Fixed issues that caused throttle matching failure for some models.
2. Improved the oil reset performance for 2016 Q7 models.
3. Improved performance when entering the system applications by test.