

MaxiSys MS906TS Kia V5.10 2016-12-14

1. Updated TPMS Status function.
2. Added diagnostic function for K4, K5.
3. Fixed bugs that caused communication failure for some models.