

MaxiSys Chrysler V7.10 2016-12-17

1. Fixed an issue that caused failure to read codes when perform scanning in some models before 2003.
2. Fixed an issue that caused failure to erase codes in ABS in some models before 2003.
3. Added functional prompting messages for Self-learning of Engine in some 2007-2011 models.
4. Improved Italian translation.