

MaxiSys MS906 OS Program V03.25.00 2016-12-21

1. Fixed an issue that the device reports error when system was resumed from hibernation during the operation of digital videoscope.
2. Improved the prompting message for formatting and factory reset.
3. Updated the management program version to V2.22.
 - 1) Fixed bugs that caused errors in email sending.
4. Fixed an issue that unable to power on the system at low temperature (below -10°C).
5. Fixed an issue that users failed to upload attachments in MaxiFix.
6. Fixed an issue that system sometimes reported errors when management program (Maxisys) updating completed.