

MaxiSys MS906TS MSTs V2.03 2016-12-23

1. Fixed an issue that failed to activate OEM-Sensor for some models.
2. Optimized communication in functions for some models.
3. Improved language display in Relearn steps.