

MaxiSys Saab V2.70 2016-12-27

1. Fixed an issue that caused functional failure in Add Keys for 2004 saab 9-3.