

Release Notes (November)

This release includes improved performance and bug fixes for [MaxiSys series products](#), and [MaxiSys 906/908/908 pro](#).

MaxiSys Series

✧ Asia

◆ Toyota (V4.30)

- Added Active Test and Freeze Frame for systems including Engine, Transmission and Hybrid Control system for Carola HV, Levin HV, Camry and Crown after 2015.
- Added Coding function in Hybrid Control for Carola HV, Levin HV and Prius after 2015.
- Added Scan Historical Codes and Pending Codes in Auto Scan.
- Improved Function Menu for all models.

◆ Nissan/Infiniti (V5.20)

- Added hot function menu for users to enter 15 hot functions (such as Injector, Brake and TPMS) through a fast path.
- Improved accuracy in fault code location, and updated Freeze Frame function for 26 systems.
- Developed a new mode for Anti-theft feature; updated the Coding function and added coverage for 7 ECUs.

- Added 203 functions, such as Save Computer Data, Write Saved Data and Oil Grade Factor.
- Added 50 Active Tests, such as Injector cylinder 1 and High pressure circuit leak test.
- Improved scanning time for system auto scan.
- Allows users to perform online anti-theft function without the 20-digit password for some models, such as 2013 TEANA, 2015 TEANA and 2015 X-trail.

Maxisys pro & 908 & 906

✧ **American**

◆ **GMUSA(V9.80)**

- Fixed an issue that could prevent Clutch Pedal Position Learn from executing successfully in Engine system for 2012 Chevrolet Truck Orlando.
- Fixed an issue that could cause crash when executing New BCM Setup in Body module for 2004 (2) Pontiac (Product lines N).
- Added VIN Analysis for some models.
- Added Push-button Oil Reset function.

◆ **GM(V6.40)**

- Fixed an issue that might cause communication failure in Active Test and Live Data for 2015 Chevrolet and Sail.

- Fixed an issue that might cause failure in Active Test, such as Pump Motor Test and Solenoid Valve Test, for 2004 Chevrolet and Sail.

- Fixed an issue that caused process problems in special function Steering Wheel Angle Sensor Centering in Power Steering Control Module for 2013 Chevrolet Cruze.

- Fixed an issue that caused failure in ABS Bleeding for 2007 Buick Firstland.

- Improved Active Test function and optimized menu display for special functions.

- Added Auto Oil Reset function.

✧ **European:**

◆ **VW (V8.00)**

- Added Code Cloud Backup and Obtain Backup Code, and improved Online Coding function for some VW models.

- Added basic function Secure Login Online for some models.

- Added Throttle Matching and Battery Matching in Hot functions.

◆ **Porsche (V5.70)(MaxiSys 908 only)**

- Added Brake Pad Replacement (Operation Guide) function in EPB for Manca, 991, 981 .

- Integrated Brake Pad Replacement (Operation Guide) into Hot Function for Manca, 991, 981, Panamera and New Cayenne.

- Added Push-button Oil Reset in Hot Function.

- Optimized some special functions such as VIN Analysis for Panamera, 981, 991 and fixed some bugs.

◆ **Opel/Vauxhall (V4.90)**

- Added special function Program Variant Configuration in SDM for 2006 Astra-H.

- Added special function Replace Differ. Pressure sensor in ECM for 2011 Corsa-D.

- Added special functions Program Idle Speed, Replace Injector, Replace Mass Air Flow Sensor and Replace Throttle Actuator in ECM for 2010-2013 Corsa-D.

- Added Auto Oil Reset function.

- Fixed bugs that caused process errors in special functions Program Transponder & Remote Key in CIM for 2007 Zafira-B.

- Fixed bugs that caused process errors in special function Program Odometer in IPC for 2009 Zafira-B.

- Fixed bugs that caused error when entering ECM for 2009-2011 Insignia.

- Fixed bugs in some basic functions in ECM/G9T 720(2.2I), such as Live Data and Active test, for 2002 Movano.

➤ Added Regeneration D. Particulate Filter in special functions for 2009 Astra-H and 2011 Corsa-D.

✧ **Asia**

◆ **Mitsubishi (V5.00) (MaxiSys 908 only)**

- Added basic functions for 2016 models and some 2015 models.
- Improved manual model-choosing menu by adjusting display sequence and adding menus to choose engine models.
- Improved basic function such as Active Test and Live Data.
- Improved Auto Scan, Programming and Service function by shortening the processing time.
- Improved special functions and fixed some bugs.

◆ **Isuzu (V3.20)**

- Fixed an issue that DTC status failed to be displayed in DTC information interface for some systems.
- Added Hot Functions, such as Oil Reset, Injector and Immobilizer.
- Added Auto Oil Reset function.